

# Historic Libertyville

BEGINNING STREET NUMBER	117
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt117(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<b>ZONING</b>
-	R-7
<b>GROUND FLOOR USE</b>	<b>NUMBER OF STORIES</b>
Residence	2
<b>UPPER FLOOR USE</b>	<b>PROPERTY INDEX NUMBER</b>
Residential	1121203011
<b>CURRENT OCCUPANT</b>	
-	

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<b>NR ELIGIBLE?</b>
C	No
<b>WITHIN DISTRICT?</b>	<b>CRITERIA</b>
No	-
<b>NR LANDMARK?</b>	<b>ALTERNATE ADDRESS?</b>
No	-
<b>YEAR</b>	
-	

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<b>HISTORIC USE</b>
Building	Domestic - single dwelling
<b>CONDITION</b>	<b>SECONDARY STRUCTURE</b>
Good	Detached garage
<b>INTEGRITY</b>	<b>NR SECOND</b>
Minor alterations and additions	NC
<b>CURRENT USE</b>	
Domestic - single dwelling	

## **ARCHITECTURAL DESCRIPTION**

### **ARCHITECTURAL CLASSIFICATION**

Gable Front

### **DETAILS**

-

### **OTHER YEAR**

-

### **DATE SOURCE**

Assessor/Surveyor

### **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

### **WALL MATERIAL 2 (CURRENT)**

-

### **PLAN**

Rectangular

### **NO OF STORIES**

2.5

### **ROOF TYPE**

Front Gable

### **ROOF MATERIAL**

Asphalt - shingle

### **FOUNDATION**

Parged

### **PORCH**

Full Front

### **WINDOW MATERIAL**

Aluminum/vinyl

### **WINDOW MATERIAL 2**

-

### **WINDOW TYPE**

Double Hung

### **WINDOW CONFIGURATION**

1/1

### **SIGNIFICANCE**

-

### **HISTORIC FEATURES**

Front gable roof and rectangular massing; full-front hipped-roof porch structure

### **ALTERATIONS**

Replacement siding (1963); replacement windows in original openings (2010); one-story rear addition (1973); alterations to front porch--enclosure around entry; verge board at gable and spindle work on porch are not historic

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt117(3)



Photo Id: First117

## **HISTORIC INFORMATION**

**OLD ADDRESS (CITY DIR.YEAR)**

-

**BUILDING MOVED?**

-

**MOVED FROM**

-

**ORIGINAL OWNER**

-

**ORIGINAL ARCHITECT**

-

**ARCHITECT SOURCE**

-

**BUILDER**

-

**SURVEYOR**

LR

**SURVEYOR ORGANIZATION**

Ramsey Historic Consultants

**SURVEY DATE**

May-June 2016

**SURVEY AREA**

Downtown Libertyville

## **PERMIT/HISTORIC INFORMATION**

**OLD ADDRESS**

-

**DATE OF CONSTRUCTION**

-

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #**

-

**DATE MOVED**

-

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #**

-

**DATE**

-

**BUILDING PERMIT DESCRIPTION**

-

**COST**

-

**ORIGINAL OWNER OCCUPIED?**

-

**EXTERIOR ALTERATION PERMITS**

#240 (9/18/1950)--enclosed back porch and reshingle; #3316 (7/30/1963)--aluminum replacement siding, replace two windows; 7236 (6/1973)--rear addition (\$7500); No Permit # (11/29/2010)--replacement windows in original openings

**OTHER PERMIT INFORMATION**

2654 (6/5/1960)--garage; 93-??? (5/24/1993)--addition to garage

**COA INFO**

-

**HISTORIC INFO**

Sanborn Maps, 1933, 1948

**OTHER SOURCES**

-

**HISTORIC INFO COMPILER**

LR

**VOLUNTEER**

-