Historic Libertyville

BEGINNING STREET NUMBER	130	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: MapleAveW130(4)

BUILDING DETAILS

BUILDING NAME	ZONING
Dymond, Franklin P. House	R-8
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116311008
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB		
С		
WITHIN DIS	TRICT?	
No		
NR LANDMA	ξ Κ?	
No		
YEAR		
-		

NR ELIGIBLE?

No CRITERIA

-

ALTERNATE ADDRESS?

GENERAL INFORMATION

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Moderate alterations and additions	
CURRENT USE	
Domestic - multiple dwelling	

HISTORIC USE

Domestic - single dwelling
SECONDARY STRUCTURE

Detached garage

NR SECOND

NC

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

OTHER YEAR

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

PLAN

Irregular

- 5- -

NO OF STORIES

2.5

ROOF TYPE

Hipped

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

HISTORIC FEATURES

Hipped roof; three-sided 2-story front bay with pent roof; 2story square pend roof bay on east elevation; east side hipped roof porch structure north of bay (enclosed); wood windows on first story; classical lintels over window openings; beveled glass transom over window on 1st story of front bay

ALTERATIONS

Replacement siding; wraparound front porch removed and replaced with smaller entry and west side porch (post-1948); east side porch enclosed (post-1948); 2nd story replacement windows in original openings

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW130(1)



Photo Id: MapleAveW130(2)



Photo Id: Maple130



Photo Id: 130Maple

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Dymond, Franklin P.	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

#451 (9/12/1942)--unknown alteration

OTHER PERMIT INFORMATION

JRB-04-0016 (6/25/2004)--detached garage

COA INFO

HISTORIC INFO

From Illinois Digital Archives (info provided by Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--"Residence of Franklin P. Dymond on Division Street, later renamed Maple Avenue. The exact address is 130 West Maple Avenue. At the turn of the twentieth century, Franklin P. Dymond was president of the Lake County Bank and was an owner (with R. J. Proctor and W. T. Eaton) of the Lake County Gravel Company, both in Libertyville. He was also engaged in the mercantile business, first as a partner with E. W. Parkhurst and later with M. B Colby. According to the book Libertyville Illustrated, "Franklin P. Dymond was born in Jefferson, Cook county, Illinois, now a part of Chicago, in 1852. His father, William D. Dymond, was born in England in 1822, and came to Lake county in 1849. After living for six years in Jefferson, Ill., he returned to Lake County and purchased a fine farm near Libertyville, where he still lives. F. P. Dymond's wife is a sister of M. B. Colby, who was born in Vermont in 1849, coming to Libertyville with his father, E. W. Colby, in 1855."

OTHER SOURCES

Historic photograph of house on Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--

http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/5/rec/1

HISTORIC INFO COMPILER

LR

VOLUNTEER