Domestic - multiple dwelling

BEGINNING STREET NOMBER	130	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	_	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW130(4)
CRITERIA		
CRITERIA	-	
	<u>BUILDIN</u>	NG DETAILS
BUILDING NAME		ZONING
Dymond, Franklin P. House		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116311008
CURRENT OCCUPANT		
-		
	ΝΔΤΙΟΝΔ	AL REGISTER
	MAITONA	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	NFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Moderate alterations and additions		NC
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Queen Anne	Parged
DETAILS	PORCH
-	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Hipped roof; three-sided 2-story front bay with pent roof; 2-
ROOF TYPE	story square pend roof bay on east elevation; east side hipped roof porch structure north of bay (enclosed); wood windows on
Hipped	first story; classical lintels over window openings; beveled glass
ROOF MATERIAL	transom over window on 1st story of front bay

Asphalt - shingle

#### ALTERATIONS

Replacement siding; wraparound front porch removed and replaced with smaller entry and west side porch (post-1948); east side porch enclosed (post-1948); 2nd story replacement windows in original openings



Photo Id: MapleAveW130(1)



Photo Id: MapleAveW130(2)



Photo Id: Maple130



Photo Id: 130Maple

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Dymond, Franklin P.	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT #	MOVING INFORMATION  DATE MOVED
-	-
<u>ORIGIN</u>	AL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	JRB-04-0016 (6/25/2004)detached garage
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
- COST	From Illinois Digital Archives (info provided by Libertyville- Mundelein Historical Society and Cook Memorial Public Library) "Residence of Franklin P. Dymond on Division Street, later

ORIGINAL OWNER OCCUPIED?

**EXTERIOR ALTERATION PERMITS** 

#451 (9/12/1942)--unknown alteration

From Illinois Digital Archives (info provided by Libertyville-Mundelein Historical Society and Cook Memorial Public Library)"Residence of Franklin P. Dymond on Division Street, later renamed Maple Avenue. The exact address is 130 West Maple Avenue. At the turn of the twentieth century, Franklin P. Dymond was president of the Lake County Bank and was an owner (with R. J. Proctor and W. T. Eaton) of the Lake County Gravel Company, both in Libertyville. He was also engaged in the mercantile business, first as a partner with E. W. Parkhurst and later with M. B Colby. According to the book Libertyville Illustrated, "Franklin P. Dymond was born in Jefferson, Cook county, Illinois, now a part of Chicago, in 1852. His father, William D. Dymond, was born in England in 1822, and came to Lake county in 1849. After living for six years in Jefferson, Ill., he returned to Lake County and purchased a fine farm near Libertyville, where he still lives. F. P. Dymond's wife is a sister of M. B. Colby, who was born in Vermont in 1849, coming to Libertyville with his father, E. W. Colby, in 1855."

#### OTHER SOURCES

Historic photograph of house on Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--

http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/5/rec/1

#### HISTORIC INFO COMPILER

LR

#### VOLUNTEER

-			

BEGINNING STREET NUMBER	133	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW133(1)
CRITERIA	-	
BUILDING NAME	<u>BUIL</u>	DING DETAILS  ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116316001
CURRENT OCCUPANT		
I .		I .

## **NATIONAL REGISTER**

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
С	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

IEAK	
-	
G	ENERAL INFORMATION
CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Minor alterations	С
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gabled Ell	Parged
DETAILS	PORCH
Queen Anne	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double hung & other
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood	-
PLAN	SIGNIFICANCE
Т	-
NO OF STORIES	HISTORIC FEATURES
2	Front gable bay intersected by west-side gal
ROOF TYPE	corners and sunburst ornament under gable gable bay on east facade; historic wood surr
Cross Gable	window openings
ROOF MATERIAL	ALTERATIONS

Asphalt - shingle

able ell; with cutaway e; 2-story square rrounds and lintels on

Hipped roof front entry porch and front sun porch are historic alterations (replaced original wraparound front porch some time between 1924 and 1933); 1/1 replacement windows in original openings (not historic)



Photo Id: MapleAveW133(2)



Photo Id: MapleAveW133(3)



Photo Id: maple133(2)



Photo Id: maple133

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/HIST</u>	TORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOV	/ING INFORMATION
PERMIT MOV	TING INFORMATION
MOVING PERMIT #	DATE MOVED
PIOVING PERMIT #	DATE MOVED
-	
ORIGINAL PE	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
No Permit # (2/17/1955)replace obsolete heating unit	-
, , , ,	

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER	134		
END STREET NUMBER	-		
STREET # SUFFIX	-		
STREET NAME	W. Maple Avenue		
PIN			
<b>LOCAL</b>			
WITHIN LOCAL DISTRICT?	No		
LOCAL DIST CONTRIB/NON-CONTRIB?	С		
LOCAL LANDMARK?	No		
YEAR	-	Photo Ide Maria Ava Wd 24/2)	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW134(3)	
CRITERIA	-		
	<u>BUILDI</u>	ING DETAILS	
BUILDING NAME		ZONING	
-		R-7	
GROUND FLOOR USE		NUMBER OF STORIES	
Residential		2	
UPPER FLOOR USE		PROPERTY INDEX NUMBER	
Residential		1116311007	
CURRENT OCCUPANT			
-			
	<u>NATION</u>	AL REGISTER	
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?	
С		No	
WITHIN DISTRICT?		CRITERIA	
No		-	
NR LANDMARK?		ALTERNATE ADDRESS?	
No		-	
YEAR			
-			
	<b>GENERAL</b>	INFORMATION	
CATEGORY		HISTORIC USE	
Building		Domestic - single dwelling	
CONDITION		SECONDARY STRUCTURE	
Good		Detached garage	
INTEGRITY		NR SECOND	
Minor alterations		С	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1; 3/1; 4/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof and rectangular massing; east and west gables;
ROOF TYPE	east side three-sided window bay; wood windows
Front Gable	ALTERATIONS
ROOF MATERIAL	Replacement siding; front porch screened; shutters
Asphalt - shingle	



Photo Id: MapleAveW134(4)



Photo Id: maple134

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/H</u>	ISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT N	MOVING INFORMATION
<u>i Lixi-izi i</u>	TOTING IN OKMATION
MOVING PERMIT #	DATE MOVED
-	
<u>ORIGINAL</u>	PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	_

Domestic - single dwelling

**BEGINNING STREET NUMBER** 205 **END STREET NUMBER** STREET # SUFFIX STREET NAME W. Maple Avenue **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** Photo Id: MapleAveW205(1) LOCAL LANDMARK ELIGIBLE? Potentially Eligible **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** R-7 **GROUND FLOOR USE** NUMBER OF STORIES Residential **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential 1116315003 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good Detached garage INTEGRITY NR SECOND Minor alterations and additions **CURRENT USE** 

ARCHITECTURAL CLASSIFICATION	
Queen Anne/Colonial Revival	
DETAILS	
-	
OTHER YEAR	
-	
DATE SOURCE	_
Surveyor	
WALL MATERIAL (CURRENT)	_
Wood	
WALL MATERIAL 2 (CURRENT)	_
Wood - shingles	
PLAN	_
Irregular	
NO OF STORIES	
2.5	
ROOF TYPE	_
Hipped	
ROOF MATERIAL	_
Asphalt - shingle	

#### **FOUNDATION**

Not visible

#### PORCH

Wrap around

#### WINDOW MATERIAL

Aluminum/vinyl

#### **WINDOW MATERIAL 2**

i \_

#### WINDOW TYPE

Double hung & other

#### WINDOW CONFIGURATION

Multi-light/1

#### SIGNIFICANCE

Although altered, this turn-of-the-century Queen Anne with Colonial Revival detailing may be eligible for local landmark designation.

#### HISTORIC FEATURES

Flared hipped roof with overhanging eaves; front and side hipped roof dormers; hipped roof wraparound porch structure; three-sided and square window bays on front facade above porch; east side square oriel bay; 2-story three-sided bay on west elevation

#### ALTERATIONS

Replacement windows in original openings; rear deck addition; one-story rear addition; east end of porch screened; replacement porch piers and front steps/railing on porch



Photo Id: MapleAveW205(2)



Photo Id: maple205



Photo Id: maple2052

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDICT MOVIE	IC THEODINATION
PERMIT MOVIE	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ODICINAL DEDA	ATT THEODMATION
ORIGINAL PERM	<u>MIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#92-102 (7/31/1992)1/2 story addition; 227 (11/28/1951)reshingling roof	-

Domestic - multiple dwelling

		ALTERNATION DE LA CONTRACTOR DE LA CONTR
BEGINNING STREET NUMBER	206	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW206(2)
CRITERIA	-	
	DUITI DI	NC DETAILS
	ROILDI	NG DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential Apartments		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential Apartments		1116311006
CURRENT OCCUPANT		
-		
	NATION	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	<b>GENERAL</b>	INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - multiple dwelling
CONDITION		SECONDARY STRUCTURE
Good		[underground garage]
INTEGRITY	i	NR SECOND
Minor alterations		-
CURRENT USE		

Neo-Colonial	ARCHITECTURAL CLASSIFICATION	FOUNDATION
-	Neo-Colonial	-
OTHER YEAR  - DATE SOURCE  Permits  WALL MATERIAL (CURRENT)  - WALL MATERIAL 2 (CURRENT)  - PLAN  - PLAN  NO OF STORIES  - ROOF TYPE  - ALTERATIONS  - ALTERATIONS  - ALTERATIONS	DETAILS	PORCH
-	-	-
DATE SOURCE  Permits  WALL MATERIAL (CURRENT)  WALL MATERIAL 2 (CURRENT)  PLAN  PLAN  NO OF STORIES  ROOF TYPE  ALTERATIONS  -  WINDOW MATERIAL 2  -  WINDOW TYPE  -  WINDOW CONFIGURATION  -  WINDOW CONFIGURATION  -  ALTERATIONS  -  ALTERATIONS  -	OTHER YEAR	WINDOW MATERIAL
Permits	-	-
WALL MATERIAL (CURRENT)  WINDOW TYPE  WINDOW CONFIGURATION  SIGNIFICANCE  NO OF STORIES  HISTORIC FEATURES  ROOF TYPE  ALTERATIONS  -	DATE SOURCE	WINDOW MATERIAL 2
-	Permits	-
WALL MATERIAL 2 (CURRENT)  - PLAN  - SIGNIFICANCE  - NO OF STORIES  - HISTORIC FEATURES  - ROOF TYPE  ALTERATIONS	WALL MATERIAL (CURRENT)	WINDOW TYPE
- PLAN SIGNIFICANCE	-	-
PLAN  SIGNIFICANCE  -  NO OF STORIES  HISTORIC FEATURES  -  ROOF TYPE  ALTERATIONS  -	WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-	-
NO OF STORIES  - ROOF TYPE  - ALTERATIONS  -	PLAN	SIGNIFICANCE
- COP TYPE ALTERATIONS - COP TYPE	-	-
ROOF TYPE ALTERATIONS  -	NO OF STORIES	HISTORIC FEATURES
	-	-
	ROOF TYPE	ALTERATIONS
ROOF MATERIAL	-	-
	ROOF MATERIAL	



Photo Id: Maple206

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	Meyer, Lincoln
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Meyer, Lincoln	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
Budinger, Jean-Paul	Downtown Libertyville
ARCHITECT SOURCE	
Permit	
PERMIT/H	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
<u>PERMIT I</u>	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINAI</u>	PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
4807	-
DATE	COA INFO
2/24/1969	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
2 story brick and frame apartment building	-
COST	OTHER SOURCES
\$247,000.00	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
No	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER

Domestic - single dwelling

BEGINNING STREET NUMBER	213	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW213(1)
CRITERIA	-	
	BUILDIN	NG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116315014
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	NATIONA	AL REGISTER  NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	NFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		-
INTEGRITY		NR SECOND
Minor alterations and additions		-
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
-	Wrap around
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof and rectangular massing; 2-st
ROOF TYPE	gable bay; some historic windows (1st and 2nd
Front Gable	ALTERATIONS
ROOF MATERIAL	Penlacement siding: some replacement window

Asphalt - shingle

ory east side stories of front

placement siding; some replacement windows in original openings on side elevation; new window under front gable; extensive alterations to porch (concrete base and steps, wrought iron railings); 1 story rear addition (1980); rear deck addition (1980)



Photo Id: MapleAveW213(2)



Photo Id: maple213

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
OLD ADDRESS	RIC INFORMATION  DATE OF CONSTRUCTION
MOVING PERMIT #	- IT INFORMATION
ORIGINAL PLKI	TIT INTORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
_	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#2901 (7/19/1961)repair front porch (new floor, ceiling, cornice boards, railing and columns), remove side door, install	-
window; 79-185 (8/15/1980)addition; JB-05-0029 (5/2/2006)shed	

**CURRENT USE** 

Religion - religious facility

BEGINNING STREET NUMBER	219	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	THE VIEW OF
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW219(7)
CRITERIA	-	
	BUILDIN	NG DETAILS
BUILDING NAME		ZONING
First Presbyterian Church		I-B
GROUND FLOOR USE		NUMBER OF STORIES
Church		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Church		1116300138
CURRENT OCCUPANT		
ND DYCTDYGT CONTDYD (NOV CONTDYD	NATIONA	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC WITHIN DISTRICT?		No CRITERIA
No		_
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	NFORMATION
CATEGORY		HISTORIC USE
Building		Religion - religious facility
CONDITION		SECONDARY STRUCTURE
Good		
INTEGRITY		NR SECOND
Major alterations and/or additions		-

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Colonial Revival	Not visible
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
1961; 1985	Wood
DATE SOURCE	WINDOW MATERIAL 2
Illinois Digital Archives; Permits	Clad Wood
WALL MATERIAL (CURRENT)	WINDOW TYPE
Brick	Combination
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2	Original church building at northwest corner of loteast end of
ROOF TYPE	front (north) facade features full-height pilasters and triangular pediment; three front entries with classical surrounds; 2-story
Combination	west secondary entrance bay with triangular pediment; his
ROOF MATERIAL	wood windows; office wing with flat roof and wood cornice
	ALTERATIONS

2-story educational building addition at east end of original building (1961); 2-story addition south of original church building (larger than original building and 1961 addition combined), with new sanctuary and offices--addition features a new main entrance with front portico and steeple along Douglas Avenue



Photo Id: MapleAveW219(4)



Photo Id: MapleAveW219(3)



Photo Id: Maple219



Photo Id: Maple219



Photo Id: 219maple

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT /UICTOR	NIC INFORMATION
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDIGE MOVEM	IC INFORMATION
PERMII MOVIN	<u>IG INFORMATION</u>
MOVING PERMIT #	DATE MOVED
-	-
ODICINAL DEDM	ATT INFORMATION
ORIGINAL PERM	<u>IIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	#86-314 (7/14/1986)storage shed
DATE	COA INFO
-	From Illinois Digital Archives (info from Libertyville-Mundelein
BUILDING PERMIT DESCRIPTION	Historical Society and Cook Memorial Public Library)"This
-	church was organized in 1886. The first building was on East Church Street on land that had belonged to Horace Butler. The
COST	first pastor was Reverend George P. Folsom. In 1825, the
	congregation bought a lot at the corner of Douglas Street and
ORIGINAL OWNER OCCUPIED?	Maple Avenue. The building erected thereon was dedicated in 1928 and is shown in this photograph. Over the years the
ORIGINAL OWNER OCCOPIED!	building was added to and in 1955 the adjoining property was
-	purchased. An education building was erected and dedicated in
EXTERIOR ALTERATION PERMITS	1961."
#2782 (11/15/1960)educational building addition; No permit	HISTORIC INFO
# (12/17/1992)aluminum soffit and fascia; 85-86 (4/9/1985)- -new sanctuary, offices, classrooms, and kitchen	Historic photograph of church on Illinois Digital Archives (in
(\$1,700,000.00)	collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library)
	http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1
	1/id/2095/rec/12
	OTHER SOURCES
	Sanborn Maps1924, 1933, 1948
	HISTORIC INFO COMPILER
	LR
	VOLUNTEER
	- 5-5
	-

**CURRENT USE** 

Domestic - single dwelling

**BEGINNING STREET NUMBER** 234 **END STREET NUMBER** STREET # SUFFIX STREET NAME W. Maple Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** Photo Id: MapleAveW234(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** R-7 **GROUND FLOOR USE** NUMBER OF STORIES Residential PROPERTY INDEX NUMBER **UPPER FLOOR USE** Residential 1116311019 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good [attached garage] INTEGRITY NR SECOND Historic alterations and additions

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Side Gable	Brick
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
1925 (c)	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor/Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double hung & fixed
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	3/1; 1-light
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Side gable roof and rectangular massing
ROOF TYPE	ALTERATIONS
Multi-gable	2-story enclosed front porch addition (1920sfoundation is
ROOF MATERIAL	different than side gable section) with 3/1 windows on front facade; stucco cladding (1920s); single-light wood replacen
Asphalt - shingle	windows throughout (not historically compatible type or



Photo Id: MapleAveW234(3)



Photo Id: Maple234

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT/HISTOR	RIC INFORMATION
<u> </u>	ALC INI OKHATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
<u>PERMIT MOVIN</u>	<u>G INFORMATION</u>
MOUTING DEDMIT #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINAL PERM</u>	<u>IT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn maps1933 (Sheet 4), 1948 (Sheet 4)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#2786 (11/21/1960)reshingle roof; JBA-01-0030 (3/27/2001)- -garage addition	-

Domestic - single dwelling

BEGINNING STREET NUMBER	302	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	Photo Td. Manla AvelW202/2)
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW302(3)
CRITERIA	-	
	BUILD	ING DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116311018
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	NATIO	NAL REGISTER  NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		_
YEAR		
-		
	<u>GENERAL</u>	<u>INFORMATION</u>
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Historic additions/minor alterations		NC
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gabled Ell	Concrete-block
DETAILS	PORCH
-	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	6/1; 1/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2	Hipped main roof, with large 2-story gable front bay and 2-story
ROOF TYPE	west side gable bay; smaller gable along roofline at east elevation
Gable-on-Hip	ALTERATIONS
ROOF MATERIAL	ALIERATIONS

Asphalt - shingle

Replacement front sun porch (historic--pre-1933); non-historic shed-roof entry porch at east end of front sun porch; northwest corner sun porch (historic--pre-1933); non-historic replacement windows in original openings on front and side elevations of house; one-story rear addition (historic--pre-1933)



Photo Id: MapleAveW302(2)



Photo Id: maple302

OLD ADDRESS (CITY DIR.YEAR	BUILDER
- PULL DANG MOVEDS	- CUDVEYOR
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
_	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
<u>PERMIT</u>	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINA</u>	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	JRM-05-0021 (7/8/2005)garage
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
_	
COST	OTHER SOURCES
-	Sanborn Maps1933 (Sheet 4), 1948 (Sheet 4)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#1711 (2/5/1957)3 windows out/1 window in 4/6;	-
, , , , , , , , , , , , , , , , , , , ,	

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER	305	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Maple Avenue	
PIN	- Trapic / Transc	
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	SSRUCE SOLAR
YEAR		Helping Another Family Have to the San 847-677-0950 Nate Variable San 847-677-0950
	N-	Photo Id: MapleAveW305(1)
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	
	BUILDI	NG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116300137
CURRENT OCCUPANT		
[-		
	<u>NATION A</u>	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
C		No
WITHIN DISTRICT?		CRITERIA
No NR LANDMARK?		ALTERNATE ADDRESS?
No No		-
YEAR		
-		
	<u>GENERAL I</u>	<u>INFORMATION</u>
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
Condition		SECONDARY STRUCTURE
Good		[attached garage
INTEGRITY Miner alterations and additions		NR SECOND
Minor alterations and additions		1 -

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional - Craftsman	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	



Photo Id: MapleAveW305(2)



Photo Id: maple305

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
	j
<u>PERMIT/HISTO</u>	ORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DERMIT MOV	ING INFORMATION
FEMPILI PIOV.	ING INI OKMATION
MOVING PERMIT #	DATE MOVED
<u>ORIGINAL PER</u>	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1933 (Sheet 4), 1948 (Sheet 4)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#845 (5/15/1954)exterior workrear steps, enclose rear	-
porch, renew side and front steps; #2370 (8/23/1950)Flat	