BEGINNING STREET NUMBER	435	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: ParkAveW435(1)

### **BUILDING DETAILS**

BUILDING NAME	ZONING
-	R-7
GROUND FLOOR USE	NUMBER OF STORIES
Residential Apartments	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential Apartments	1121108003
CURRENT OCCUPANT	
-	

### **NATIONAL REGISTER**

NR DISTRICT CONTRIB/NON-CONTRIB	
с	
WITHIN DI	STRICT?
No	
NR LANDM	ARK?
No	
YEAR	
-	

### NR ELIGIBLE?

No CRITERIA

-

ALTERNATE ADDRESS?

### **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Minor alterations	
CURRENT USE	
Domestic - multiple dwelling	

### HISTORIC USE

Domestic - single dwelling

SECONDARY STRUCTURE

[attached garage]

NR SECOND

-

#### ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

### OTHER YEAR

-----

DATE SOURCE

Assessor

### WALL MATERIAL (CURRENT)

Wood

### WALL MATERIAL 2 (CURRENT)

Wood - shingles

### PLAN

Irregular

NO OF STORIES

### 2

ROOF TYPE

#### Front Gable

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Brick

### PORCH

Wrap around

### WINDOW MATERIAL

Wood

### WINDOW MATERIAL 2

-

### WINDOW TYPE

Double hung & fixed

### WINDOW CONFIGURATION

1/1; 1-light; multi-light

### SIGNIFICANCE

#### HISTORIC FEATURES

Nested front gables on front facade; wrap around porch with turned columns and spindlework; historic front door; multi-light window on west facade

### ALTERATIONS

Replacement siding; railings removed on porch; windows (1/1 double hung) are wood replacement windows, likely from the mid-20th century; octagonal window on front facade; two-story rear addition; one-story rear/west garage addition



Photo Id: ParkAveW435(3)



Photo Id: Maple435



Photo Id: wpark435

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
_	
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGIN	AL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
DATE	COA INFO
-	
BUILDING PERMIT DESCRIPTION	HISTORIC INFO

\_ COST -

\_

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

-

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

\_

-

\_

BEGINNING STREET NUMBER	101
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN101(1)

### **BUILDING DETAILS**

### **BUILDING NAME**

-
GROUND FLOOR USE
Funeral Home
UPPER FLOOR USE
Funeral Home
CURRENT OCCUPANT
McMurrough Funeral Chapel

### ZONING C-2

NUMBER OF STORIES

2

PROPERTY INDEX NUMBER

1121202012

### **NATIONAL REGISTER**

### NR DISTRICT CONTRIB/NON-CONTRIB

С	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

#### **NR ELIGIBLE?**

No

CRITERIA

### ALTERNATE ADDRESS?

-

### **GENERAL INFORMATION**

CATEGORY	

INTEGRITY	
Good	
CONDITION	
Building	

Major alterations and additions (historic)

### CURRENT USE

Funerary - mortuary

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
NR SECOND
-

#### ARCHITECTURAL CLASSIFICATION

Neo-Colonial

OTHER YEAR

1950s

DATE SOURCE

Surveyor/

### WALL MATERIAL (CURRENT)

Aluminum/vinyl

### WALL MATERIAL 2 (CURRENT)

Aluminum/vinyl

### PLAN

Irregular

### NO OF STORIES

### 2

ROOF TYPE

#### Front Gable

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Not visible

PORCH

Full Front

### WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

#### -

WINDOW TYPE

Double hung & other

#### WINDOW CONFIGURATION

#### 12/12; 1/1

SIGNIFICANCE

#### -

#### HISTORIC FEATURES

Some original windows visible along south elevation

### ALTERATIONS

East facade expanded and reconfigured into a Neo-Colonial design, with full-height front portico and symmetrical fenestration; replacement windows throughout original house; 1-story west addition stretching nearly to the west end of the lot, with secondary entrance facing south onto Park Avenue



Photo Id: ParkPIN101(3)



Photo Id: ParkPlN101(7)



Photo Id: parkpla101



Photo Id: parkp101



Photo Id: park101

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT	HISTORIC INFORMATION

#### **OLD ADDRESS**

DATE OF CONSTRUCTION

### **PERMIT MOVING INFORMATION**

**MOVING PERMIT #** 

DATE MOVED

### **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

**ORIGINAL OWNER OCCUPIED?** 

EXTERIOR ALTERATION PERMITS

#### **OTHER PERMIT INFORMATION**

-

\_

COA INFO

HISTORIC INFO

According to the company website, "In 1947, Bernice and John "Jack" McMurrough purchased the then Osborne Funeral Home at our current location. Osborne's promotional material denoting the company as "Furniture and Undertaking." Jack also operated an emergency ambulance service along with the funeral home, this was long before the village had its own ambulance service. In the 1950's they expanded the funeral home to include the current main chapel expanding the facility to over twice its size."(http://libertyvillefuneralhome.com/109/Our\_Family.html) Historic photograph of house before alterations (from the early 1950s) at Illinois Digital Archives (in collection of the Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--

http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/2054/rec/2 Historic photograph of House on page

### OTHER SOURCES

Sanborn Maps--1924, 1933, 1948

HISTORIC INFO COMPILER

#### LR

### VOLUNTEER

BEGINNING STREET NUMBER	102
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN102(1)

### **BUILDING DETAILS**

### **BUILDING NAME**

-	
GROUND FLOOR USE	
Commercial	
UPPER FLOOR USE	
Unknown	
CURRENT OCCUPANT	

ZONING	
C-2	
NUMBER OF STORIES	
1.5	
PROPERTY INDEX NUMBER	
-	

### **NATIONAL REGISTER**

### NR DISTRICT CONTRIB/NON-CONTRIB

С	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

### **NR ELIGIBLE?**

No

CRITERIA

### ALTERNATE ADDRESS?

-

## **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
minor alterations and additions	
CURRENT USE	
Commerce/Trade	

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
NR SECOND
-

#### ARCHITECTURAL CLASSIFICATION

Bungalow

DETAILS

OTHER YEAR

\_

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

**NO OF STORIES** 

1.5

ROOF TYPE

Hipped

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Concrete-block

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

3/1

SIGNIFICANCE

### HISTORIC FEATURES

Hipped roof with overhanging eaves; south side hipped dormer; hipped-roof front porch with solid knee walls and grouped

square columns; three-sided front and south bay windows

### ALTERATIONS

Replacement siding; replacement windows in original openings (historic configuration); rear porch enclosed



Photo Id: ParkPIN102(3)



Photo Id: parkplace102

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-

### **PERMIT MOVING INFORMATION**

**MOVING PERMIT #** 

DATE MOVED

### **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

#### **OTHER PERMIT INFORMATION**

| -

\_

COA INFO

### HISTORIC INFO

From Illinois Digital Archives (info from Libertyville-Mundelein Historical Society and Cook Memorial Public Library): "This is a mail-order house from the Sears Catalog. The name of the model is Avondale. This model was offered between 1911 and 1922. It has been remodeled with a rear addition and aluminum siding. According to the original Sears catalog description, this was "a fine example of a modern bungalow."

#### OTHER SOURCES

#### HISTORIC INFO COMPILER

LR

### VOLUNTEER

-

BEGINNING STREET NUMBER	210
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN210(2)

### **BUILDING DETAILS**

### **BUILDING NAME**

-	
GROUND FLOOR USE	
Duplex	
UPPER FLOOR USE	
Duplex	
CURRENT OCCUPANT	

R-7 NUMBER OF STORIES

PROPERTY INDEX NUMBER

1116422019

ZONING

2

### **NATIONAL REGISTER**

### NR DISTRICT CONTRIB/NON-CONTRIB

NC	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

#### NR ELIGIBLE?

No

CRITERIA

### ALTERNATE ADDRESS?

\_

### **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	-
Excellent	]
INTEGRITY	_
Not altered	]
CURRENT USE	-
Domestic - multiple dwelling	]

HISTORIC USE	
Domestic - multiple dwelling	
SECONDARY STRUCTURE	
-	
NR SECOND	
-	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURA
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	

ATION



Photo Id: ParkPIN210(3)



Photo Id: ParkPlace210

OLD ADDRESS (CITY DIR.YEAR	BUILDER	
-	-	
BUILDING MOVED?	SURVEYOR	
-	LR	
MOVED FROM	SURVEYOR ORGANIZATION	
-	Ramsey Historic Consultants	
ORIGINAL OWNER	SURVEY DATE	
-	May-June 2016	
ORIGINAL ARCHITECT	SURVEY AREA	
-	Downtown Libertyville	
ARCHITECT SOURCE		
-		
PERMIT/HISTO	DRIC INFORMATION	
OLD ADDRESS	DATE OF CONSTRUCTION	
-	-	
PERMIT MOVING INFORMATION		
MOVING PERMIT #	DATE MOVED	
-	-	

### **ORIGINAL PERMIT INFORMATION**

### **BUILDING PERMIT #**

JRB-06-0045

DATE

6/15/2006

**BUILDING PERMIT DESCRIPTION** 

New home construction

COST

\$700,000.00

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

### OTHER PERMIT INFORMATION

JRAB-06-0024 (4/19/2007)--detached garage

COA INFO

-HISTORIC INFO

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR VOLUNTEER

-

BEGINNING STREET NUMBER	216
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN216(1)

### **BUILDING DETAILS**

### **BUILDING NAME**

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
-	
CURRENT OCCUPANT	

ZONING	
R-7	
NUMBER OF STORIES	
2.5	
PROPERTY INDEX NUMBER	

1116422009

### **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

### NR ELIGIBLE?

No

CRITERIA

### ALTERNATE ADDRESS?

-

## **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Minor alterations	
CURRENT USE	
Domestic - single dwelling	

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
C

#### ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

Craftsman

OTHER YEAR

-DATE SOURCE

- - - -

Sanborn maps (1924, 1933)
WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

### PLAN

Rectangular

liteetangalai

### NO OF STORIES

2.5

### ROOF TYPE

Front Gable

### **ROOF MATERIAL**

Asphalt - shingle

#### FOUNDATION

Concrete-block

PORCH

Corner entry

### WINDOW MATERIAL

Aluminum/vinyl

### WINDOW MATERIAL 2

Wood

WINDOW TYPE

Double Hung

### WINDOW CONFIGURATION

#### 6/6; 3/1; 2/1

SIGNIFICANCE

#### -

#### **HISTORIC FEATURES**

Front gable bay with inset corner entry porch; 3/1 and 2/1 wood windows enclosing porch

### ALTERATIONS

Replacement siding; replacement windows in original openings



Photo Id: ParkPIN216



Photo Id: ParkPl216

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	

### **PERMIT/HISTORIC INFORMATION**

OLD ADDRESS

DATE OF CONSTRUCTION

### **PERMIT MOVING INFORMATION**

**MOVING PERMIT #** 

DATE MOVED

### **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

\_

**ORIGINAL OWNER OCCUPIED?** 

### EXTERIOR ALTERATION PERMITS

2732 (8/26/1960)--construction of concrete stair; No permit # (6/11/1959)--removing old chimney, repair back steps, move one door and one window in rear

#### **OTHER PERMIT INFORMATION**

-

\_

COA INFO

HISTORIC INFO

Sanborn Maps--1924 (Sheet 6), 1933 (Sheet 5), 1948 (Sheet 5) OTHER SOURCES

\_

HISTORIC INFO COMPILER

LR VOLUNTEER

-

BEGINNING STREET NUMBER	218
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN218(1)

### **BUILDING DETAILS**

### **BUILDING NAME**

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

R-7 NUMBER OF STORIES

PROPERTY INDEX NUMBER

1116422008

ZONING

2

### **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

#### NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

\_

### **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Minor alterations	
CURRENT USE	
Domestic - single dwelling	

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
NC

#### ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

### PLAN

Rectangular

NO OF STORIES

2

### ROOF TYPE

Front Gable

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Brick

PORCH

Front entry

### WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

### WINDOW CONFIGURATION

1/1

### SIGNIFICANCE

-

#### HISTORIC FEATURES

Front gable roof and rectangular massing; gable roof front porch structure; historic wood front door

### ALTERATIONS

One-story rear addition; replacement siding; replacement porch supports; fixed shutters



Photo Id: ParkPIN218



Photo Id: ParkPl218

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT	HISTORIC INFORMATION
<u>FERMIN</u>	INSTORIC IN ORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ODICINA	
ORIGINA	AL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	99-423 (1/3/2000)detached garage
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	Sanborn Maps1924 (Sheet 6), 1933 (Sheet 5), 1948 (Sheet 5)
COST	OTHER SOURCES

ORIGINAL OWNER OCCUPIED?

\_

\_

EXTERIOR ALTERATION PERMITS

| -

### HISTORIC INFO COMPILER

LR VOLUNTEER

-

BEGINNING STREET NUMBER	220
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN220(1)

### **BUILDING DETAILS**

### **BUILDING NAME**

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

ZONING	
D_8	

NUMBER OF STORIES

2

PROPERTY INDEX NUMBER

1116422007

### **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

С	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

#### NR ELIGIBLE?

No

CRITERIA

### ALTERNATE ADDRESS?

-

## **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	_
Moderate alterations	
CURRENT USE	
Domestic - multiple dwelling	

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
C

#### ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

### OTHER YEAR

-DATE SOURCE

Surveyor

### WALL MATERIAL (CURRENT)

Aluminum/vinyl

### WALL MATERIAL 2 (CURRENT)

PLAN

#### Rectangular

NO OF STORIES

### 2

**ROOF TYPE** 

#### Hipped

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Parged

PORCH

#### Full Front

#### WINDOW MATERIAL

Wood

#### WINDOW MATERIAL 2

-

### WINDOW TYPE

Double Hung

### WINDOW CONFIGURATION

#### 1/1

### SIGNIFICANCE

-

#### **HISTORIC FEATURES**

Hipped roof; two-story front gable bay with cutaway corners and pent roof

### ALTERATIONS

Replacement front porch (post-1948); replacement siding (1974); replacement windows in original openings (historic, not original); rear addition (1971)



Photo Id: ParkPIN220(3)



Photo Id: ParkPIN220



Photo Id: ParkPlace220



Photo Id: ParkPlace220(2)



Photo Id: 220parkplace

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	

### **PERMIT/HISTORIC INFORMATION**

#### OLD ADDRESS

DATE OF CONSTRUCTION

### **PERMIT MOVING INFORMATION**

#### **MOVING PERMIT #**

-

DATE MOVED

### **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

-

ORIGINAL OWNER OCCUPIED?

### EXTERIOR ALTERATION PERMITS

7666 (3/4/1974)--aluminum siding; 6444 (7/22/1971)-enlarging kitchen 2nd floor apartment, adding small porch, adding outside stairway to 2nd floor apartment; 2695 (7/18/1960)--reshingle roof, change siding, insulate walls, repair front porch and stairs

#### **OTHER PERMIT INFORMATION**

|-

\_

COA INFO

HISTORIC INFO

-

### OTHER SOURCES

Sanborn Maps--1912 (Sheet 3); 1924 (Sheet 6), 1933 (Sheet 5), 1948 (Sheet 5)

#### HISTORIC INFO COMPILER

LR

#### VOLUNTEER

-

BEGINNING STREET NUMBER	221
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPlace221

### **BUILDING DETAILS**

BUILDING NAME	ZONING
St. Joseph School	I-B
GROUND FLOOR USE	NUMBER OF STORIES
School	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
School	-
CURRENT OCCUPANT	
St. Joseph School	

### **NATIONAL REGISTER**

### NR DISTRICT CONTRIB/NON-CONTRIB

NC	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

### NR ELIGIBLE?

No

CRITERIA

\_\_\_\_\_

### ALTERNATE ADDRESS?

-

### **GENERAL INFORMATION**

CATEGORY	HISTORIC USE
Building	Education - school
CONDITION	SECONDARY STRUCTURE
Good	-
INTEGRITY	NR SECOND
Major alterations and additions	-
CURRENT USE	
Education - school	

### ARCHITECTURAL CLASSIFICATION

	Romanesque Revival/Gothic Revival (original building)
DETAILS	

#### DETAILS

International Style (addition)

### OTHER YEAR

1957-8; 1992

### DATE SOURCE

Libertyville Then & Now (p. 28); permits

### WALL MATERIAL (CURRENT)

Brick

### WALL MATERIAL 2 (CURRENT)

Concrete; metal

#### PLAN

Irregular

#### NO OF STORIES

2&3

### ROOF TYPE

Combination

### ROOF MATERIAL

Asphalt - single/not visible

#### FOUNDATION

Concrete

PORCH

East entry

#### WINDOW MATERIAL

Metal

### WINDOW MATERIAL 2

-

### WINDOW TYPE

Double hung, fixed & awning

### WINDOW CONFIGURATION

1/1; 1-light

### SIGNIFICANCE

-

#### HISTORIC FEATURES

Original 1925-6 Romanesque Revival building still partially visible along Maple--red brick exterior, parapet gable main roof; lower front gable bay with crenelated, stepped parapet; brick label molds over select windows; center entry bay (now partially obscured) with stone crest ornament, panel, and pointed-arch window openings at upper stories

#### ALTERATIONS

1926 building obscured by multiple additions, dating from the mid-20th century and later. 1957 addition (historic)--2-story south addition features ribbon first-floor windows and ribbon clerestory windows on 2nd story; 1-story projecting north section features a flat roof, recessed entry with round columns, and buff brick exterior; long, 1st-story concrete planters Nonhistoric alterations include: hipped roof added to south section of building (1992); some windows removed for air conditioning units along east and west facades of south section; multiple additions at rear (west) elevation of building (no date, not historic); metal roofing and replacement windows in north side entry (in front of 1920s school building)





Photo Id: MapleAveE121(1) Photo Id: St\_Josephs\_Catholic\_School

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	Peterson & Weeks
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
Hyland & Corse	Downtown Libertyville
ARCHITECT SOURCE	
Libertyville: Then & Now (p. 28)	

### **PERMIT/HISTORIC INFORMATION**

#### **OLD ADDRESS**

DATE OF CONSTRUCTION

### **PERMIT MOVING INFORMATION**

#### **MOVING PERMIT #**

-

DATE MOVED

### **ORIGINAL PERMIT INFORMATION**

#### **BUILDING PERMIT #**

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

-

**ORIGINAL OWNER OCCUPIED?** 

#### EXTERIOR ALTERATION PERMITS

90-655 (10/26/1990)--remodeling of existing building, adding elevator, adding bridge addition for elevator walkway; 92-482 (8/6/1992)--installing new sloped roof over existing

#### **OTHER PERMIT INFORMATION**

| -

\_

COA INFO

### HISTORIC INFO

Original school building along Maple Avenue was completed in 1926. The new school was begun in 1957 and completed in 1959 ("Celebrating the Bi-Centennial: 1776-1976, Libertyville, IL"); From LIBERTYVILLE: THEN & NOW (p. 28): "After many years of consideration, construction started in 1925 on St. Joseph Catholic School. The building, designed by Hyland and Corse, was built at a cost of \$80,000. The school opened in 1926 with an enrollment of 150 children. In 1957, ground was broken on a new expansion project adding classrooms, a convent, chapel, and one of the largest grammar school gymnasiums in the archdiocese. With many expansions, the school continues to serve as a kindergarten through eighth educational facility."

### OTHER SOURCES

Sanborn Maps--1948

### HISTORIC INFO COMPILER

LR

VOLUNTEER

-

BEGINNING STREET NUMBER	222
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN222(1)

### **BUILDING DETAILS**

### **BUILDING NAME**

GROUND FLOOR USE	
Duplex	
UPPER FLOOR USE	
N/A	
CURRENT OCCUPANT	

ZONING R-8 NUMBER OF STORIES 1 PROPERTY INDEX NUMBER 1116422006

# NATIONAL REGISTER

#### NR DISTRICT CONTRIB/NON-CONTRIB

WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

#### **NR ELIGIBLE?**

No

CRITERIA

\_\_\_\_\_

### ALTERNATE ADDRESS?

-

### **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Minor alterations	
CURRENT USE	
Domestic - multiple dwelling	

### HISTORIC USE

Domestic - multiple dwelling

SECONDARY STRUCTURE

-

NR SECOND

#### ARCHITECTURAL CLASSIFICATION

Ranch

DETAILS

OTHER YEAR

\_\_\_\_\_

DATE SOURCE

Permit

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

1

**ROOF TYPE** 

Hipped

**ROOF MATERIAL** 

Asphalt - shingle

### FOUNDATION

Concrete

PORCH

Multiple entries

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Glass Block

WINDOW TYPE

Double hung & fixed

WINDOW CONFIGURATION

2/2 horizontal; 1-light

SIGNIFICANCE

### HISTORIC FEATURES

hipped roof with overhanging eaves; corner entry porches with wrought iron railings; historic doors; double hung and picture windows

### ALTERATIONS

Glass block in north side window; replacement secondary entry porch on north elevation



Photo Id: ParkPlace222

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	L. C. Modern Home Builders
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Dishak, Ben	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT	/HISTORIC INFORMATION

### OLD ADDRESS

DATE OF CONSTRUCTION

### **PERMIT MOVING INFORMATION**

-

-

#### **MOVING PERMIT #**

-

DATE MOVED

### **ORIGINAL PERMIT INFORMATION**

### **BUILDING PERMIT #**

3584

DATE

10/29/1964

**BUILDING PERMIT DESCRIPTION** 

Erect 2 unit duplex apartment

COST

\$28,000.00

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

#### **OTHER PERMIT INFORMATION**

COA INFO

\_

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR VOLUNTEER

.

BEGINNING STREET NUMBER	230	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Park Place	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	Yes	
CRITERIA	А, Н	



Photo Id: ParkPIN230(3)

### **BUILDING DETAILS**

### **BUILDING NAME**

St. John's Evangelical Lutheran Church Parsonage	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	
-	

ZONING
R-7
NUMBER OF STORIES
2
PROPERTY INDEX NUMBER
1116422002

### **NATIONAL REGISTER**

### NR DISTRICT CONTRIB/NON-CONTRIB

WITHIN DISTRICT?	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

### NR ELIGIBLE?

No

CRITERIA

### ALTERNATE ADDRESS?

-

## **GENERAL INFORMATION**

ł

ATEGORY	
Building	
ONDITION	
Good	
INTEGRITY	
Minor alterations	
URRENT USE	
Domestic - single dwelling	

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
NC

#### ARCHITECTURAL CLASSIFICATION

Craftsman

DETAILS

OTHER YEAR

-

### DATE SOURCE

Owner (House History Questionnaire)

### WALL MATERIAL (CURRENT)

Brick

### WALL MATERIAL 2 (CURRENT)

PLAN

Irregular

#### NO OF STORIES

2.5

### ROOF TYPE

Hipped

#### **ROOF MATERIAL**

Asphalt - shingle

#### FOUNDATION

Not visible

PORCH

### Front

### WINDOW MATERIAL

Wood

### WINDOW MATERIAL 2

Aluminum/vinyl

### WINDOW TYPE

Double hung, casement & awning

### WINDOW CONFIGURATION

3/1; 4-light; multi-light

### SIGNIFICANCE

This handsome Craftsman residence served as the parsonage for St. John's Lutheran Church from 1927-1965.

### HISTORIC FEATURES

Hipped roof; 2-story southwest corner square bay; front dormer; hipped-roof front porch with brick piers and knee walls; historic 3/1, 4-light, and leaded glass windows

### ALTERATIONS

Front porch enclosed (new windows and doors in original porch structure--c. 2010)



Photo Id: ParkPIN230



Photo Id: ParkPlace230

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
OLD ADDRESS	DATE OF CONSTRUCTION
PERM	MIT MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
- ORIG	INAL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	JRAB-09-0013 (8/12/2009)garage
DATE	COA INFO

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

### HISTORIC INFO

House was constructed in 1923-4 as the first parsonage for St. John's Evangelical Lutheran Church. The congregation acquired the land in 1904. The first resident of the parsonage was Reverend William Lehmann, who lived in the house from 1927-1965. The house was then used as a rental until 2009, when it was sold to Lazzaretto Construction [see house history questionnaire provided by current owner]

#### OTHER SOURCES

Sanborn Maps--1912 (Sheet 3); 1924 (Sheet 6); 1933 (Sheet 5); 1948 (Sheet 5)

### HISTORIC INFO COMPILER

LR VOLUNTEER