Historic Libertyville

Commerce/Trade

BEGINNING STREET NUMBER 536-542 **END STREET NUMBER** STREET # SUFFIX STREET NAME N. Milwaukee Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? **LOCAL LANDMARK? YEAR** Photo Id: MilwaukeeAveN536-542(1) LOCAL LANDMARK ELIGIBLE? Potentially Eligible **CRITERIA** A, D **BUILDING DETAILS BUILDING NAME** ZONING First National Bank C-1 NUMBER OF STORIES **GROUND FLOOR USE** Commercial UPPER FLOOR USE PROPERTY INDEX NUMBER Unknown 1116405001 (536), CURRENT OCCUPANT Vacant/Spring Valley Trading Co. (536), Avenue 21 Dancewear (538), Dancenter North (540), Starbucks (542) **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? С No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No **YEAR GENERAL INFORMATION CATEGORY HISTORIC USE** Building Commerce/Trade CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Moderate alterations **CURRENT USE**

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	
Two Part Commercial Block	
DETAILS	
-	
OTHER YEAR	
-	
DATE SOURCE	_
Sanborn Maps/Surveyor	
WALL MATERIAL (CURRENT)	
Brick	
WALL MATERIAL 2 (CURRENT)	
-	
PLAN	
Rectangular	
NO OF STORIES	
3	
ROOF TYPE	
Flat	
ROOF MATERIAL	
Not Visible	

FOUNDATION

Not visible

PORCH

-

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

_

WINDOW TYPE

Double hung & storefront

WINDOW CONFIGURATION

6/1; 1-light

SIGNIFICANCE

Despite alterations, this brick commercial block with 1930s Art Deco/Art Moderne storefront may be eligible for local landmark designation.

HISTORIC FEATURES

Brick west and north facades; ornamental brick panels under metal cornice; continuous soldier course string course at 2ndstory window openings; stone storefront at northwest corner is historic alteration dating from c. 1930

ALTERATIONS

Original bank entrance with columns and oversized canopy removed; northwest corner storefront remodeled (c. 1930-historic alteration), with stone surround; storefronts at south side remodeled (1960s-70s), but later rehabilitated into historic configuration; round-arch 2nd story windows at east end of north facade bricked in--smaller 6/1 windows placed within opening; replacement windows on first story of north facade; replacement 2nd and 3rd story windows on both facades (historic configuration)

ADDITIONAL PHOTOGRAPHS



Photo Id: 538-540NMilwaukeeAve



Photo Id: NMil536542



Photo Id: 536-542milwaukee



Photo Id: 536-542milwaukee2



Photo Id: 536-542milwaukee3

HISTORIC INFORMATION

MOVED FROM ORIGINAL OWNER ORIGINAL ARCHITECT ARCHITECT SOURCE PERMIT/HISTORI OLD ADDRESS PERMIT MOVING MOVING PERMIT # ORIGINAL PERMIT BUILDING PERMIT # BUILDING PERMIT # COST COST COGRIGINAL OWNER OCCUPIED? CORIGINAL OWNER OCCUPIED?	DATE OF CONSTRUCTION - INFORMATION DATE MOVED -
DERMIT MOVING MOVING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	LR SURVEYOR ORGANIZATION Ramsey Historic Consultants SURVEY DATE May-June 2016 SURVEY AREA Downtown Libertyville CINFORMATION DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
ORIGINAL OWNER ORIGINAL ARCHITECT ARCHITECT SOURCE PERMIT/HISTORI OLD ADDRESS PERMIT MOVING MOVING PERMIT # ORIGINAL PERMIT BUILDING PERMIT # BUILDING PERMIT DESCRIPTION COST ORIGINAL OWNER OCCUPIED? EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	SURVEYOR ORGANIZATION Ramsey Historic Consultants SURVEY DATE May-June 2016 SURVEY AREA Downtown Libertyville CINFORMATION DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
ORIGINAL OWNER ORIGINAL ARCHITECT ARCHITECT SOURCE PERMIT/HISTORI OLD ADDRESS PERMIT MOVING MOVING PERMIT # ORIGINAL PERMIT BUILDING PERMIT # BUILDING PERMIT DESCRIPTION COST ORIGINAL OWNER OCCUPIED? EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	Ramsey Historic Consultants SURVEY DATE May-June 2016 SURVEY AREA Downtown Libertyville CINFORMATION DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
ORIGINAL ARCHITECT ARCHITECT SOURCE DERMIT/HISTORI OLD ADDRESS DERMIT MOVING MOVING PERMIT # DATE BUILDING PERMIT DESCRIPTION COST ORIGINAL OWNER OCCUPIED? EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	SURVEY DATE May-June 2016 SURVEY AREA Downtown Libertyville CINFORMATION DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
ORIGINAL ARCHITECT ARCHITECT SOURCE DERMIT/HISTORI OLD ADDRESS DERMIT MOVING MOVING PERMIT # DATE BUILDING PERMIT DESCRIPTION COST ORIGINAL OWNER OCCUPIED? EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	May-June 2016 SURVEY AREA Downtown Libertyville CINFORMATION DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
ARCHITECT SOURCE - PERMIT/HISTORI OLD ADDRESS - PERMIT MOVING MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	SURVEY AREA Downtown Libertyville C INFORMATION DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
ARCHITECT SOURCE - PERMIT/HISTORI OLD ADDRESS - PERMIT MOVING MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	Downtown Libertyville C INFORMATION DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
PERMIT/HISTORI OLD ADDRESS - PERMIT MOVING MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003) replacement upper windows in original openings; 94-508	DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
PERMIT/HISTORI OLD ADDRESS - PERMIT MOVING MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003) replacement upper windows in original openings; 94-508	DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
DERMIT MOVING MOVING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
DERMIT MOVING MOVING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	DATE OF CONSTRUCTION - INFORMATION DATE MOVED - INFORMATION
PERMIT MOVING MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003) replacement upper windows in original openings; 94-508	INFORMATION DATE MOVED INFORMATION
MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	DATE MOVED - INFORMATION
MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	DATE MOVED - INFORMATION
MOVING PERMIT # - ORIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	DATE MOVED - INFORMATION
DRIGINAL PERMIT BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	INFORMATION
BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	
BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	
- COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	- COA INFO
- COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	-
- ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	HISTORIC INFO
- ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	The First National Bank was the second bank in Libertyville,
EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	begun in January of 1903. In 1932, the bank merged with Lake County National Bank into the First Lake County National Bank.
EXTERIOR ALTERATION PERMITS 1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	The upper floors of the building housed a theater, meeting
1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	rooms, and offices.
1048 (3/5/1955)resurfacing front with enameled steel sections, recess front door of aluminum, alter display case; Appearance Review Commission minutes (7/21/2003)replacement upper windows in original openings; 94-508	OTHER SOURCES
(542)	Illinois Digital Archives holds several historic photographs of the building soon after construction, as well as later photos from the 1950s and 1970s: http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/102/rec/3 http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/103/rec/4
	http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6264/rec/5 http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/2107/rec/6 http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/2034/rec/7 http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6265/rec/11 Sanborn Maps1907 (Sheet 2), 1912 (Sheet 2), 1924 (Sheet 2), 1933 (Sheet 2), 1948 (Sheet 2) IMAGES OF AMERICA: LIBERTYVILLE, p. 54-55

VOLUNTEER