

Historic Libertyville

BEGINNING STREET NUMBER	129
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt129(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1121203008
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Moderate alterations and additions	NC
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor/Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable roof; north and south intersecting gables; three-sided north window bay; hipped roof full front porch structure (altered)

ALTERATIONS

Replacement siding; replacement windows in original openings; porch knee wall and columns are non-historic replacements

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt129(2)



Photo Id: First129



Photo Id:

FirstStN129

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

Skinner, William

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

JRR_12-0047 (2012)--front porch; PB-02-0680 (2002)--
replacement siding

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Historic photo of house taken shortly after construction on
Illinois Digital Archives--
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/6504/rec/7>

OTHER SOURCES

Sanborn Maps, 1924, 1933, 1948

HISTORIC INFO COMPILER

LR

VOLUNTEER

-