## **Historic Libertyville**

Domestic - single dwelling

BEGINNING STREET NUMBER	207	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	First Street	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: FirstSt207(1)
CRITERIA		
CRITERIA		
	<u>BUILD</u>	ING DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116422017
CURRENT OCCUPANT		
-		
	<u>10ITAN</u>	NAL REGISTER
	·	
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENEDAL	 _ <u>INFORMATION</u>
	GENERAL	LINFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor alterations		NC
CURRENT USE		

## **ARCHITECTURAL DESCRIPTION**

in porch); windows on second story of front facade appear too small--may be replacement windows in downsized openings

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
Prairie/Craftsman	-
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Aluminum/vinyl	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof and rectangular massing; hipped roof front porch structure (enclosed)
ROOF TYPE	
Front Gable	ALTERATIONS
ROOF MATERIAL	Front porch enclosed (appears to have been enclosed partially at
Asphalt - shingle	an earlier date, then fully enclosed laternon-historic windows in porch); windows on second story of front facade appear too

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt207(4)



Photo Id: first2072



Photo Id: first207

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	
<u>ORIGINA</u>	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	-