## **Historic Libertyville**

Major alterations

Domestic - single dwelling

**CURRENT USE** 

**BEGINNING STREET NUMBER** 218 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** First Street PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? No **YEAR** Photo Id: FirstSt218(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-6 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1116423009 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Detached garage INTEGRITY NR SECOND

С

## **ARCHITECTURAL DESCRIPTION**

| ARCHITECTURAL CLASSIFICATION | FOUNDATION   |
|------------------------------|--|
| Gable Front                  | Parged   |
| DETAILS                      | PORCH  |
| -                            | -  |
| OTHER YEAR                   | WINDOW MATERIAL  |
| -                            | -  |
| DATE SOURCE                  | WINDOW MATERIAL 2  |
| Assessor                     | Aluminum/vinyl   |
| WALL MATERIAL (CURRENT)      | WINDOW TYPE  |
| Wood                         | Double hung & fixed  |
| WALL MATERIAL 2 (CURRENT)    | WINDOW CONFIGURATION   |
| Wood - shingles              | 1/1; 1-light   |
| PLAN                         | SIGNIFICANCE   |
| Rectangular                  | -  |
| NO OF STORIES                | HISTORIC FEATURES  |
| 1.5                          | Front gable roof and rectangular massing   |
| ROOF TYPE                    | ALTERATIONS  |
| Front Gable                  | Replacement siding; replacement windows in original openings; south dormer addition; front porch removed; wood entry stoop; replacement front door |
| ROOF MATERIAL                |  |
| Asphalt - shingle            |  |

## **ADDITIONAL PHOTOGRAPHS**





Photo Id: first218

## **HISTORIC INFORMATION**

| OLD ADDRESS (CITY DIR.YEAR   | BUILDER                             |
|--|-------------------------------------|
| -  | -                                   |
| BUILDING MOVED?  | SURVEYOR                            |
| -  | LR                                  |
| MOVED FROM   | SURVEYOR ORGANIZATION               |
| -  | Ramsey Historic Consultants         |
| ORIGINAL OWNER   | SURVEY DATE                         |
| -  | May-June 2016                       |
| ORIGINAL ARCHITECT   | SURVEY AREA                         |
| -  | Downtown Libertyville               |
| ARCHITECT SOURCE   |                                     |
| _  |                                     |
| PERMIT/HISTO   | RIC INFORMATION                     |
| OLD ADDRESS  | DATE OF CONSTRUCTION                |
| -  | -                                   |
| PERMIT MOVI  | NG INFORMATION                      |
| MOVING PERMIT #  | DATE MOVED                          |
| -  | -                                   |
| ORIGINAL PERI  | MIT INFORMATION                     |
| BUILDING PERMIT #  | OTHER PERMIT INFORMATION            |
| _  | #3790 (9/21/1965)2 car frame garage |
| DATE   | COA INFO                            |
| _  | _                                   |
| BUILDING PERMIT DESCRIPTION  | HISTORIC INFO                       |
|  | _                                   |
| COST   | OTHER SOURCES                       |
| _  | Sanborn Maps1924, 1933, 1948        |
| ORIGINAL OWNER OCCUPIED?   | HISTORIC INFO COMPILER              |
|  | LR                                  |
| EXTERIOR ALTERATION PERMITS  | VOLUNTEER                           |
|  | TOLONILLIK                          |
| #3007 (3/28/1962)aluminum siding; removling front porch; pour concrete stoop, iron railing; No permit # (3/3/1958)garage addition; 81-3 (1/25/1981)fire repair | -                                   |