## **Historic Libertyville**

**CURRENT USE** 

Domestic - single dwelling

**BEGINNING STREET NUMBER** 319 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** First Street PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? LOCAL LANDMARK? **YEAR** Photo Id: FirstSt319(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER N/A 1116415015 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Shed INTEGRITY NR SECOND NC minor alterations

## **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Ranch	Concrete
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1	Shallow side gable roof and rectangular massing of original house; center entry; center wood window at north window ba on front facade
ROOF TYPE	
Side Gable	ALTERATIONS
ROOF MATERIAL	
Acabalt chinala	Aluminum siding (1980); 1-story rear addition (1966);

are 1/1 replacement windows

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt319(2)



Photo Id: first319

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
_	
OLD ADDRESS	DATE OF CONSTRUCTION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVING INFORMATION  MOVING PERMIT # DATE MOVED	
FIGURE 1 ERFIZI #	DATE MOVES
	[-
<u>ORIGINAL PERM</u>	<u>IT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#4078 (12/29/1966))addition; 86-384 (8/20/1986)alteration to gable roof; 80-317 (10/8/1980)aluminum siding	-