## **Historic Libertyville**

Domestic - single dwelling

BEGINNING STREET NUMBER	135			
END STREET NUMBER	-			
STREET # SUFFIX	-	iii O		
STREET NAME	Newberry Avenue			
PIN				
LOCAL				
WITHIN LOCAL DISTRICT?	No			
LOCAL DIST CONTRIB/NON-CONTRIB?	С			
LOCAL LANDMARK?	No			
YEAR	-			
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: NewberryAve135(1)		
CRITERIA	-			
BUILDING DETAILS				
BUILDING NAME		ZONING		
-		R-7		
GROUND FLOOR USE		NUMBER OF STORIES		
Residential				
UPPER FLOOR USE		PROPERTY INDEX NUMBER		
-		1116404022		
CURRENT OCCUPANT				
-				
	<u>NATIO</u>	NAL REGISTER		
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?		
С		No		
WITHIN DISTRICT?		CRITERIA		
No		-		
NR LANDMARK?		ALTERNATE ADDRESS?		
No		-		
YEAR		_		
-				
	<u>GENERA</u>	<u>L INFORMATION</u>		
CATECORY		HISTORIC LICE		
CATEGORY		HISTORIC USE		
Building  CONDITION		Domestic - single dwelling SECONDARY STRUCTURE		
		SECONDARI SIRUCIURE		
Fair		ND SECOND		
INTEGRITY Medical and additions		NR SECOND		
Moderate alterations and additions				

## **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front Cottage	Parged
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Sanborn Map	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double hung & other
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1; 1-light
PLAN	SIGNIFICANCE
L	-
NO OF STORIES	HISTORIC FEATURES
1	Sanborn maps indicate that the front gable section of the house was built in the 19th century, and the west wing added before 1907.  ALTERATIONS
ROOF TYPE	
Multi-gable	
ROOF MATERIAL	Replacement siding (1998); replacement windows in original
Asphalt - shingle	openings; fixed shutters; replacement front door; replacement front stoop; rear porch addition (1960)

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: NewberryAve135(2)



Photo Id: Newberry135

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
105 Newberry Avenue (Sanborn maps before 1933)	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/HISTOR</u>	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
	C THEODINATION
PERMIT MOVIN	<u>G INFORMATION</u>
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	IIT INFORMATION
OKIGIIWE I EKI	
BUILDING PERMIT #	OTHER PERMIT INFORMATION
	_
DATE	COA INFO
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
BOLDING LENGTH BESCHIFTION	Sanborn Maps1897 (Sheet 2), 1907 (Sheet 2), 1912 (Sheet
COST	2), 1924 (Sheet 2), 1933 (Sheet 3), 1948 (Sheet 3)
	OTHER SOURCES
ORIGINAL OWNER OCCUPIED?	-
ONIGHNE OWNER OCCUPIED:	HISTORIC INFO COMPILER
EVTEDIOD ALTEDATION DEDMITS	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
98-565 (7/10/1998)aluminum siding; 2601 (4/7/1960)4 foot addition to existing rear porch	_
and the second s	