

Historic Libertyville

BEGINNING STREET NUMBER	121
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Park Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkAveW121(2)

BUILDING DETAILS

BUILDING NAME	ZONING
-	C-2
GROUND FLOOR USE	NUMBER OF STORIES
Commercial/Office	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Unknown	1121211001
CURRENT OCCUPANT	
State Farm Insurance	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	-
INTEGRITY	NR SECOND
Moderate alterations	-
CURRENT USE	
Commerce/Trade - office	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Cross Gable

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Cross

NO OF STORIES

2

ROOF TYPE

Cross Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Corner entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung, fixed & casement

WINDOW CONFIGURATION

1/1; multi-light; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Two story front gable bay with east and west two-story cross-bays; cutaway corners on front bay; square, east-side oriel bay with historic wood windows

ALTERATIONS

Replacement siding (2005); replacement windows in downsized openings (except in oriel bay); corner entry porch (historic alteration likely dating from the 1910s or 20s, enclosed later); fixed shutters; rear east-side addition; east deck addition; exterior staircase on west bay (2006)

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkAveW121(1)



Photo Id: WParkAve121



Photo Id: WParkAve121(2)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

85-236 (7/25/1985)--alterations; PB-05-0438 (5/24/2005)--siding; JCM-04-0035 (3/15/2006)--second-floor door, deck & stairs (rear)

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1924 (Sheet 9); 1933 (Sheet 5); 1948 (Sheet 5)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-