

Historic Libertyville

BEGINNING STREET NUMBER	207
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	E. Park Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkAveE207(4)

BUILDING DETAILS

BUILDING NAME	ZONING
-	C-2
GROUND FLOOR USE	NUMBER OF STORIES
Office	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Office	1121212008
CURRENT OCCUPANT	
Natural Health Chiropractic	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NC	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Moderate alterations	C
CURRENT USE	
Commerce/Trade	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front Cottage

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung & fixed

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable roof and rectangular massing; hipped-roof full-front porch structure (enclosed)

ALTERATIONS

Replacement siding (1994); replacement windows in original openings; front porch enclosed (two door openings, one picture window); fixed shutters

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkAveE207



Photo Id: EParkAve207(2)



Photo Id: EParkAve207

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

-

OTHER PERMIT INFORMATION

94-159 (4/13/1994)--install vinyl siding, soffit, fascia, and gutters; 6955 (9/11/1973)--remove existing O. H. Dor and install plate glass window

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1933, 1948

HISTORIC INFO COMPILER

LR

VOLUNTEER

-