

Historic Libertyville

BEGINNING STREET NUMBER	208
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Park Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Potentially Eligible
CRITERIA	A



Photo Id: ParkAveW208(1)

BUILDING DETAILS

BUILDING NAME	Waldo, A. W. House	ZONING	R-8
GROUND FLOOR USE	Residential	NUMBER OF STORIES	3
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1121100008
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Good	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Moderate alterations	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

-

OTHER YEAR

-

DATE SOURCE

LIBERTYVILLE ILLUSTRATED (p. 15)

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

Wood - shingles

PLAN

-

NO OF STORIES

2.5

ROOF TYPE

Combination

ROOF MATERIAL

Wood - shingle

FOUNDATION

Not visible

PORCH

Wrap around

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double hung & fixed

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

Despite alterations, this Queen Anne residence may be eligible for local landmark designation.

HISTORIC FEATURES

Hipped main roof with projecting front-gable through-the-cornice dormer on south facade (dormer features overhang supported by scrolled brackets); 2.5-story east side polygonal tower with pointed roof; wraparound front porch structure (not original, but historic--dates from between 1924 and 1933; partially enclosed)

ALTERATIONS

Replacement siding (1991); wood-shingle roofing; east end of wraparound porch enclosed (post-1948); replacement railings on porch; one-story rear addition; replacement windows in original openings

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkAveW208(2)



Photo Id: Park208W

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

90-399 (1/16/1991)--siding; 94-326 (6/1/1994)--roof; 94-579 (8/8/1994)--alterations; 99-369 (5/14/99)--alterations

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Photograph of house on p. 15 of LIBERTYVILLE ILLUSTRATED: Abner W. Waldo "was born in central Vermont in 1830, and removed to the great Northwest while yet a young man, settling in Wisconsin in 1855. After the war, during the latter portion of which he served his country in the First Wisconsin heaving Artillery, he disposed of his farm and removed to Chicago, where he was employed as a bookkeeper for some six years. He then, in 1871, engaged in the lumber business in quite an extensive way. In 1883 he purchased a large improved farm near Libertyville, which he sold in 1896. In that year he retired from business in Chicago and removed to Libertyville, where he erected a fine residence, surrounded by choice trees. Mr. Waldo is a public-spirited man, a splendid example of what New England has done for the Great West."

OTHER SOURCES

Sanborn Maps--1924 (Sheet 9); 1933 (Sheet 5); 1948 (Sheet 5)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-