Historic Libertyville

Domestic - single dwelling

BEGINNING STREET NUMBER	214	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW214
CRITERIA	-	
	BUIL	DING DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1121100006
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	NATIO	NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-	GENER#	AL INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		-
INTEGRITY		NR SECOND
Moderate alterations and additions		-
CUIDDENT LISE		

ARCHITECTURAL DESCRIPTION

enclosed, with replacement front steps and railing; replacement

siding (1994)

ARCHITECTURAL CLASSIFICATION	FOUNDATION
American Foursquare	Not visible
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Aluminum/vinyl	1/1; 6/1; 9/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Hipped roof with overhanging eaves; hipped-roof front and side dormers; three-sided west bay; hipped-roof front porch; cente three-sided bay above porch; original stucco cladding visible under porch
ROOF TYPE	
Hipped	
ROOF MATERIAL	ALTERATIONS
Asphalt - shingle	Large two-story rear addition (1953, 1982); front porch

ADDITIONAL PHOTOGRAPHS



Photo Id: Park214W

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVI	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ODICINAL DEDI	MIT INCODMATION
ORIGINAL PERI	MIT INFORMATION
PULL DANC DEPMIT #	OTHER REDMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
DATE	COA INFO
	COATHO
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
_	Sanborn Maps1933 (Sheet 5); 1948 (Sheet 5)
COST	OTHER SOURCES
_	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
_	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
82-3- (3/30/1982)one-story rear addition; 94-756	-
(10/9/1994)install siding, trim, and gutters; 720 (9/21/1953)4 bedroom and kitchen addition; 83-164 (6/17/1983)enclose stairway on exterior of building	[-