Historic Libertyville

Domestic - multiple dwelling

BEGINNING STREET NUMBER 301 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** W. Park Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** Photo Id: ParkAveW301 LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 NUMBER OF STORIES **GROUND FLOOR USE** Residential Apartments **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential Apartments 1121108017 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Major alterations **CURRENT USE**

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
-	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof; two-story east bay with cutaway corners
ROOF TYPE	ALTERATIONS
Front Gable	Replacement siding; replacement windows in downsized openings; fixed shutters; replacement front porch (post-1948); replacement door; one-story rear addition (may have originally been rear porch that was enclosed)
ROOF MATERIAL	
Asphalt - shingle	

ADDITIONAL PHOTOGRAPHS



Photo Id: WPark301

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
MOVING PERMIT #	DATE MOVED -
ORIGINAL PERM BUILDING PERMIT #	OTHER PERMIT INFORMATION
	-
DATE	COA INFO
	_
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	_
COST	OTHER SOURCES
-	_
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
98-1122 (12/22/1998)alterations to 2nd-floor dwelling; #99-382 (5/19/1999)alterations to eastern first floor apartment; 2239 (4/3/1950)residing walls and repair porch; No Permit # (10/25/1957)install outside stairway as rear exit from 2nd-floor apartment	-