Historic Libertyville

Domestic - multiple dwelling

BEGINNING STREET NUMBER 123 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** W. Maple Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? No **YEAR** LOCAL LANDMARK ELIGIBLE? No Photo Id: maple123 **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-8 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1116316003 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Major alterations and additions **CURRENT USE**

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Queen Anne	Not visible
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
irregular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Hipped main roof; large 2-story front gable bay
ROOF TYPE	story east bay with cutaway corners; west side window
-	ALTERATIONS
ROOF MATERIAL	Replacement siding; original wraparound porch
Asphalt - shingle	(post-1948); 1-story east side addition (may ha

at north end; 2gable dormer

removed ve originally been part of porch that was enclosed); replacement windows, most in original openings; 1st story front window in altered opening; replacement front door and surround, concrete stoop (1950s); concrete stoop and door at west elevation

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW123(2)



Photo Id: MapleAveW123(3)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT /UICI	
PERMIT/HIS	TORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	
PERMIT MOV	<u>/ING INFORMATION</u>
	
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINAL PE</u>	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#1907 (9/16/1957)enlarge first floor living quarters; create	-
two apartments on 2nd floor; #6945 (8/30/1972)close mallium	n
window on east wall of living room, move corner windows on	

with door height