Historic Libertyville

Domestic - single dwelling

BEGINNING STREET NUMBER	234	The Action of the Control of the Con		
END STREET NUMBER	-			
STREET # SUFFIX	-			
STREET NAME	W. Maple Avenue			
PIN				
LOCAL				
WITHIN LOCAL DISTRICT?	No			
LOCAL DIST CONTRIB/NON-CONTRIB?	С			
LOCAL LANDMARK?	No			
YEAR	-			
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: MapleAveW234(1)		
CRITERIA	-			
DUIL DING DETAIL C				
BUILDING DETAILS				
BUILDING NAME		ZONING		
-		R-7		
GROUND FLOOR USE		NUMBER OF STORIES		
Residential		2		
UPPER FLOOR USE		PROPERTY INDEX NUMBER		
Residential		1116311019		
CURRENT OCCUPANT				
-				
	NATIO	DNAL REGISTER		
	IVATIO	MAL REGISTER		
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?		
С		No		
WITHIN DISTRICT?		CRITERIA		
No		-		
NR LANDMARK?		ALTERNATE ADDRESS?		
No		-		
YEAR				
-				
	GENEDA	 LINEODMATION		
GENERAL INFORMATION				
CATEGORY		HISTORIC USE		
Building		Domestic - single dwelling		
CONDITION		SECONDARY STRUCTURE		
Good		[attached garage]		
INTEGRITY		NR SECOND		
Historic alterations and additions		-		
CUIDDENT LICE				

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION	
Side Gable	Brick	
DETAILS	PORCH	
-	-	
OTHER YEAR	WINDOW MATERIAL	
1925 (c)	Wood	
DATE SOURCE	WINDOW MATERIAL 2	
Assessor/Surveyor	-	
WALL MATERIAL (CURRENT)	WINDOW TYPE	
Stucco	Double hung & fixed	
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION	
-	3/1; 1-light	
PLAN	SIGNIFICANCE	
Irregular	-	
NO OF STORIES	HISTORIC FEATURES	
2.5	Side gable roof and rectangular massing	
ROOF TYPE	ALTERATIONS	
Multi-gable	2-story enclosed front porch addition (1920sfoundation is	
ROOF MATERIAL	different than side gable section) with 3/1 windows on front facade; stucco cladding (1920s); single-light wood replacemen	
Asphalt - shingle	windows throughout (not historically compatible type or configuration): 1-story rear addition and garage addition (2001)	

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW234(3)



Photo Id: Maple234

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVIN	G INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	IT INFORMATION
<u> </u>	<u> </u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn maps1933 (Sheet 4), 1948 (Sheet 4)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#2786 (11/21/1960)reshingle roof; JBA-01-0030 (3/27/2001)- -garage addition	-