Historic Libertyville

Domestic - single dwelling

| BEGINNING STREET NUMBER | 308 | |
|---------------------------------|-----------------|----------------------------|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | W. Maple Avenue | |
| PIN | | |
| LOCAL | | |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | С | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | No | Photo Id: MapleAveW308(1) |
| CRITERIA | - | |
| | BUILD | ING DETAILS |
| BUILDING NAME | | ZONING |
| - | | R-7 |
| GROUND FLOOR USE | | NUMBER OF STORIES |
| Residential | | 2 |
| UPPER FLOOR USE | | PROPERTY INDEX NUMBER |
| Residential | | 1116311017 |
| CURRENT OCCUPANT | | |
| - | | |
| | NATION | NAL REGISTER |
| | | |
| NR DISTRICT CONTRIB/NON-CONTRIB | | NR ELIGIBLE? |
| С | | No |
| WITHIN DISTRICT? | | CRITERIA |
| No | | - |
| NR LANDMARK? | | ALTERNATE ADDRESS? |
| No | | - |
| YEAR | | |
| - | | |
| | GENERAL | . INFORMATION |
| CATEGORY | | HISTORIC USE |
| Building | | Domestic - single dwelling |
| CONDITION | | SECONDARY STRUCTURE |
| Good | | Detached garage |
| INTEGRITY | | NR SECOND |
| Moderate alterations | | NC |
| | | |

ARCHITECTURAL DESCRIPTION

| ARCHITECTURAL CLASSIFICATION | FOUNDATION | |
|------------------------------|---|--|
| American Foursquare | Parged | |
| DETAILS | PORCH | |
| - | Full Front | |
| OTHER YEAR | WINDOW MATERIAL | |
| - | Aluminum/vinyl | |
| DATE SOURCE | WINDOW MATERIAL 2 | |
| Assessor | - | |
| WALL MATERIAL (CURRENT) | WINDOW TYPE | |
| Stucco | Double hung & casement | |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION | |
| Wood - shingles | - | |
| PLAN | SIGNIFICANCE | |
| Rectangular | - | |
| NO OF STORIES | HISTORIC FEATURES | |
| 2.5 | Hipped roof and rectangular massing; hipped ro | |
| ROOF TYPE | hipped-roof full front porch structure | |
| Hipped | ALTERATIONS | |
| ROOF MATERIAL | Stucco siding (post-1948); front porch enclosed | |

Asphalt - shingle

oof front gable;

ed with 1/1 windows, new door and sidelights; replacement windows in original openings; replacement front door; concrete front steps with wood railing

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW308(2)



Photo Id: Maple308

HISTORIC INFORMATION

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|-----------------------------|--|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| PERMIT/I | HISTORIC INFORMATION |
| | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| DERMIT | MOVING INFORMATION |
| <u>I EKPILI</u> | MOVING IN ORMATION |
| MOVING PERMIT # | DATE MOVED |
| _ | - |
| | |
| <u>ORIGINA</u> | <u>L PERMIT INFORMATION</u> |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | #JRAB-02-0021 (8/26/2002)garage |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | Sanborn Maps1933 (Sheet 4), 1948 (Sheet 4) |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| - | - |
| | |