

Historic Libertyville

BEGINNING STREET NUMBER	315
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Maple Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Potentially Eligible
CRITERIA	A



Photo Id: MapleAveW315(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-7
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116300135
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Minor alterations	NC
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Cross Form

DETAILS

Italianate/Queen Anne

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

-

PLAN

Irregular

NO OF STORIES

2

ROOF TYPE

Cross Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Wrap around

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

Even with alterations to east porch and replacement windows, this Cross Form residence with Queen Anne and Italianate detailing may be eligible for local landmark designation.

HISTORIC FEATURES

Cross gable roofline, with 2-story front gable bay intersected by east and west projecting gable bays; wraparound front porch (likely an historic alteration from early 20th century); 1-story east window bay with classical cornice

ALTERATIONS

Replacement windows in original openings; rear and southeast porches enclosed and connected (1982)

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW315(4)



Photo Id: maple315

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

JB-06-303 (2006)--remove and replace side porch; 82-60
(5/3/1982)--porch extension, hanging of bay window; #581
(4/22/1953)--repair work on rear of house foundation; #2273
(5/20/1950)--transfer door and window to another location and
repair roof under bay window

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1933 (Sheet 4), 1948 (Sheet 4)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-