

Historic Libertyville

BEGINNING STREET NUMBER	220
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN220(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-8
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116422007
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Moderate alterations	C
CURRENT USE	
Domestic - multiple dwelling	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Hipped

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Full Front

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Hipped roof; two-story front gable bay with cutaway corners and pent roof

ALTERATIONS

Replacement front porch (post-1948); replacement siding (1974); replacement windows in original openings (historic, not original); rear addition (1971)

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkPIN220(3)



Photo Id: ParkPlace220(2)



Photo Id: ParkPIN220



Photo Id: ParkPlace220



Photo Id: 220parkplace

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

7666 (3/4/1974)--aluminum siding; 6444 (7/22/1971)--enlarging kitchen 2nd floor apartment, adding small porch, adding outside stairway to 2nd floor apartment; 2695 (7/18/1960)--reshingle roof, change siding, insulate walls, repair front porch and stairs

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1912 (Sheet 3); 1924 (Sheet 6), 1933 (Sheet 5), 1948 (Sheet 5)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-