Historic Libertyville

Domestic - single dwelling

BEGINNING STREET NUMBER 328 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** Jackson Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? LOCAL LANDMARK? **YEAR** Photo Id: JacksonAve328(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER 1116313004 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Detached garage INTEGRITY NR SECOND NC Minor alterations **CURRENT USE**

ARCHITECTURAL DESCRIPTION

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|--|
| Bungalow | Concrete-block |
| DETAILS | PORCH |
| - | Full Front |
| OTHER YEAR | WINDOW MATERIAL |
| - | Aluminum/vinyl |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Surveyor | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Aluminum/vinyl | Double Hung |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | 1/1 |
| PLAN | SIGNIFICANCE |
| Rectangular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 1.5 | Side gable roof; inset front porch structure; shed-roof front dormer |
| ROOF TYPE | |
| Side Gable | ALTERATIONS |
| ROOF MATERIAL | Replacement siding; replacement windows in original openir |

Asphalt - shingle

Replacement siding; replacement windows in original openings; front bay with casement windows; replacement front door; replacement columns, railing, and base on front porch (1995); 2-story rear addition (1989)

ADDITIONAL PHOTOGRAPHS



Photo Id: JacksonAve328(3)



Photo Id: Jackson328(2)



Photo Id: Jackson328

HISTORIC INFORMATION

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|--|----------------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| PERMIT/HI | STORIC INFORMATION |
| | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| DERMIT M | OVING INFORMATION |
| I EKPILI PK | OVING INI OKHATION |
| MOVING PERMIT # | DATE MOVED |
| _ | - |
| | |
| <u>ORIGINAL I</u> | PERMIT INFORMATION |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | 89-602 (5/28/1992)two-car garage |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | Sanborn Maps, 1933, 1948 |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| 89-602 (9/26/1989)two-story addition and rear deck addit | |
| 95-755 (10/2/1995)alterations to existing front porch; 470 |)2 |