## **Historic Libertyville**

Domestic - single dwelling

BEGINNING STREET NUMBER	209	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Newberry Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	Placks Tdt Nambaum Aug 200(1)
LOCAL LANDMARK ELIGIBLE?	Yes	Photo Id: NewberryAve209(1)
CRITERIA	Α	
	BUILDIN	IG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116405038
CURRENT OCCUPANT		
-		
	<b>NATIONA</b>	L REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
c		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	NFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor alterations		С
CUDDENT LICE		

## **ARCHITECTURAL DESCRIPTION**

Replacement front steps; replacement window on east facade

toward rear

ARCHITECTURAL CLASSIFICATION	FOUNDATION	
Craftsman	Not visible	
DETAILS	PORCH	
-	Front entry	
OTHER YEAR	WINDOW MATERIAL	
-	Wood	
DATE SOURCE	WINDOW MATERIAL 2	
Assessor	-	
WALL MATERIAL (CURRENT)	WINDOW TYPE	
Wood - shingles	Double Hung	
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION	
-	6/1	
PLAN	SIGNIFICANCE	
Rectangular	Fine, well-preserved mid-1920s Craftsman residence, with through-the-cornice front dormer and gable-roof entry porch.	
NO OF STORIES		
2	HISTORIC FEATURES	
ROOF TYPE	Side gable roof with overhanging eaves; large through-the- cornice front dormer; gable entry porch with exposed rafter tails; historic wood windows; shingle cladding; historic front	
Side Gable		
ROOF MATERIAL	door	
Asnhalt - shingle	ALTERATIONS	

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: NewberryAve209(2)



Photo Id: Newberry209

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
OLD ADDRESS	DATE OF CONSTRUCTION
-	
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
OPIGINA	L PERMIT INFORMATION
ORIGINA	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
_	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	-