Historic Libertyville

BEGINNING STREET NUMBER	214	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: BroadwayAve214(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-7
GROUND FLOOR USE	NUMBER OF STORIES
Residence	1.5
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116419014
CURRENT OCCUPANT	L
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	
с	
WITHIN DI	STRICT?
No	
NR LANDM	ARK?
No	
YEAR	
-	

NR ELIGIBLE?

No CRITERIA

-

ALTERNATE ADDRESS?

GENERAL INFORMATION

HISTORIC USE

Domestic - single dwelling
SECONDARY STRUCTURE

Detached garage

NR SECOND

NC

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Bungalow

DETAILS

Craftsman

OTHER YEAR

-DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

3/1; 4/1

SIGNIFICANCE

-

HISTORIC FEATURES

Broad side gable roof with long, shed-roof front dormer; inset corner entry porch; 4/1 wood windows on first floor; three-sided window bay on east facade

ALTERATIONS

Replacement siding; replacement windows in dormer; entry porch enclosed

ADDITIONAL PHOTOGRAPHS



Photo Id: BroadwayAve214(2)



Photo Id: broadway214

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	-
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
OLD ADDRESS	DATE OF CONSTRUCTION -
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA BUILDING PERMIT #	AL PERMIT INFORMATION
	88-477 (7/27/1988)garage
DATE	COA INFO
- BUILDING PERMIT DESCRIPTION	- HISTORIC INFO
-	
COST	OTHER SOURCES

ORIGINAL OWNER OCCUPIED?

_

EXTERIOR ALTERATION PERMITS

1576 (8/27/1956)--replace two rear kitchen windows

-

HISTORIC INFO COMPILER

LR VOLUNTEER

-