## **Historic Libertyville**

Domestic - single dwelling

BEGINNING STREET NUMBER	313	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	E. Church Street	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	Photo Id: ChurchStE313(1)
LOCAL LANDMARK ELIGIBLE?	No	Prioto Id: Charchstes13(1)
CRITERIA	-	
	BUILDI	NG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residence		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116416002
CURRENT OCCUPANT		
-		
	NATIONA	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Major alterations and additions		NC
CUDDENT LICE		

## **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
L-Form	Not visible
DETAILS	PORCH
-	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
L	-
NO OF STORIES	HISTORIC FEATURES
1.5	L-shaped massing, with front-gable bay intersected by 1.5-story side gable bay; 1-story square window bay at east facade
ROOF TYPE	
Multi-gable	ALTERATIONS
ROOF MATERIAL	Replacement windows in original openings (2013); replacement
Asphalt - shingle	siding (1991); replacement front porch (historic1952); 2nd- story rear addition

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: ChurchStE313(4)



Photo Id: EEchurch313

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
_	
<u>PERMIT/HISTO</u>	ORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVI	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PER	MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	Sanborn Maps (1925; 1933; 1948)
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
JB-13-10147 (10/21/2013)replacement windows; 2173 (8/18/1958)remove front porch; 91-24 (1/22/1991)vinyl siding and aluminum trim	-