# **Historic Libertyville**

BEGINNING STREET NUMBER	435	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: ParkAveW435(1)

## **BUILDING DETAILS**

BUILDING NAME	ZONING
-	R-7
GROUND FLOOR USE	NUMBER OF STORIES
Residential Apartments	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential Apartments	1121108003
CURRENT OCCUPANT	
-	

## **NATIONAL REGISTER**

NR DISTRICT CONTRIB/NON-CONTRIB	
с	
WITHIN DI	STRICT?
No	
NR LANDM	ARK?
No	
YEAR	
-	

#### NR ELIGIBLE?

No CRITERIA

-

ALTERNATE ADDRESS?

## **GENERAL INFORMATION**

Building CONDITION Good INTEGRITY
Good
INTEGRITY
Minor alterations
CURRENT USE
Domestic - multiple dwelling

### HISTORIC USE

Domestic - single dwelling

SECONDARY STRUCTURE

[attached garage]

NR SECOND

-

## **ARCHITECTURAL DESCRIPTION**

#### ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

OTHER YEAR

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

Wood - shingles

PLAN

#### Irregular

NO OF STORIES

### 2

**ROOF TYPE** 

Front Gable

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Brick

PORCH

Wrap around

### WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung & fixed

WINDOW CONFIGURATION

1/1; 1-light; multi-light

SIGNIFICANCE

#### HISTORIC FEATURES

Nested front gables on front facade; wrap around porch with turned columns and spindlework; historic front door; multi-light window on west facade

### ALTERATIONS

Replacement siding; railings removed on porch; windows (1/1 double hung) are wood replacement windows, likely from the mid-20th century; octagonal window on front facade; two-story rear addition; one-story rear/west garage addition

# **ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW435(3)



Photo Id: Maple435



Photo Id: wpark435

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	AL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	
DATE	COA INFO
	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO

\_ COST -

\_

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

VOLUNTEER

### \_

\_