

Historic Libertyville

BEGINNING STREET NUMBER	302
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Maple Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: MapleAveW302(3)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-7
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116311018
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Historic additions/minor alterations	NC
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gabled Ell

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

-

PLAN

Irregular

NO OF STORIES

2

ROOF TYPE

Gable-on-Hip

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

6/1; 1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Hipped main roof, with large 2-story gable front bay and 2-story west side gable bay; smaller gable along roofline at east elevation

ALTERATIONS

Replacement front sun porch (historic--pre-1933); non-historic shed-roof entry porch at east end of front sun porch; northwest corner sun porch (historic--pre-1933); non-historic replacement windows in original openings on front and side elevations of house; one-story rear addition (historic--pre-1933)

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW302(2)



Photo Id: maple302

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

#1711 (2/5/1957)--3 windows out/1 window in 4/6;

OTHER PERMIT INFORMATION

JRM-05-0021 (7/8/2005)--garage

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1933 (Sheet 4), 1948 (Sheet 4)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-