Domestic - single dwelling

BEGINNING STREET NUMBER	147	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	<b>一种种的</b>
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW147(3)
CRITERIA	-	
	BUILD	ING DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1121109001
CURRENT OCCUPANT		
-		
	NATION	IAL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL	INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Barn
INTEGRITY		NR SECOND
Moderate alterations		С

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Italianate	Brick
DETAILS	PORCH
-	Corner entry
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor/owner	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double hung & fixed
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1; multi-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2	Hipped roof; wood cornice with paneled frieze and brackets wi
ROOF TYPE	drop pendants; square front oriel bay with classical surround
Hipped	and historic wood windows; 1/1 wood windows on all facades with classical surrounds
ROOF MATERIAL	ALTERATIONS
Asphalt - shingle	Replacement siding (1976); Two-story rear addition;

replacement front porch (later enclosed)



Photo Id: ParkAveW147(5)



Photo Id: ParkAveW147(2)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/H	IISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
MOVING PERMIT #	DATE MOVED
ORIGINAL BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	Sanborn Maps1924 (Sheet 9); 1933 (Sheet 5); 1948 (Sheet 5)
COST	According to current owner, the house was owned by William
-	Laycock, "reportedly the creator of the first Libertyville  Manufacturing Company that made Kriebel steam engines for
ORIGINAL OWNER OCCUPIED?	lake boats."
_	OTHER SOURCES
EXTERIOR ALTERATION PERMITS	
	HISTORIC INFO COMPILER
76-19 (8/12/1976)replacement siding	LR
	VOLUNTEER
	-

Domestic - multiple dwelling

BEGINNING STREET NUMBER	207	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW207(4)
CRITERIA	-	
	BUILI	DING DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential Apartments		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential Apartments		1121108068
CURRENT OCCUPANT		
Park Royale Apartments		
	<u>NATIO</u>	NAL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC		No
WITHIN DISTRICT?		CRITERIA
No NR LANDMARK?		ALTERNATE ADDRESS?
No No		ALIENTALE ADDRESS:
YEAR		
-		
	GENERA	<u>L INFORMATION</u>
CATEGORY		HISTORIC USE
Building		Domestic - multiple dwelling
CONDITION		SECONDARY STRUCTURE
Good		-
INTEGRITY		NR SECOND
Minor alterations		-
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	



Photo Id: ParkAveW207(3)



Photo Id: WPark207



Photo Id: wpark207

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	
<u>PERMIT</u>	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINA</u>	<u>L PERMIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	-
EXTERIOR ALTERATION PERMITS	VOLUNTEER
_	

Domestic - single dwelling

**BEGINNING STREET NUMBER** 208 **END STREET NUMBER** STREET # SUFFIX STREET NAME W. Park Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** Photo Id: ParkAveW208(1) LOCAL LANDMARK ELIGIBLE? Potentially Eligible **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** Waldo, A. W. House R-8 **GROUND FLOOR USE** NUMBER OF STORIES Residential PROPERTY INDEX NUMBER **UPPER FLOOR USE** Residential 1121100008 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good Detached garage INTEGRITY NR SECOND Moderate alterations **CURRENT USE** 

ARCHITECTURAL CLASSIFICATION	
Queen Anne	
DETAILS	
-	
OTHER YEAR	
-	
DATE SOURCE	
LIBERTYVILLE ILLUSTRATED (p. 15)	
WALL MATERIAL (CURRENT)	
Wood	
WALL MATERIAL 2 (CURRENT)	
Wood - shingles	
PLAN	
-	
NO OF STORIES	
2.5	
ROOF TYPE	
Combination	
ROOF MATERIAL	
Wood - shingle	

#### **FOUNDATION**

Not visible

#### PORCH

Wrap around

#### WINDOW MATERIAL

Wood

#### **WINDOW MATERIAL 2**

Aluminum/vinyl

#### WINDOW TYPE

Double hung & fixed

#### WINDOW CONFIGURATION

1/1; 1-light

#### SIGNIFICANCE

Despite alterations, this Queen Anne residence may be eligible for local landmark designation.

#### HISTORIC FEATURES

Hipped main roof with projecting front-gable through-the-cornice dormer on south facade (dormer features overhang supported by scrolled brackets); 2.5-story east side polygonal tower with pointed roof; wraparound front porch structure (not original, but historic--dates from between 1924 and 1933; partially enclosed)

#### ALTERATIONS

Replacement siding (1991); wood-shingle roofing; east end of wraparound porch enclosed (post-1948); replacement railings on porch; one-story rear addition; replacement windows in original openings



Photo Id: ParkAveW208(2)



Photo Id: Park208W

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
_	_
<u>PERMIT MOVIN</u>	<u>IG INFORMATION</u>
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	<u>IIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	Photograph of house on p. 15 of LIBERTYVILLE ILLUSTRATED: Abner W. Waldo "was born in central Vermont in 1830, and
COST	removed to the great Northwest while yet a young man, settling
-	in Wisconsin in 1855. After the war, during the latter portion of which he served his country in the First Wisconsin heaving
ORIGINAL OWNER OCCUPIED?	Artillery, he disposed of his farm and removed to Chicago, where
-	he was employed as a bookkeeper for some six years. He then, in 1871, engaged in the lumber business in quite an extensive
EXTERIOR ALTERATION PERMITS	way. In 1883 he purchased a large improved farm near
90-399 (1/16/1991)siding; 94-326 (6/1/1994)roof; 94-579 (8/8/1994)alterations; 99-369 (5/14/99)alterations	Libertyville, which he sold in 1896. In that year he retired from
(0/0/1551) dicerations/ 55 505 (5/11/55) directations	business in Chicago and removed to Libertyville, where he erected a fine residence, surrounded by choice trees. Mr. Waldo
	is a public-spirited man, a splendid example of what New
	England has done for the Great West."
	OTHER SOURCES
	Sanborn Maps1924 (Sheet 9); 1933 (Sheet 5); 1948 (Sheet 5)
	HISTORIC INFO COMPILER
	11-
	LR
	VOLUNTEER

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER	214	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW214
CRITERIA		
CRITERIA		
	<b>BUILDI</b>	NG DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1121100006
CURRENT OCCUPANT		
-		
	NATION	AL REGISTER
		<del></del>
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL	<u>INFORMATION</u>
	<u> </u>	
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		-
INTEGRITY		NR SECOND
Moderate alterations and additions		-

enclosed, with replacement front steps and railing; replacement

siding (1994)

ARCHITECTURAL CLASSIFICATION	FOUNDATION
American Foursquare	Not visible
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Aluminum/vinyl	1/1; 6/1; 9/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Hipped roof with overhanging eaves; hipped-roof front and side
ROOF TYPE	dormers; three-sided west bay; hipped-roof front porch; cented three-sided bay above porch; original stucco cladding visible under porch
Hipped	
ROOF MATERIAL	ALTERATIONS
Asphalt - shingle	Large two-story rear addition (1953, 1982); front porch



Photo Id: Park214W

OLD ADDRESS (CITY DIR.YEAR	BUILDER
BUILDING MOVED?	- SURVEYOR
BOILDING PIOVED!	LR
MOVED FROM	SURVEYOR ORGANIZATION
PIOVED FROM	
- OPTICINAL OWNER	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
	TORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
MOVING PERMIT #  -  ORIGINAL PE	DATE MOVED  - ERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	Sanborn Maps1933 (Sheet 5); 1948 (Sheet 5)
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
82-3- (3/30/1982)one-story rear addition; 94-756 (10/9/1994)install siding, trim, and gutters; 720 (9/21/1953)-4 bedroom and kitchen addition; 83-164 (6/17/1983)enclose stairway on exterior of building	)-

BEGINNING STREET NUMBER	219-221		
END STREET NUMBER	-		
STREET # SUFFIX	-		
STREET NAME	W. Park Avenue		
PIN			
<b>LOCAL</b>			
WITHIN LOCAL DISTRICT?	No		
LOCAL DIST CONTRIB/NON-CONTRIB?	С		
LOCAL LANDMARK?	No		
YEAR	-		
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW219-221(1)	
CRITERIA	-		
BUILDING NAME	BUILDING DETAILS  BUILDING NAME  ZONING		
-		R-8	
GROUND FLOOR USE		NUMBER OF STORIES	
Residential Apartments		2	
UPPER FLOOR USE		PROPERTY INDEX NUMBER	
Residential Apartments		1121108019	
CURRENT OCCUPANT			
-			
NATIONAL REGISTER			
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?	
С		No	
WITHIN DISTRICT?		CRITERIA	
No		-	
NR LANDMARK?		ALTERNATE ADDRESS?	
No YEAR		-	

## **GENERAL INFORMATION**

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage; shed
INTEGRITY	NR SECOND
Moderate alterations	NC; NC
CURRENT USE	
Domestic - multiple dwellings	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Concrete-block
DETAILS	PORCH
Tudor Revival	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Wood
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double hung, fixed & casement
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Aluminum/vinyl	1/1; 1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof; stucco with wood corner boards, string courses, and minimal decorative half-timbering; three-sided ea window bay; east and west gables; some historic wood window on side facades
ROOF TYPE	
Front Gable	
ROOF MATERIAL	ALTERATIONS
Asphalt - shingle	Front porch enclosed



Photo Id: ParkAveW219-221(2)



Photo Id: wpark219221

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT /UICTOR	NIC INFORMATION
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVIN	G INFORMATION
MOUTING DEDMIT #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	<u>IIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
_	-
DATE	COA INFO
_	_
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
_	_
COST	OTHER SOURCES
_	_
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#93-484 (12/23/1993)2nd-story apartment in the two-family	_
dwelling; 91-319 (8/16/1991)screened in porch	

**CURRENT USE** 

Domestic - multiple dwelling

**BEGINNING STREET NUMBER** 220-224 **END STREET NUMBER** STREET # SUFFIX STREET NAME W. Park Avenue **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** LOCAL LANDMARK ELIGIBLE? No Photo Id: WPark220-224 **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** R-8 **GROUND FLOOR USE** NUMBER OF STORIES Residential Apartments **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential Apartments **CURRENT OCCUPANT NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - multiple dwelling CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Minor alterations

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Contemporary	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	



Photo Id: ParkAveW220-226

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/</u>	<u>HISTORIC INFORMATION</u>
OLD ADDRESS	DATE OF CONSTRUCTION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT	MOVING INFORMATION
<u>- = : : : : : : : : : : : : : : : : : : </u>	THE TANK AND
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	AL PERMIT INFORMATION
BUILDING DEDMIT #	OTHER REPAIR INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
7943	
DATE	COA INFO
2/6/1975	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	-
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	-

Minor alterations

CURRENT USE

Domestic - multiple dwelling

BEGINNING STREET NUMBER	225	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW225(1)
CRITERIA	-	
	<u>BUIL</u>	DING DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential Apartments		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential Apartments		1121108018
CURRENT OCCUPANT		
	NATIO	DNAL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		
NR LANDMARK?		ALTERNATE ADDRESS?
No		
YEAR		
-		
	<b>GENER</b>	AL INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor alterations		С

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Concrete-block
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood - shingles	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof with cornice returns; hipped-roof front porch
ROOF TYPE	structure; gable through-the-cornice dormers on side facades; one-story, three-sided window bay on east facade
Front Gable	ALTERATIONS
ROOF MATERIAL	
Asphalt - shingle	Replacement windows in original openings; front porch enclosed with aluminum/vinyl windows (1970); fixed shutters; concrete



Photo Id: ParkAveW225(2)



Photo Id: ParkAveW225



Photo Id: Park225W

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/HISTO</u>	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOVIN	NG INFORMATION
FERMIT MOVI	NO INI OKHATION
MOVING PERMIT #	DATE MOVED
	SAIL MOVES
<u>ORIGINAL PERI</u>	<u>MIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
6383 (6/14/1971)enclosing present porch with windows and pouring new concrete stairs	-

CURRENT USE

Domestic - multiple dwelling

BEGINNING STREET NUMBER	301	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW301
CRITERIA	-	
	<u>BUIL</u>	DING DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential Apartments		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential Apartments		1121108017
CURRENT OCCUPANT		
-		
	<u>NATI</u>	ONAL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	<b>GENER</b>	AL INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		-
INTEGRITY		NR SECOND
Major alterations		-

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
-	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof; two-story east bay with cutaway corners
ROOF TYPE	ALTERATIONS
Front Gable	Replacement siding; replacement windows in downsized openings; fixed shutters; replacement front porch (post-1948) replacement door; one-story rear addition (may have originall been rear porch that was enclosed)
ROOF MATERIAL	
Asphalt - shingle	



Photo Id: WPark301

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVIN	IG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ODICINAL DEDA	ATT INCODMATION
ORIGINAL PERI	<u> IIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
_	_
DATE	COA INFO
_	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
_	_
COST	OTHER SOURCES
_	_
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
_	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
98-1122 (12/22/1998)alterations to 2nd-floor dwelling;	-
#99-382 (5/19/1999)alterations to eastern first floor	
apartment; 2239 (4/3/1950)residing walls and repair porch; No Permit # (10/25/1957)install outside stairway as rear exit	
from 2nd-floor apartment	

Domestic - multiple dwelling

CURRENT USE

BEGINNING STREET NUMBER	305	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveW305
CRITERIA	-	
	<u>BUILDII</u>	NG DETAILS
BUILDING NAME		ZONING
GROUND FLOOR USE		R-7 NUMBER OF STORIES
		2
Residential Apartments  UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential Apartments		1121108016
CURRENT OCCUPANT		1121100010
-		
	<u>NATION</u>	AL REGISTER
ND DISTRICT CONTRID (NON CONTRID		ND ELYCYDLES
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENEDALI	INFORMATION
	GLINERAL	INI ORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Major alterations and additions		NC

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front Cottage	Not visible
DETAILS	PORCH
-	Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof; hipped roof front porch with entry bay at east
ROOF TYPE	end
Front Gable	ALTERATIONS
ROOF MATERIAL	Replacement siding (1970); replacement windows in original openings; wrought iron railings on porch; large shed-roof side dormer additions (1970); rear deck addition
Asphalt - shingle	



Photo Id: Park305W

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Meyer, Herman	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOVIN	NG INFORMATION
FERMIT MOVI	IG INI OKHATION
MOVING PERMIT #	DATE MOVED
-	-
BUILDING PERMIT #	OTHER PERMIT INFORMATION
DATE	COA INFO
	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
_	From Illinois Digital Archives (information provided by
COST	Libertyville-Mundelein Historical Society and Cook Memorial
_	Public Library): " Note on back: "Residence of Herman Meyer, [305] Park Ave. Built by Henry Engleberry, Cont'r. Libertyville."
ORIGINAL OWNER OCCUPIED?	Photograph by Beswick Photo Studio, Libertyville, Ill. The
-	Beswick Photo Studio is listed in the Libertyville section of the Waukegan city directory between 1903 and 1913. According to
EXTERIOR ALTERATION PERMITS	the Lake County Assessor's office the house was built in 1920."
6047 (6/18/1970)dormer additions, siding; JRR-15-0058 (2012)interior and exterior remodelgut; 7733 (3/7/1975)additional bed rooms and bath	Historic photograph of building on Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library): http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6507/rec/2
	OTHER SOURCES
	-
	HISTORIC INFO COMPILER
	LR
	VOLUNTEER
	-
	T I

CONDITION

INTEGRITY

Major alterations

CURRENT USE

Domestic - multiple dwelling

BEGINNING STREET NUMBER	311	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Park Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	_	
		Photo Id: ParkAveW311(3)
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	
	BUILD	ING DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1121108015
CURRENT OCCUPANT		7
-		
	NATION	NAL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC		No
WITHIN DISTRICT?		CRITERIA
No		
NR LANDMARK?		ALTERNATE ADDRESS?
YEAR		] [-
-		7
		1
	<u>GENERAL</u>	<u>. INFORMATION</u>
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling

SECONDARY STRUCTURE

Coach house

NR SECOND

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Italianate	Brick
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
1930 (c)	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2	Hipped roof; two-story east bay
ROOF TYPE	ALTERATIONS
Hipped	Replacement siding (1990); replacement windows in original openings (not historic); front entry bay addition (open porch addition built c. 1930 and later enclosed); fixed shutters; two-story west addition that is flush with front facade (historic additionc. 1930)
ROOF MATERIAL	
Asphalt - shingle	



Photo Id: ParkAveW311(2)



Photo Id: ParkAveW311(4)



Photo Id: wpark311

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
_	
DEDMIT/HIST	NDIC INCODMATION
PERMIT/HISIC	DRIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVI	ING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PER	MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1933 (Sheet 9); 1948 (Sheet 9)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
No Permit # (5/18/1953)asbestos shingles on exterior of house; 90-674 (12/20/1990)residing duplex, aluminum fascia, soffit, gutter and downspout	-