Domestic - single dwelling

BEGINNING STREET NUMBER	204	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	First Street	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: FirstSt204(1)
CRITERIA	-	
	DUTIE	AINC DETAILS
	BUILD	DING DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116423012
CURRENT OCCUPANT		
-		
	NATIO	NAL REGISTER
	INATIO	MAE REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	CENEDAL	
	GENERAL	L INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor alterations		С
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2	Front gable roof; rectangular massing; 2-story south side bay
ROOF TYPE	with cutaway corners; hipped roof porch structure (partially enclosed); north side gable dormer; historic 1/1 wood windows
Front Gable	ALTERATIONS
ROOF MATERIAL	
Asphalt - shingle	Replacement siding; front porch partially enclosed; replacement front steps to porch



Photo Id: FirstSt204(3)



Photo Id: FirstStreet204

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
DEDMIT /	HISTORIC INFORMATION
PERMIT!	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA BUILDING PERMIT #	AL PERMIT INFORMATION OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
COST	Historic photograph of house on Illinois Digital Archives (from collection of the Libertyville Mundelein Historical Society and Cook Memorial Public Library) http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1
ORIGINAL OWNER OCCUPIED?	1/id/6506/rec/9
-	OTHER SOURCES
EXTERIOR ALTERATION PERMITS	Sanborn Maps, 1924, 1933, 1948
-	HISTORIC INFO COMPILER
	LR
	VOLUNTEER
	-

CURRENT OCCUPANT

BEGINNING STREET NUMBER	207	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	First Street	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: FirstSt207(1)
CRITERIA	-	
	<u>B</u> l	JILDING DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116422017

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?	
С	No	
WITHIN DISTRICT?	CRITERIA	
No	-	
NR LANDMARK?	ALTERNATE ADDRESS?	
No	-	
YEAR		

-	
G	ENERAL INFORMATION
CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Minor alterations	NC
CURRENT USE	
Domestic - single dwelling	

in porch); windows on second story of front facade appear too small--may be replacement windows in downsized openings

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
Prairie/Craftsman	-
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Aluminum/vinyl	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gable roof and rectangular massing; hipped roof front
ROOF TYPE	porch structure (enclosed)
Front Gable	ALTERATIONS
ROOF MATERIAL	Front porch enclosed (appears to have been enclosed partially at an earlier date, then fully enclosed laternon-historic windows

Asphalt - shingle



Photo Id: FirstSt207(4)



Photo Id: first2072



Photo Id: first207

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/HI</u>	STORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MA	OVING INFORMATION
PERMIT MY	OVING INFORMATION
MOVING PERMIT #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL	PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
_	
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
DOTEDING FERRIT DESCRIPTION	TILOTORIZO INI O
COST	OTHER SOURCES
COST	
ODICINAL OWNED OCCUPIEDS	Sanborn maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER

BEGINNING STREET NUMBER	208
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt208(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116423011
CURRENT OCCUPANT	
-	
<u>NAT</u>	TIONAL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB C WITHIN DISTRICT?	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB C WITHIN DISTRICT?	NR ELIGIBLE? No CRITERIA
NR DISTRICT CONTRIB/NON-CONTRIB C WITHIN DISTRICT? No NR LANDMARK?	NR ELIGIBLE? No CRITERIA

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Moderate alterations and additions	С
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Brick
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
1960s	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Assessor/Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	6/1; 1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2	Front gable roof; rectangular massing; hipped-roof full-front
ROOF TYPE	porch structure
Front Gable	ALTERATIONS
ROOF MATERIAL	Replacement siding; replacement windows in original openings; front porch enclosed (1969); front steps replaced; rear deck
Asphalt - shingle	addition





Photo Id: FirstStreet208

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/H</u>	<u>ISTORIC INFORMATION</u>
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT N	MOVING INFORMATION
PERMIT	HOVING INFORMATION
MOVING PERMIT #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	
<u>ORIGINAL</u>	<u>PERMIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#5020 (11/6/1969)replace front porch	
" 3020 (11/0/1303) Teplace Holle policii	-

BEGINNING STREET NUMBER	213
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt213(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116422016
CURRENT OCCUPANT	
<u>NAT</u>	TIONAL REGISTER
<u>NAT</u>	TIONAL REGISTER NR ELIGIBLE?
<u>NAT</u>	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? No	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? No	NR ELIGIBLE? No CRITERIA -
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? NO NR LANDMARK?	NR ELIGIBLE? No CRITERIA - ALTERNATE ADDRESS?

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Excellent	Detached garage
INTEGRITY	NR SECOND
Major alterations and additions	NC
CURRENT USE	
Domestic - single dwelling	

multiple dormer additions on north and south side of roof (1962,

later); large 2-story rear addition; replacement siding;

replacement windows in original openings

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional - Queen Anne (altered)	Not visible
DETAILS	PORCH
-	Wrap around
OTHER YEAR	WINDOW MATERIAL
2012	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor/Permit	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Hardie board	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	6/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	[According to Sanborn maps from 1924-1948, house was a 1.5-
ROOF TYPE	story dwelling with a full-width, open front porch]
Front Gable	ALTERATIONS
ROOF MATERIAL	Original house obscured by multiple alterations and additions, most of which date from 2012wraparound front porch;
	inost of which date from 2012wraparound front porch;

Asphalt - shingle





Photo Id: first213



Photo Id: first213

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTO	DRIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVI	ING INFORMATION
	
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINAL PER</u>	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	#2559 (9/21/1964)2 car garage;
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#3027 (4/28/1962)two dormers; #3451 (1964)frame	-
dormers in rear of house; #7950 (9/9/1974)rebuild and expand back porch; JRA-01-0019 (2000)2 story addition, porch, interior remodel (\$150,000)	

BEGINNING STREET NUMBER	214
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt214(2)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116423010
CURRENT OCCUPANT	
-	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
С	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

-	
GEN	ERAL INFORMATION
CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Moderate alterations and additions	NC
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Brick
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
1991; 2004	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor/Permit	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood - shingles	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2	Front gable roof; rectangular massing; hipped-roof full-front
ROOF TYPE	porch structure (enclosed)
Front Gable	ALTERATIONS
ROOF MATERIAL	Front porch enclosed (2004); 2-story rear addition and deck
Asphalt - shingle	(1991-2); replacement siding; replacement windows in origina openings



Photo Id: FirstSt214(4)



Photo Id: First214

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDIATE /UIGT	
PERMIT/HISTO	ORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOV	ING INFORMATION
	
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PER	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
<u>-</u>	#94-572 (1994)three-car garage
DATE	COA INFO
<u>-</u>	
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
JRM-04-0029 (2004)front porch and skylights;#91-422 (1991)addition and deck; 1734 (1957)shingle house and	_

21/
-
-
First Street
No
NC
No
-
No
-



Photo Id: FirstSt217(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116422015
CURRENT OCCUPANT	
-	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NC	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Major alterations and additions	NC
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Dutch Colonial Revival	Parged
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
L	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gambrel roof; large gabled through-the-corn
ROOF TYPE	north facade
Front Gambrel	ALTERATIONS
ROOF MATERIAL	Replacement siding; replacement front porch (not
	story rear/south addition (2003); stone veneer about

Asphalt - shingle

Parged	
--------	--

nice dormer on

Replacement siding; replacement front porch (not historic); 2-story rear/south addition (2003); stone veneer above entry (1950s); replacement front door; replacement windows in original openings



Photo Id: FirstSt217(3)



Photo Id: FirstSt217(4)



Photo Id: first217



Photo Id: first217

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
	1IT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
- DATE	- COA TNEO
DATE	COA INFO
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	North facade of the house visible in historic photograph of 227
COST	First Street on Illinois Digital Archive
-	http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6537/rec/8
ORIGINAL OWNER OCCUPIED?	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
EXTERIOR ALTERATION PERMITS	HISTORIC INFO COMPILER
JLA-01-0047 (2003)addition and interior remodeling; #626	LR
(6/9/1953)alteration and installing roof over present porch deck; No permit # (7/7/1954)replacing front bay window with	VOLUNTEER
thermapane window; No permit # (5/6/1959)exterior stone veneer front and planter, iron post; #2323 (7.18.1950)roof over deck	-

BEGINNING STREET NUMBER	218
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt218(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116423009
CURRENT OCCUPANT	
-	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NC	No No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Major alterations	С
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double hung & fixed
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood - shingles	1/1; 1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof and rectangular massing
ROOF TYPE	ALTERATIONS
Front Gable	Replacement siding; replacement windows in original openings;
ROOF MATERIAL	south dormer addition; front porch removed; wood entry stoop; replacement front door
Asphalt - shingle	Teplacement from adoi





Photo Id: first218

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDIATE (UTCT	
PERMIT/HIST	ORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	
PERMIT MOV	ING INFORMATION
-	
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PER	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	#3790 (9/21/1965)2 car frame garage
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#3007 (3/28/1962)aluminum siding; removling front porch;	-
pour concrete stoop, iron railing; No permit # (3/3/1958)	

BEGINNING STREET NUMBER	221
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt221(3)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116422014
CURRENT OCCUPANT	
- <u>NAT</u>	IONAL REGISTER
<u>NAT</u>	IONAL REGISTER NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
NAT	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT?	NR ELIGIBLE?
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? No	NR ELIGIBLE? No CRITERIA -

GENERAL INFORMATION

CATEGORY	HISTORIC USE	
Building	Domestic - single dwelling	
CONDITION	SECONDARY STRUCTURE	,
Excellent	Detached garage	
INTEGRITY	NR SECOND	
Minor alterations	NC	
CURRENT USE		
Domestic - single dwelling		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional - Queen Anne	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	



Photo Id: FirstSt221(4)



Photo Id: First221

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	Allstyle Builders
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Vance, Michael J.	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
Holsman, J. Peter	Downtown Libertyville
ARCHITECT SOURCE	
Permit	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	AL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
96-487	-
DATE	COA INFO
7/5/1996	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
Single Family Dwelling	-
COST	OTHER SOURCES
\$216,000.00	-
t	
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER LR
ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS	

BEGINNING STREET NUMBER	224
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt224(2)

BUILDING DETAILS

BUILDING NAME	ZONING	
-	R-6	
GROUND FLOOR USE	NUMBER OF STORIES	
Residential	2	
UPPER FLOOR USE	PROPERTY INDEX NUMBER	
Residential	1116423008	
CURRENT OCCUPANT		
_		
<u>NAT</u>	TIONAL REGISTER	
NR DISTRICT CONTRIB/NON-CONTRIB	TIONAL REGISTER NR ELIGIBLE?	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?	
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT?	NR ELIGIBLE?	
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT?	NR ELIGIBLE? No CRITERIA	
NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? NO NR LANDMARK?	NR ELIGIBLE? No CRITERIA - ALTERNATE ADDRESS?	

GENERAL INFORMATION

CATEGORY	HISTORIC USE	
Building	Domestic - single dwelling	
CONDITION	SECONDARY STRUCTURE	
Good	Detached garage	
INTEGRITY	NR SECOND	
Major alterations and additions	NC	
CURRENT USE		
Domestic - single dwelling		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Vernacular (altered)	Concrete
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
2005	-
DATE SOURCE	WINDOW MATERIAL 2
Permits	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	6/1
PLAN	SIGNIFICANCE
Т	-
NO OF STORIES	HISTORIC FEATURES
2.5	-
ROOF TYPE	ALTERATIONS
Combination	Original one-story frame residence (1956) obscured by
ROOF MATERIAL	extensive alterations and additions2nd story addition; front porch; replacement siding; replacement windows on first story
Asphalt - shingle	of original house: replacement front door



Photo Id: FirstSt224(4)



Photo Id: First224

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	Roewert, Roy
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Stocke, Fred	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOVIA	IC INFORMATION
PERMIT MOVIE	IG INFORMATION
MOVING PERMIT #	DATE MOVED
PIOVING PERMIT #	DATE MOVED
-	[-
ORIGINAL PERM	<u> IIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
1499	JRB-03-0199 (2003)detached garage
DATE	COA INFO
7/6/1956	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
1 story frame single family residence	-
COST	OTHER SOURCES
\$17,000.00	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
JD-02-0012 (2002)deck; JRA-05-0020 (2005)second floor addition	-

BEGINNING STREET NUMBER 227 **END STREET NUMBER** STREET # SUFFIX STREET NAME First Street PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? YEAR LOCAL LANDMARK ELIGIBLE? No **CRITERIA**



Photo Id: FirstSt227(1)

BUILDING DETAILS

BUILDING NAME	ZONING	
-	R-6	
GROUND FLOOR USE	NUMBER OF STORIES	
Residential	2	
UPPER FLOOR USE	PROPERTY INDEX NUMBER	
Residential	1116422013	
CURRENT OCCUPANT		
NAT	IONAL REGISTER	
	TIONAL REGISTER NR ELIGIBLE?	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?	
NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?	
NR DISTRICT CONTRIB/NON-CONTRIB C WITHIN DISTRICT? No	NR ELIGIBLE? No CRITERIA	
NR DISTRICT CONTRIB/NON-CONTRIB C WITHIN DISTRICT? No	NR ELIGIBLE? No CRITERIA	
NR DISTRICT CONTRIB/NON-CONTRIB C WITHIN DISTRICT? No NR LANDMARK?	NR ELIGIBLE? No CRITERIA - ALTERNATE ADDRESS?	

GENERAL INFORMATION

CATEGORY	HISTORIC USE	
Building	Domestic - single dwelling	
CONDITION	SECONDARY STRUCTURE	
Good	Detached garage	
INTEGRITY	NR SECOND	
Moderate alterations and additions	NC	
CURRENT USE		
Domestic - single dwelling		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Dutch Colonial Revival	Stone (clad)
DETAILS	PORCH
-	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Hardie board	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	8/8; 12/12
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Front gambrel roof; inset northeast corner porch; slightly
ROOF TYPE	recessed, three-sided window bay at south end of front facade;
Front Gambrel	2-story gable bay on south facade ALTERATIONS
ROOF MATERIAL	
Asphalt - shingle	Replacement siding; replacement windows in original openings (configuration is not historically appropriate); two-story rear

addition (2007); round window under front gambrel



Photo Id: FirstSt227(5)



Photo Id: First227

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Davis, James T.	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
OLD ADDRESS	DATE OF CONSTRUCTION
MOVING PERMIT #	DATE MOVED
-	-
ORIG	INAL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	4030 (10-18-1966)garage
DATE	COA INFO
	COA INI O

BUILDING PERMIT DESCRIPTION

-COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

#3253 (4/23/1963)--addition; JRA-07-0038 (10/3/2007)--addition and interior remodel

HISTORIC INFO

From Illinois Digital Archives (information provided by Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--"Note included with photograph: "M/M Detters were visitors to Cook Hse on one of the pre-Christmas weekends when we had our "Victorian Christmas" celebration. They live @ 207 N. 1st St in a house which was built probably @ the turn of the century. Mrs. Deters asked if by chance the society could help her in finding who built the house & further were there any pictures. We found a picture. Jim Davis who operated an express or delivery service with a one horse wagon was the 1st owner. JMM 2/5/79" Lake County Recorder of Deeds Document 1873555 states that Lot 10 Block 5 in C. Frank Wright's Addition was purchased by Gary and Susan Deters in 1977. This lot is 227 1st Street, not 207 1st Street. Carrie Davis, wife of James T. Davis, bought Lot 10 Block 5 in C. Frank Wright's Addition in 1905 (Recorder of Deeds Book 145n page 626). The Lake County Assessor's office reports that the house was built in 1905. Photograph by Beswick Photo Studio, Libertyville, Ill. The Beswick Photo Studio is listed in the Libertyville section of the Waukegan city directory between 1903 and 1913."

OTHER SOURCES

Historic photo of house on Illinois Digital Archive (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--

http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6537/rec/8

HISTORIC INFO COMPILER

VOLUNTEER	
-	