CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER 228 **END STREET NUMBER** STREET # SUFFIX STREET NAME First Street PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** Photo Id: FirstSt228(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-6 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1116423007 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Detached garage INTEGRITY NR SECOND NC Major alterations and additions

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|---|
| Gable Front | Concrete |
| DETAILS | PORCH |
| - | Full Front |
| OTHER YEAR | WINDOW MATERIAL |
| - | Wood |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Assessor | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Aluminum/vinyl | Double hung & fixed |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | 1/1; 1-light |
| PLAN | SIGNIFICANCE |
| Rectangular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 2 | Front gable roof; rectangular massing |
| ROOF TYPE | ALTERATIONS |
| Front Gable | Non-historic alterations include replacement siding; replacement |
| ROOF MATERIAL | windows in original openings; front porch enclosed; wood steps to front porch entrance; 2-story rear addition; rear deck additio |
| Asphalt - shingle | Lo none poten endance, 2 story real addition, real deck addition |



Photo Id: FirstSt228(4)



Photo Id: first228

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|-----------------------------|------------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| PERMIT/ | HISTORIC INFORMATION |
| | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| PFRMIT | MOVING INFORMATION |
| IENTEL | HOVING IN GRAPHON |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| | |
| <u>ORIGINA</u> | <u>L PERMIT INFORMATION</u> |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | 94-713 (10/7/1994)garage |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | Sanborn Maps1924, 1933, 1948 |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| - | - |
| | |

| BEGINNING STREET NUMBER | 315 | |
|---------------------------------|--------------|--|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | First Street | |
| PIN | | |
| <u>LOCAL</u> | | |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | NC | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | No | |
| CRITERIA | - | |
| | DI | |



Photo Id: FirstSt315(1)

BUILDING DETAILS

| BUILDING NAME | ZONING |
|--|-------------------------------|
| - | R-7 |
| GROUND FLOOR USE | NUMBER OF STORIES |
| Residential | 2 |
| UPPER FLOOR USE | PROPERTY INDEX NUMBER |
| Residential | 1116415016 |
| CURRENT OCCUPANT | |
| | |
| - NAT | TONAL DEGISTED |
| <u>-</u> <u>NAT</u> | IONAL REGISTER |
| | TIONAL REGISTER NR ELIGIBLE? |
| | |
| NR DISTRICT CONTRIB/NON-CONTRIB NC | NR ELIGIBLE? |
| NR DISTRICT CONTRIB/NON-CONTRIB NC | NR ELIGIBLE? |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? No | NR ELIGIBLE? |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? | NR ELIGIBLE? No CRITERIA |

GENERAL INFORMATION

| HISTORIC USE |
|----------------------------|
| Domestic - single dwelling |
| SECONDARY STRUCTURE |
| Detached garage |
| NR SECOND |
| NC |
| |
| |
| |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|----------------------|
| New Traditional | - |
| DETAILS | PORCH |
| - | - |
| OTHER YEAR | WINDOW MATERIAL |
| - | - |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Permit | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| - | - |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | - |
| PLAN | SIGNIFICANCE |
| - | - |
| NO OF STORIES | HISTORIC FEATURES |
| - | - |
| ROOF TYPE | ALTERATIONS |
| - | - |
| ROOF MATERIAL | |
| | |



Photo Id: FirstSt315(2)



Photo Id: first315



Photo Id: first315(2)

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|-----------------------------|-----------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| Nawrock, Douglas | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| DEDMIT // | UICTORIC INFORMATION |
| PERMII/ | HISTORIC INFORMATION |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| _ | - |
| | |
| <u>PERMIT</u> | MOVING INFORMATION |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| ORIGINA | L PERMIT INFORMATION |
| - | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| JRB-06-0011 | - |
| DATE | COA INFO |
| 4/7/2006 | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| New single family residence | - |
| COST | OTHER SOURCES |
| \$425,830.00 | - |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| - | - |
| <u> </u> | |

| BEGINNING STREET NUMBER | 316 |
|---------------------------------|--------------|
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | First Street |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | С |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | No |
| CRITERIA | - |
| | |



Photo Id: FirstSt316(1)

BUILDING DETAILS

| ZONING | |
|---|---|
| R-7 | |
| NUMBER OF STORIES | |
| 2 | |
| PROPERTY INDEX NUMBER | |
| 1116419002 | |
| | |
| | |
| | |
| TONAL DECICTED | |
| IONAL REGISTER | |
| TIONAL REGISTER | |
| TIONAL REGISTER NR ELIGIBLE? | |
| | |
| NR ELIGIBLE? | |
| NR ELIGIBLE? | |
| NR ELIGIBLE? | |
| NR ELIGIBLE? No CRITERIA | |
| NR ELIGIBLE? No CRITERIA - ALTERNATE ADDRESS? | |
| | R-7 NUMBER OF STORIES 2 PROPERTY INDEX NUMBER |

| GENERAL INFORMATION | | |
|----------------------------|----------------------------|--|
| CATEGORY | HISTORIC USE | |
| Building | Domestic - single dwelling | |
| CONDITION | SECONDARY STRUCTURE | |
| Good | Detached garage | |
| INTEGRITY | NR SECOND | |
| Minor alterations | С | |
| CURRENT USE | | |
| Domestic - single dwelling | | |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|---|
| Gable Front Cottage | Parged |
| DETAILS | PORCH |
| - | Full Front |
| OTHER YEAR | WINDOW MATERIAL |
| - | Wood |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Assessor | Aluminum/vinyl |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Aluminum/vinyl | Double hung & casement |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | 6/1; 1-light |
| PLAN | SIGNIFICANCE |
| Rectangular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 1.5 | Front gable roof; rectangular massing; hipped-roof porch |
| ROOF TYPE | (enclosed) |
| Front Gable | ALTERATIONS |
| ROOF MATERIAL | Front porch enclosed (post-1948); replacement windows in |
| Asphalt - shingle | original openings (casement and fixed); replacement siding (1978) |



Photo Id: FirstSt316(2)

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|--|------------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| PERMIT/HISTOR | RIC INFORMATION |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| | IG INFORMATION |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| ORIGINAL PERM | IIT INFORMATION |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | - |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | Sanborn Maps1924, 1933, 1948 |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| 7393 (11/26/1973)aluminum siding; 6082 (7/30/1970)install vinyl siding | - |

N/A

CURRENT OCCUPANT

| BEGINNING STREET NUMBER | 319 | |
|---------------------------------|--------------|--|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | First Street | Marie Commission of the Commis |
| PIN | | |
| LOCAL | | |
| WITHIN LOCAL DISTRICT? | No | SINGLA MENTAL AND A SECOND STATE OF THE SECOND |
| LOCAL DIST CONTRIB/NON-CONTRIB? | С | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | No | Photo Id: FirstSt319(1) |
| CRITERIA | - | |
| | BU | JILDING DETAILS |
| BUILDING NAME | | ZONING |
| - | | R-7 |
| GROUND FLOOR USE | | NUMBER OF STORIES |
| Residential | | 1 |
| UPPER FLOOR USE | | PROPERTY INDEX NUMBER |

NATIONAL REGISTER

1116415015

| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
|---------------------------------|--------------------|
| С | No |
| WITHIN DISTRICT? | CRITERIA |
| No | - |
| NR LANDMARK? | ALTERNATE ADDRESS? |
| No | - |
| YEAR | |
| - | |

GENERAL INFORMATION

| <u> </u> | ENERAL INI ORPATION |
|----------------------------|----------------------------|
| CATEGORY | HISTORIC USE |
| Building | Domestic - single dwelling |
| CONDITION | SECONDARY STRUCTURE |
| Good | Shed |
| INTEGRITY | NR SECOND |
| minor alterations | NC |
| CURRENT USE | |
| Domestic - single dwelling | |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|---|
| Ranch | Concrete |
| DETAILS | PORCH |
| - | - |
| OTHER YEAR | WINDOW MATERIAL |
| - | Wood |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Assessor | Aluminum/vinyl |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Aluminum/vinyl | Double Hung |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | 1/1 |
| PLAN | SIGNIFICANCE |
| Rectangular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 1 | Shallow side gable roof and rectangular massing of original |
| ROOF TYPE | house; center entry; center wood window at north window bay |
| Side Gable | ALTERATIONS |
| ROOF MATERIAL | |
| Acabalt chinala | Aluminum siding (1980); 1-story rear addition (1966); |

are 1/1 replacement windows



Photo Id: FirstSt319(2)



Photo Id: first319

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|--|-----------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| _ | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| PERMIT MOVIN MOVING PERMIT # | G INFORMATION DATE MOVED |
| | _ |
| | - |
| <u>ORIGINAL PERM</u> | IT INFORMATION |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | - |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | - |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| #4078 (12/29/1966))addition; 86-384 (8/20/1986)alteration to gable roof; 80-317 (10/8/1980)aluminum siding | - |

| BEGINNING STREET NUMBER | 321 | |
|---------------------------------|--------------|-------------------------|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | First Street | |
| PIN | | |
| LOCAL | | |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | С | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | Yes | Photo Id: FirstSt321(1) |
| CRITERIA | А | |
| | <u>B</u> (| JILDING DETAILS |
| BUILDING NAME | | ZONING |
| - | | R-7 |
| GROUND FLOOR USE | | NUMBER OF STORIES |
| Residential | | 2 |
| UPPER FLOOR USE | | PROPERTY INDEX NUMBER |
| Residential | | 1116415014 |
| CURRENT OCCUPANT | | |
| - | | |
| | NA | TIONAL REGISTER |
| NR DISTRICT CONTRIB/NON-CONTRIB | | NR ELIGIBLE? |
| | | |

| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
|---------------------------------|--------------------|
| С | No |
| WITHIN DISTRICT? | CRITERIA |
| No | - |
| NR LANDMARK? | ALTERNATE ADDRESS? |
| No | - |
| YEAR | |
| - | |

GENERAL INFORMATION

| CATEGORY | HISTORIC USE |
|----------------------------|----------------------------|
| Building | Domestic - single dwelling |
| CONDITION | SECONDARY STRUCTURE |
| Good | Detached garage |
| INTEGRITY | NR SECOND |
| Minor alterations | С |
| CURRENT USE | |
| Domestic - single dwelling | |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|---|
| Gable Front | Concrete-block |
| DETAILS | PORCH |
| Craftsman | Full Front |
| OTHER YEAR | WINDOW MATERIAL |
| - | Wood |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Sanborn map (1924) | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Wood - shingles | Double Hung |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | 1/1; 3/1 |
| PLAN | SIGNIFICANCE |
| Rectangular NO OF STORIES | Well-preserved example of the Gable F Craftsman-style detailing. |
| 2 | HISTORIC FEATURES |
| ROOF TYPE Front Gable | Front gable roof and rectangular massi south end of porch structure is original historic 3/1 wood windows |
| ROOF MATERIAL | ALTERATIONS |
| Asphalt - shingle | Sanborn maps show north end of porcl |

Front vernacular type, with

ssing; wood shingle siding; al (Sanborn map, 1924);

ch was built as an open porch some time between 1924 and 1933--enclosed later with 1/1 windows; aluminum soffits



Photo Id: FirstSt321(3)



Photo Id: First321

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|--|---------------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| <u>PERMIT/HI</u> | ISTORIC INFORMATION |
| | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | |
| PERMIT M | OVING INFORMATION |
| <u>- = </u> | |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| | |
| <u>ORIGINAL</u> | PERMIT INFORMATION |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | Sanborn Maps (1924, 1933, 1948) |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| #80-187 (5/18/1980)replace deck and fence; 3287 | |
| (6/19/1963)repair porch; JB-06-0066 (5/2006)remove | and |

| BEGINNING STREET NUMBER | 325 |
|---------------------------------|--------------|
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | First Street |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | NC |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | No |
| CRITERIA | - |
| | |



Photo Id: FirstSt325

BUILDING DETAILS

| R-7 |
|----------------------------|
| |
| NUMBER OF STORIES |
| 2 |
| PROPERTY INDEX NUMBER |
| 1116415013 |
| 1 |
| |
| AL REGISTER |
| NR ELIGIBLE? |
| |
| NR ELIGIBLE? |
| NR ELIGIBLE? |
| NR ELIGIBLE? |
| NR ELIGIBLE? No CRITERIA |
| |

GENERAL INFORMATION

| CATEGORY | HISTORIC USE | |
|----------------------------|----------------------------|--|
| Building | Domestic - single dwelling | |
| CONDITION | SECONDARY STRUCTURE | |
| Excellent | [attached garage] | |
| INTEGRITY | NR SECOND | |
| Not altered | - | |
| CURRENT USE | | |
| Domestic - single dwelling | | |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|----------------------|
| New Traditional - Tudor | - |
| DETAILS | PORCH |
| - | - |
| OTHER YEAR | WINDOW MATERIAL |
| - | - |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Permit | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| - | - |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | - |
| PLAN | SIGNIFICANCE |
| - | - |
| NO OF STORIES | HISTORIC FEATURES |
| - | - |
| ROOF TYPE | ALTERATIONS |
| - | - |
| ROOF MATERIAL | |
| | |



Photo Id: first3252



Photo Id: first325

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|-----------------------------|-----------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| <u>PERMIT/</u> | HISTORIC INFORMATION |
| | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| PERMIT | MOVING INFORMATION |
| EKNILI | THOUTHOUTH OKNIATION |
| MOVING PERMIT # | DATE MOVED |
| | |
| - | |
| <u>ORIGINA</u> | AL PERMIT INFORMATION |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| JRB-07-0024 | - |
| DATE | COA INFO |
| 3/17/2008 | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| Single Family Dwelling | - |
| COST | OTHER SOURCES |
| - | - |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| _ | |
| | |

| BEGINNING STREET NUMBER | 331-333 |
|---------------------------------|--------------|
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | First Street |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | NC |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | No |
| CRITERIA | - |
| | |



Photo Id: FirstSt331-333(1)

BUILDING DETAILS

| BUILDING NAME | ZONING |
|---|---|
| - | R-7 |
| GROUND FLOOR USE | NUMBER OF STORIES |
| Duplex | 3 |
| UPPER FLOOR USE | PROPERTY INDEX NUMBER |
| Duplex | 1116415028 - 1116415029 |
| CURRENT OCCUPANT | |
| - | |
| <u>NAT</u> | TIONAL REGISTER |
| | TIONAL REGISTER NR ELIGIBLE? |
| | |
| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? No | NR ELIGIBLE? No CRITERIA |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? No | NR ELIGIBLE? No CRITERIA - |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? NO NR LANDMARK? | NR ELIGIBLE? No CRITERIA - ALTERNATE ADDRESS? |

GENERAL INFORMATION

| CATEGORY | HISTORIC USE | |
|------------------------------|------------------------------|--|
| Building | Domestic - multiple dwelling | |
| CONDITION | SECONDARY STRUCTURE | |
| Good | [attached garage] | |
| INTEGRITY | NR SECOND | |
| Not altered | - | |
| CURRENT USE | | |
| Domestic - multiple dwelling | | |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|----------------------|
| No Style | - |
| DETAILS | PORCH |
| - | - |
| OTHER YEAR | WINDOW MATERIAL |
| - | - |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Permit | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| - | - |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | - |
| PLAN | SIGNIFICANCE |
| - | - |
| NO OF STORIES | HISTORIC FEATURES |
| - | - |
| ROOF TYPE | ALTERATIONS |
| - | - |
| ROOF MATERIAL | |
| | |



Photo Id: First331333

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|-----------------------------|-----------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| PERMIT/ | HISTORIC INFORMATION |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| _ | |
| - | |
| <u>PERMIT</u> | MOVING INFORMATION |
| | |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| ODICINA | L DEDMIT INFORMATION |
| ORIGINA | AL PERMIT INFORMATION |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| JRB-01-0046 | - |
| DATE | COA INFO |
| 4/9/2001 | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| Duplex | - |
| COST | OTHER SOURCES |
| - | - |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| - | - |
| | |

| BEGINNING STREET NUMBER | 504 |
|---------------------------------|--------------|
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | First Street |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | NC |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | No |
| CRITERIA | - |
| | |



Photo Id: FirstSt504(1)

BUILDING DETAILS

| BUILDING NAME | ZONING |
|---|---|
| - | I-2 |
| GROUND FLOOR USE | NUMBER OF STORIES |
| Commercial | 1 |
| UPPER FLOOR USE | PROPERTY INDEX NUMBER |
| N/A | 1116408004 |
| CURRENT OCCUPANT | |
| - | |
| <u>NAT</u> | TIONAL REGISTER |
| | TIONAL REGISTER NR ELIGIBLE? |
| | |
| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? | NR ELIGIBLE? No CRITERIA |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? | NR ELIGIBLE? No CRITERIA - |
| NR DISTRICT CONTRIB/NON-CONTRIB NC WITHIN DISTRICT? NO NR LANDMARK? | NR ELIGIBLE? No CRITERIA - ALTERNATE ADDRESS? |

GENERAL INFORMATION

| CATEGORY | HISTORIC USE |
|---------------------------------|--|
| Building | Industry/Processing/Extraction - Warehouse |
| CONDITION | SECONDARY STRUCTURE |
| Good | - |
| INTEGRITY | NR SECOND |
| Major alterations and additiona | - |
| CURRENT USE | |
| Commerce/Trade | |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|---|
| No Style | Concrete |
| DETAILS | PORCH |
| - | - |
| OTHER YEAR | WINDOW MATERIAL |
| - | Aluminum/vinyl |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Permit | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Concrete block | Double Hung |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | 1/1 |
| PLAN | SIGNIFICANCE |
| Rectangular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 1 | Broad gable roof |
| ROOF TYPE | ALTERATIONS |
| Front Gable | Gable roof replacing original flat roof; replacement windows in |
| ROOF MATERIAL | downsized openings; replacement front door; awning over entry; 1 story rear addition (1985) |
| Asphalt - shingle | Citaly, 1 Scory (car addition (1909) |



Photo Id: First504

| OLD ADDRESS (CITY DIR.YEAR | BUILDER | |
|---|--|--|
| - | - | |
| BUILDING MOVED? | SURVEYOR | |
| - | LR | |
| MOVED FROM | SURVEYOR ORGANIZATION | |
| - | Ramsey Historic Consultants | |
| ORIGINAL OWNER | SURVEY DATE | |
| Ortseifen, A. J. | May-June 2016 | |
| ORIGINAL ARCHITECT | SURVEY AREA | |
| - | Downtown Libertyville | |
| ARCHITECT SOURCE | | |
| - | | |
| PERMIT/HISTO | PRIC INFORMATION | |
| OLD ADDRESS | DATE OF CONSTRUCTION | |
| - | - | |
| PERMIT MOVI | NG INFORMATION | |
| MOVING PERMIT # | DATE MOVED | |
| - | - | |
| BUILDING PERMIT # 447 | OTHER PERMIT INFORMATION | |
| DATE | COA INFO | |
| 9/10/1952 | - | |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO | |
| - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS | Building was occupied by Ace Welding Serviceinformation on business on Illinois Digital Archive (provided by Libertyville-Mundelein Historical Society and Cook Memorial Public Library) "Historic photo of building on Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library)This business offered general repairs on residential and industrial steel structures and ornamental iron. In addition, they manufactured new truck bodies and utility and boat trailers." | |
| 85-327 (1985)addition (?not clear on permit, \$30,000); | OTHER SOURCES | |
| | Historic photo of building on Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library) http://www.idaillinois.org/cdm/ref/collection/cookmemo11/id/19 | |
| | HISTORIC INFO COMPILER | |
| | LR | |
| | VOLUNTEER | |
| | - | |
| | | |

Commercial

CURRENT OCCUPANT

| BEGINNING STREET NUMBER | 510 | |
|---------------------------------|--------------|-----------------------|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | First Street | |
| PIN | | |
| <u>LOCAL</u> | | Body works |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | NC | |
| LOCAL LANDMARK? | No | |
| YEAR | - | Photo Id: FirstSt510 |
| LOCAL LANDMARK ELIGIBLE? | No | Piloto Id. Filst5t510 |
| CRITERIA | - | |
| | <u>B</u> L | JILDING DETAILS |
| BUILDING NAME | | ZONING |
| - | | I-2 |
| GROUND FLOOR USE | | NUMBER OF STORIES |
| Commercial | | 2 |
| UPPER FLOOR USE | | PROPERTY INDEX NUMBER |

NATIONAL REGISTER

1116408013

| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
|---------------------------------|--------------------|
| NC | No |
| WITHIN DISTRICT? | CRITERIA |
| No | - |
| NR LANDMARK? | ALTERNATE ADDRESS? |
| No | - |
| YEAR | |
| - | |

| - | |
|---------------------------------|--------------------------------|
| GENERAL | <u>INFORMATION</u> |
| CATEGORY | HISTORIC USE |
| Building | Industry/Processing/Extraction |
| CONDITION | SECONDARY STRUCTURE |
| Good | - |
| INTEGRITY | NR SECOND |
| Major alterations and additions | - |
| CURRENT USE | |
| Commerce/Trade | |

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|---|
| No Style | Concrete-block |
| DETAILS | PORCH |
| - | - |
| OTHER YEAR | WINDOW MATERIAL |
| - | Aluminum/vinyl |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Surveyor/Sanborn Maps | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Concrete block | Double Hung |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| Stucco | 1/1 |
| PLAN | SIGNIFICANCE |
| Rectangular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 2 | - |
| ROOF TYPE | ALTERATIONS |
| Front Gable | Multiple rear additions that are substantially larger than original |
| ROOF MATERIAL | building (last addition dates from 1984); front facade stuccoed; non-historic front entrance with awning; replacement windows in |
| Asphalt - shingle | altered openings |



Photo Id: First510

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|--|-----------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| <u>PERMIT/H</u> | <u>ISTORIC INFORMATION</u> |
| | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| PERMIT N | MOVING INFORMATION |
| <u>. =</u> | TO TENO EN CIN MILEON |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| | |
| <u>ORIGINAL</u> | <u>PERMIT INFORMATION</u> |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | Sanborn Maps1948 |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| JCR-07-0053 (1/18/2008)exterior facade and new awning architectural drawings (7/18/1985)"Proposed addition for the street designed by Paymond 1, Nowak | o. |

Domestic - single dwelling

BEGINNING STREET NUMBER 518 **END STREET NUMBER** STREET # SUFFIX STREET NAME First Street **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** Photo Id: FirstSt518(2) LOCAL LANDMARK ELIGIBLE? Potentially Eligible **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** R-7 **GROUND FLOOR USE** NUMBER OF STORIES Residential **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential 1116408002 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good Detached garage INTEGRITY NR SECOND Minor alterations and additions **CURRENT USE**

| ARCHITECTURAL CLASSIFICATION | FOUNDATI |
|------------------------------|-------------|
| Italianate | Concrete |
| DETAILS | PORCH |
| - | Front entry |
| OTHER YEAR | WINDOW |
| 2002 | Wood |
| DATE SOURCE | WINDOW |
| Surveyor/permit | - |
| WALL MATERIAL (CURRENT) | WINDOW |
| Wood | Double Hui |
| WALL MATERIAL 2 (CURRENT) | WINDOW |
| - | 1/1 |
| PLAN | SIGNIFICA |
| Rectangular | Fine examp |
| NO OF STORIES | with charac |
| 2 | surrounds. |
| ROOF TYPE | HISTORIC |
| Hipped | Shallow hip |
| ROOF MATERIAL | classical w |
| Asphalt - shingle | ALTERATIO |
| | |

ION

MATERIAL

MATERIAL 2

TYPE

CONFIGURATION

ANCE

ple Italianate residential architecture in the village, acteristic bracketed cornice and classical wood window s. The enclosed front porch and open entry porch on facade are non-historic alterations.

FEATURES

ipped roof; wood cornice with scrolled brackets; vood window surrounds

Front porch addition (not historic); original north side sun porch removed and replaced with small entry porch (not historic)



Photo Id: FirstSt518(3)



Photo Id: First518



Photo Id: First518(2)

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|---|--|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| Yes | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| Unknown | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| PERMIT/HISTO | RIC INFORMATION |
| | DATE OF CONSTRUCTION |
| | DATE OF CONSTRUCTION |
| OLD ADDRESS | - |
| - | - NG INFORMATION DATE MOVED |
| PERMIT MOVI MOVING PERMIT # ORIGINAL PER | - NG INFORMATION DATE MOVED - MIT INFORMATION |
| PERMIT MOVI MOVING PERMIT # | - NG INFORMATION DATE MOVED - |
| PERMIT MOVI MOVING PERMIT # ORIGINAL PER BUILDING PERMIT # | - NG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - |
| PERMIT MOVI MOVING PERMIT # ORIGINAL PER | - NG INFORMATION DATE MOVED - MIT INFORMATION |
| PERMIT MOVI MOVING PERMIT # ORIGINAL PER BUILDING PERMIT # DATE - | - NG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - |
| PERMIT MOVI MOVING PERMIT # ORIGINAL PER BUILDING PERMIT # | - NG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO |
| PERMIT MOVI MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - | - MG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO Based on Sanborn maps, it appears that the house was moved |
| PERMIT MOVI MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST | - NG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a one-story single-family residence was found in the village |
| PERMIT MOVI MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - | - NG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO HISTORIC INFO Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a |
| PERMIT MOVI MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST | - NG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a one-story single-family residence was found in the village building files, but the lot number doesn't match that of the |
| PERMIT MOVI MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - | - MG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a one-story single-family residence was found in the village building files, but the lot number doesn't match that of the subject house. No moving permit was found. |
| PERMIT MOVI MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - EXTERIOR ALTERATION PERMITS | - MG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a one-story single-family residence was found in the village building files, but the lot number doesn't match that of the subject house. No moving permit was found. OTHER SOURCES |
| PERMIT MOVI MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED? - | - MG INFORMATION DATE MOVED - MIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a one-story single-family residence was found in the village building files, but the lot number doesn't match that of the subject house. No moving permit was found. OTHER SOURCES Sanborn Maps1924, 1933, 1948 IHSS photograph (mid-1970s) |