CURRENT USE

Domestic - multiple dwelling

BEGINNING STREET NUMBER 221-227 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** Newberry Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** Photo Id: NewberryAve221-227 LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 GROUND FLOOR USE NUMBER OF STORIES Rowhouses UPPER FLOOR USE PROPERTY INDEX NUMBER Rowhouses 1116405069 - 1116405070 - 1116405071 - 1116405072 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - multiple dwelling CONDITION SECONDARY STRUCTURE Excellent INTEGRITY NR SECOND Not altered

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	



Photo Id: July27Morning049



Photo Id: July27Morning051



Photo Id: July27Morning053

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	-
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT / LIGHT	ODIC INFORMATION
<u>PERMIT/HIST</u>	ORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
OLD ADDRESS	DATE OF CONSTRUCTION
-	
PERMIT MOV	<u>ING INFORMATION</u>
PERMIT MOV	ING INFORMATION
PERMIT MOV	ING INFORMATION DATE MOVED
MOVING PERMIT #	DATE MOVED
MOVING PERMIT #	
MOVING PERMIT # - ORIGINAL PER	DATE MOVED - RMIT INFORMATION
MOVING PERMIT #	DATE MOVED
MOVING PERMIT # - ORIGINAL PER	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION -
MOVING PERMIT # - ORIGINAL PER	DATE MOVED - RMIT INFORMATION
MOVING PERMIT # ORIGINAL PER BUILDING PERMIT #	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION -
MOVING PERMIT # ORIGINAL PER BUILDING PERMIT #	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION -
MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE -	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION - COA INFO -
MOVING PERMIT # - ORIGINAL PER BUILDING PERMIT # - DATE -	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION - COA INFO -
MOVING PERMIT # - BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION -	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO -
MOVING PERMIT # - BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION -	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO -
MOVING PERMIT # - BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO - OTHER SOURCES -
MOVING PERMIT # - BUILDING PERMIT # - DATE - BUILDING PERMIT DESCRIPTION - COST	DATE MOVED - RMIT INFORMATION OTHER PERMIT INFORMATION - COA INFO - HISTORIC INFO - OTHER SOURCES -

Domestic - single dwelling

BEGINNING STREET NUMBER 224 **END STREET NUMBER** STREET # SUFFIX STREET NAME Newberry Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** LOCAL LANDMARK ELIGIBLE? No Photo Id: NewberryAve224(2) **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** R-7 **GROUND FLOOR USE** NUMBER OF STORIES Residential **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential 1116403020 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Excellent Detached garage INTEGRITY NR SECOND Not altered NC **CURRENT USE**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional - Queen Anne	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	



Photo Id: NewberryAve224

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT	MOVING INFORMATION
LINITI	MOVING IN GRAPHON
MOVING PERMIT #	DATE MOVED
_	
<u>ORIGINA</u>	<u>L PERMIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
JRB-05-0065	-
DATE	COA INFO
1/11/2006	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
Single Family Residence	-
COST	OTHER SOURCES
\$261,480.00	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	-
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	-

Domestic - single dwelling

BEGINNING STREET NUMBER	228	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Newberry Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	The same of the sa
YEAR	-	Photo Td. Nauhawa (220/2)
LOCAL LANDMARK ELIGIBLE?	Yes	Photo Id: NewberryAve228(3)
CRITERIA	Α	
	<u>BUILDIN</u>	NG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residential		1.5
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116400001 - 1116403021
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	NATIONA	AL REGISTER NR ELIGIBLE?
WITHIN DISTRICT?		No CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor altterations		NC
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Craftsman Bungalow	Concrete-block
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor/Sanborn Maps	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood - shingles	3/1
PLAN	SIGNIFICANCE
Rectangular	Substantial Craftsman Bungalow with very high degree of
NO OF STORIES	architectural integrity.
1.5	HISTORIC FEATURES
ROOF TYPE	Side gable roof with overhanging eaves; front dormer with
Side Gable	triangular pediment; inset full front porch with square wood columns on solid knee walls; historic wood double hung
ROOF MATERIAL	windows; wood shingles on gable walls
Asphalt - shingle	ALTERATIONS
	rear deck addition (1998)



Photo Id: NewberryAve228(2)



Photo Id: NewberryAve228(4)



Photo Id: Newberry228

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
_	
<u>PERMIT/HIST</u>	TORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
OLD ADDRESS	DATE OF CONSTRUCTION
-	
PERMIT MOV	/ING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PE	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	79-3 (7/6/1979)garage
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	Sanborn Maps1924, 1933, 1948
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
98-580 (7/16/1998)kitchen alterations and deck addition	-
, , , , , , , , , , , , , , , , , , ,	

CURRENT USE

Commerce/Trade

BEGINNING STREET NUMBER 117 **END STREET NUMBER** STREET # SUFFIX STREET NAME E. Park Avenue **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** Photo Id: ParkAveE117(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** C-2 **GROUND FLOOR USE** NUMBER OF STORIES Commercial **UPPER FLOOR USE** PROPERTY INDEX NUMBER N/A 1121212046 **CURRENT OCCUPANT NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good Detached garage INTEGRITY NR SECOND Major alterations and additions

ARCHITECTURAL CLASSIFICATION	FOUNDATION
No Style (altered)	Concrete-block
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
1962, 1990s	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor/Sanborn maps/permits	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Concrete block	Double hung, casement & storefront
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Brick	1/1; 1-light
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
1 & 2	2- and 1-story concrete block residential structure at rear
ROOF TYPE	ALTERATIONS
Combination	one-story commercial addition to north end of residential
ROOF MATERIAL	structure (1962); standing seam metal mansard roof on
Asphalt - shingle/not visible	commercial addition, entry canopy on residential section (1990s)



Photo Id: ParkAveE117(2)



Photo Id: EParkAve117(2)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTOR	DATE OF CONSTRUCTION
CED ADDRESS	DATE OF CONSTRUCTION
ORIGINAL PERM	- IIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1948 (Sheet 5)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#3171 (11/27/1962)1-story addition; 2610 (4/24/1960)build hipped roof over old flat roof; #2069 (4/13/1949)one-story frame porch addition to residence; No permit # (11/20/1957)2 bedroom & 1 bath (addition); Application for certificate of approval (6/9/1988)new fascia and mansard	-

BEGINNING STREET NUMBER	127	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	E. Park Avenue	ACTIC LACTIC
PIN		C
LOCAL		AND
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	District Ide Devices 5127(1)
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: ParkAveE127(1)
CRITERIA	-	
BUILDING NAME	<u> </u>	ZONING
-		C-2
GROUND FLOOR USE		NUMBER OF STORIES
Commercial/Office		1
UPPER FLOOR USE		PROPERTY INDEX NUMBER
N/A		1121212004
CURRENT OCCUPANT		
-		
NATIONAL REGISTER		
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC		No
WITHIN DISTRICT?		CRITERIA
No NR LANDMARK?		ALTERNATE ADDRESS?
No No		-
YEAR		

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Commerce/Trade - office
CONDITION	SECONDARY STRUCTURE
Good	-
INTEGRITY	NR SECOND
Minor alterations	-
CURRENT USE	
Commerce/Trade - office	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Freestanding Commercial	-
DETAILS	PORCH
Mansard	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Architectural drawings	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	



Photo Id: EParkAve127

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/	<u>HISTORIC INFORMATION</u>
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT	MOVING INFORMATION
PERMII	MOVING INFORMATION
MOVING REPAIR #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	L PERMIT INFORMATION
<u> </u>	
BUILDING PERMIT #	OTHER PERMIT INFORMATION
78-313	-
DATE	COA INFO
6/12/1978	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
Office Building	Architectural drawings and historic photograph of building soon
COST	after completion in permit file.
-	OTHER SOURCES
ORIGINAL OWNER OCCUPIED?	Sanborn Maps1948
-	HISTORIC INFO COMPILER
EXTERIOR ALTERATION PERMITS	LR
	VOLUNTEER

Domestic - multiple dwelling; Commerce/Trade - office

BEGINNING STREET NUMBER 131 **END STREET NUMBER** STREET # SUFFIX STREET NAME E. Park Avenue **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** Photo Id: ParkAveE131 LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING C-2 **GROUND FLOOR USE** NUMBER OF STORIES Office; Commercial **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential Apartments 1121212047 **CURRENT OCCUPANT NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION**

CATEGORY	HISTORIC USE
Building	Domestic - multiple dwelling; Commerce/Trade - office
CONDITION	SECONDARY STRUCTURE
Good	-
INTEGRITY	NR SECOND
Minor alterations	-
CURRENT USE	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Contemporary	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	



Photo Id: EParkAve131

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Sutter, F. M.	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
Sutter, F. M.	Downtown Libertyville
ARCHITECT SOURCE	
Permit	
DEDMIT /	HISTORIC INFORMATION
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PFRMIT	MOVING INFORMATION
<u>- = 10,121</u>	110 V2110 2111 0111 1/11 2011
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
88-703	-
DATE	COA INFO
9/9/1987	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
Office & Residential building	-
COST	OTHER SOURCES
\$690,000.00	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
No	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
JB-12-0103 (10/4/2012)replace siding and trim	-

Good

INTEGRITY

Minor alterations

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER 203 **END STREET NUMBER** STREET # SUFFIX STREET NAME E. Park Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** LOCAL LANDMARK ELIGIBLE? No Photo Id: EParkAve203 **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** C-2 **GROUND FLOOR USE** NUMBER OF STORIES Residential **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential 1121212007 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE**

Detached garage
NR SECOND

1-story rear porch addition (1966, enclosed); rear deck addition

(not historic)

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Side Gable	Concrete-block
DETAILS	PORCH
Craftsman	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double hung & other
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1; 6/6; 1-light; multi-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2.5	Side gable roof with low shed through-the-cornice front dormer;
ROOF TYPE	shed-roof porch with classical columns; secondary entry along east facade with shed canopy; three-sided first-story bay
Side Gable	window on west facade
ROOF MATERIAL	ALTERATIONS
Asphalt - shingle	Replacement siding (1994); replacement windows in original openings (1994); replacement railings and steps on front porch;



Photo Id: ParkAveE203(1)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
MOVING PERMIT #	NG INFORMATION DATE MOVED - MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
_	Sanborn Maps1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
94-684 (1994)replace roofing, aluminum/vinyl siding, and soffits, replace windows in kind, repair front porch decking; #3907 (5/3/1966)rear porch addition	-

CURRENT USE

Commerce/Trade

BEGINNING STREET NUMBER 207 **END STREET NUMBER** STREET # SUFFIX STREET NAME E. Park Avenue **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? No **YEAR** Photo Id: ParkAveE207(4) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** C-2 **GROUND FLOOR USE** NUMBER OF STORIES Office UPPER FLOOR USE PROPERTY INDEX NUMBER Office 1121212008 **CURRENT OCCUPANT** Natural Health Chiropractic **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good Detached garage INTEGRITY NR SECOND Moderate alterations

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front Cottage	Concrete-block
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double hung & fixed
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1; 1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof and rectangular massing; hipped-roof full-front
ROOF TYPE	porch structure (enclosed)
Front Gable	ALTERATIONS
ROOF MATERIAL	Replacement siding (1994); replacement windows in original
	openings; front porch enclosed (two door openings, one picture

window); fixed shutters

Asphalt - shingle



Photo Id: ParkAveE207



Photo Id: EParkAve207(2)



Photo Id: EParkAve207

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
_	
<u>PERMIT</u>	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINA</u>	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	94-159 (4/13/1994)install vinyl siding, soffit, fascia, and
DATE	gutters; 6955 (9/11/1973)remove existing O. H. Dor and install plate glass window
-	COA INFO
BUILDING PERMIT DESCRIPTION	-
-	HISTORIC INFO
COST	
-	OTHER SOURCES
ORIGINAL OWNER OCCUPIED?	Sanborn Maps1933, 1948
[-	HISTORIC INFO COMPILER
EXTERIOR ALTERATION PERMITS	LR
-	VOLUNTEER
	-

Commerce/Trade - office

BEGINNING STREET NUMBER 212 **END STREET NUMBER** STREET # SUFFIX STREET NAME E. Park Avenue **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? No **YEAR** Photo Id: ParkAveE212(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** C-2 **GROUND FLOOR USE** NUMBER OF STORIES Commercial **UPPER FLOOR USE** PROPERTY INDEX NUMBER N/A 1121203007 **CURRENT OCCUPANT** Shear Fashion Beauty Salon **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Commerce/Trade - office CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Minor alterations **CURRENT USE**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Freestanding Commercial	Not visible
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
1955 (c)	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Assessor/Sanborn maps/ Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stone	Casement
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Brick	1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1	Sanborn and Assessor date indicate the building was constructe
ROOF TYPE	around 1930
Flat	ALTERATIONS
ROOF MATERIAL	Lannon stone siding on front and side facades (1950);
Not Visible	replacement windows in original openings (not historic); replacement front door; aluminum on overhanging front eave



Photo Id: Park212

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOVIN	IG INFORMATION
I EKIIII IIOVIK	IN THE TAIL ON
MOVING PERMIT #	DATE MOVED
-	_
<u>ORIGINAL PERM</u>	IIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	[-
	COA TNEO
DATE	COA INFO
-	-
DATE - BUILDING PERMIT DESCRIPTION	COA INFO - HISTORIC INFO
- BUILDING PERMIT DESCRIPTION -	- HISTORIC INFO -
-	- HISTORIC INFO - OTHER SOURCES
- BUILDING PERMIT DESCRIPTION - COST	- HISTORIC INFO - OTHER SOURCES Sanborn Map1933, 1948
- BUILDING PERMIT DESCRIPTION -	- HISTORIC INFO - OTHER SOURCES Sanborn Map1933, 1948 HISTORIC INFO COMPILER
- BUILDING PERMIT DESCRIPTION - COST - ORIGINAL OWNER OCCUPIED?	- HISTORIC INFO - OTHER SOURCES Sanborn Map1933, 1948 HISTORIC INFO COMPILER LR
- BUILDING PERMIT DESCRIPTION - COST	- HISTORIC INFO - OTHER SOURCES Sanborn Map1933, 1948 HISTORIC INFO COMPILER

Domestic - multiple dwelling; Commerce/Trade

BEGINNING STREET NUMBER 215 **END STREET NUMBER** STREET # SUFFIX STREET NAME E. Park Avenue **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC **LOCAL LANDMARK? YEAR** LOCAL LANDMARK ELIGIBLE? No Photo Id: EParkAve215 **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** C-2 **GROUND FLOOR USE** NUMBER OF STORIES Office; Commercial **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential Apartments 1121212054 **CURRENT OCCUPANT NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - multiple dwelling; Commerce/Trade CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Minor alterations **CURRENT USE**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Contemporary	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	



Photo Id: EParkAve215(2)



Photo Id: EParkAve215(3)



Photo Id: EParkAve215(4)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	-
ORIGINAL ARCHITECT	SURVEY AREA
Sutter & Sutter	Downtown Libertyville
ARCHITECT SOURCE	
Architectural drawings	
PERMIT/I	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PFRMIT	MOVING INFORMATION
1 21(1121	THOUSEN SKITTLESS
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	_
i DATE	COA INFO
1/31/1991	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
Commercial/Apartment Building	-
COST	OTHER SOURCES
-	Architectural drawings in permit file at Buildings Department
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	-
<u> </u>	