Domestic - multiple dwelling

BEGINNING STREET NUMBER 118-124 **END STREET NUMBER** STREET # SUFFIX **STREET NAME Broadway Avenue** PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? LOCAL LANDMARK? **YEAR** Photo Id: BroadwayAve118-124(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-8 NUMBER OF STORIES **GROUND FLOOR USE** Residential Apartments **UPPER FLOOR USE** PROPERTY INDEX NUMBER N/A 1116414010 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - multiple dwelling CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Minor alterations **CURRENT USE**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Ranch	Not visible
DETAILS	PORCH
-	Multiple entries
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Brick	Double hung & awning
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Stucco	1/1; 1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1	Horizontal massing and flat roof; inset corner entry porches for
ROOF TYPE	each unit, with wrought iron railings
Flat	ALTERATIONS
ROOF MATERIAL	Replacement windows in original openings; replacement doors
Not Visible	



Photo Id: BroadwayAve118-124(2)



Photo Id: broadway118124(2)



Photo Id: broadway118124

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	Roewert, Roy
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Roewert, Roy	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
Hutchinson, George	Downtown Libertyville
ARCHITECT SOURCE	
Permit	
PERMIT/	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
118-126 Broadway (permit)	1955
MOVING PERMIT #	DATE MOVED -
ORIGINA	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
1136	-
DATE	COA INFO
5/23/1955	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
Four-family 1 story apartments	-
COST	OTHER SOURCES
\$24,000.00	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
No	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER 128 **END STREET NUMBER** STREET # SUFFIX STREET NAME **Broadway Avenue** PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** Photo Id: BroadwayAve128(1) LOCAL LANDMARK ELIGIBLE? Yes **CRITERIA** Н **BUILDING DETAILS BUILDING NAME ZONING** Taylor, Dr. John L. House R-8 GROUND FLOOR USE NUMBER OF STORIES Residence PROPERTY INDEX NUMBER **UPPER FLOOR USE** Residential 1116414013 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good Detached garage INTEGRITY NR SECOND Minor alterations

ARCHITECTURAL CLASSIFICATION	
Queen Anne	
DETAILS	
-	
OTHER YEAR	
-	
DATE SOURCE	_
Assessor	
WALL MATERIAL (CURRENT)	_
Wood	
WALL MATERIAL 2 (CURRENT)	_
Wood - shingles	
PLAN	_
Rectangular	
NO OF STORIES	_
2.5	
ROOF TYPE	
Combination	
ROOF MATERIAL	
Asphalt - shingle	

FOUNDATION

Brick

PORCH

Full Front

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

i

WINDOW TYPE

Double hung & casement

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

This 1890s Queen Anne house may be eligible for local landmark designation as the home of Dr. John L. Taylor, a physician who served as Lake County coroner for 43 years.

HISTORIC FEATURES

Steeply pitched side gable roof; fishscale shingles and sunburst motif on gable walls; polygonal full-height bay with pointed roof at southeast corner of facade; full-front porch structure with triangular pediment over entry; historic wood windows, some with Queen Anne-style upper sash

ALTERATIONS

Replacement floor, railings on front porch; 1-story rear addition and 2nd story rear addition (post-1948); some replacement windows in original openings on west elevation



Photo Id: BroadwayAve128(2)



Photo Id: broadway128(2)



Photo Id: broadway128



to Id: 128Broadway

Pho

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	1893
PERMIT MOVIN	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
BUILDING PERMIT #	OTHER PERMIT INFORMATION
- DATE	- COA TRIFO
DATE	COA INFO
- DUTI DANG DEDMAT DESCRIPTION	HISTORIC INFO
BUILDING PERMIT DESCRIPTION	
-	Historic photo (1950s) and information at Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and
COST	Cook Memorial Public LIbrary:
- ODICINAL OWNER OCCUPIEDS	http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/1960/rec/1 "This house stands at 128 Broadway, at the
ORIGINAL OWNER OCCUPIED?	northwest corner of Broadway and right Court. It is more than
EVERTOR ALTERATION DEPMITS	one hundred years old. It was the home of Dr. John L. Taylor who was born in Staceyville, Iowa in 1866 and came to
EXTERIOR ALTERATION PERMITS	Libertyville as a youth. Taylor graduated from Rush Medical
93-474 (8/30/1993)repairs and replacement to the base and deck of roofed porch	College in 1894 and began practicing medicine in Libertyville. He married Laura Schanck on June 1, 1895. Dr. Taylor was said to
	have delivered 3000 infants during his 50 years in medical
	practice; he also served as Lake County coroner for 43 years
	and was active in civic affairs. Automobiles were an early passion; he drove his first car around town in 1907. A classic
	example of the "country doctor," Dr. Taylor was well loved and
	respected by the entire community. On the day of his funeral, May 9, 1944, Libertyville village businesses closed from 2 to 3
	o'clock in the afternoon."
	OTHER SOURCES
	Historic photo of house on p. 38 of LIBERTYVILLE ILLUSTRATED. Sanborn Maps:
	HISTORIC INFO COMPILER
	LR
	VOLUNTEER
	-
	į l

Domestic - multiple dwelling

BEGINNING STREET NUMBER	140-142	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: BroadwayAve140-142(2)
CRITERIA	-	
BUILDING NAME	DOILDIN	VIG DETAILS ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residential Apartments		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential Apartments		1116415017
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	NATIONA	AL REGISTER NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		310 Wright Court
YEAR		
-		
	<u>GENERAL I</u>	NFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		[attached garage]
INTEGRITY		NR SECOND
Minor alterations and additions		-
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Brick
DETAILS	PORCH
Queen Anne	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2	Front gable roof; full-height polygonal bay on v
ROOF TYPE	porch structure on front facade; secondary por west facade
Front Gable	ALTERATIONS
ROOF MATERIAL	Replacement siding (2000); replacement windo
Asphalt - shingle	openings (2001); replacement columns, railing

west facade; front ch structure on

ows in original openings (2001); replacement columns, railings, and steps on front porch; replacement columns and railings on west porch; rear attached garage addition (2003)



Photo Id: BroadwayAve140-142



Photo Id: Wright310

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	DRIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	1900 (c.)
MOVING PERMIT #	DATE MOVED
ORIGINAL PER	RMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
- COST	According to Sanborn maps, the house was converted to multifamily use some time between 1933 and 1948.
	OTHER SOURCES
ORIGINAL OWNER OCCUPIED?	Sanborn Fire Company Insurance Maps, 1924, 1933, 1948
OKIGINAL OWNER OCCUPIED:	HISTORIC INFO COMPILER
EXTERIOR ALTERATION PERMITS	LR
	VOLUNTEER
PB-01-0706 (7/25/2001)replacement windows, door trim, fascia, and soffit; 00413 (5/23/2000)vinyl siding house and garage; JRA-01-0066 (3/24/2003)addition, siding, & roof deck	-

Domestic - single dwelling

BEGINNING STREET NUMBER 146 **END STREET NUMBER** STREET # SUFFIX STREET NAME **Broadway Avenue** PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** Photo Id: BroadwayAve146(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME ZONING** R-9 **GROUND FLOOR USE** NUMBER OF STORIES Residence **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential 1116415018 **CURRENT OCCUPANT NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB **NR ELIGIBLE?** WITHIN DISTRICT? CRITERIA No NR LANDMARK? **ALTERNATE ADDRESS?** No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION **SECONDARY STRUCTURE** Good INTEGRITY NR SECOND Minor alterations **CURRENT USE**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Four Over Four (altered)	Concrete
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
1969	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor/Sanborn/Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1; geometric/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2	Full front porch with hipped roof and solid knee walls;
ROOF TYPE	geometric/1 double hung windows; square oriel window bay on east facade
Hipped	ALTERATIONS
ROOF MATERIAL	
Asphalt - shingle	2nd story addition (1969); front porch enclosed; front steps and railing replaced; replacement siding



Photo Id: BroadwayAve146(2)



Photo Id: Broadway146

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT /LICTO	DIC INCODMATION
PERMIT/HISTO	ORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
OLD ADDRESS	DATE OF CONSTRUCTION
-	[-
<u>PERMIT MOVI</u>	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ODICINAL DED	MIT INFORMATION
ORIGINAL PER	MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Insurance Company Maps 1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
JD-12-0001 (3/13/2012)replace exterior stairway; 4971 (8/19/1969)raise roof 8 feet	-

Domestic - single family

BEGINNING STREET NUMBER	150	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	Photo Id: BroadwayAve150(2)
LOCAL LANDMARK ELIGIBLE?	No	Filoto Id. BroadwayAve130(2)
CRITERIA	-	
	BUILDI	NG DETAILS
BUILDING NAME		ZONING
-		-
GROUND FLOOR USE		NUMBER OF STORIES
Residence		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116415019
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	NATIONA	AL REGISTER NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-	GENERAL I	INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single family
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor alterations		NC
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Concrete-block
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Owner	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood	1/1
PLAN	SIGNIFICANCE
L	-
NO OF STORIES	HISTORIC FEATURES
2	Front gable roof; rectangular massing; north side gable
ROOF TYPE	ALTERATIONS
Front Gable	Replacement front porch columns; replacement windows in
ROOF MATERIAL	original openings; replacement front door; picture window under
Asphalt - shingle	F



Photo Id: Broadway150

OLD ADDRESS (CITY DIR.YEAR	BUILDER
- PULL DANG MOVEDS	- CURVEYOR
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTO	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
PERMIT MOVIN	NG INFORMATION
FERMIT MOVI	10 INI OKIMATION
MOVING PERMIT #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	99-292 (4/30/1999)3 car garage
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
_	Owner writes on house history form: "Martin Lynch 1909-1952
COST	lived at this house and was one of the earliest rural mail carriers
-	from the Libertyville post office." House was also featured on June 2012 Libertyville Historic Walking Tour.
ORIGINAL OWNER OCCUPIED?	OTHER SOURCES
_	O.I.ER GOORGES
EXTERIOR ALTERATION PERMITS	HISTORIC INFO COMPTI ED
	HISTORIC INFO COMPILER
75-392 (9/27/1975)addition (\$3,000); 6313 (5/4/1971) enclose front porch on three sides; 867 (6/7/1954)new steps	LR
and straighten up porch, patch stucco; 92-147 (3/24/1992) opening up and repairing existing closed in front porch	VOLUNTEER -

Domestic - single dwelling

BEGINNING STREET NUMBER	154	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: BroadwayAve154(1)
CRITERIA	-	
	<u>B</u>	UILDING DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residence		1.5
UPPER FLOOR USE		PROPERTY INDEX NUMBER
N/A		1116415021
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	N.A	ATIONAL REGISTER NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	<u>GEN</u>	ERAL INFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		-
INTEGRITY		NR SECOND
Minor alterations and additions		-
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front Cottage	Not visible
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof and rectangular massing of original structure;
ROOF TYPE	front porch structure; west and rear (north) additions appear to be early (pre-1925)
Multi-gable	ALTERATIONS
ROOF MATERIAL	Some replacement windows in original openings.
Acphalt chingle	Some replacement windows in original openings.

Asphalt - shingle



Photo Id: BroadwayAve154(2)



Photo Id: Broadway153

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/HISTOR</u>	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
	IC THEODIA TION
PERMII MOVIN	<u>IG INFORMATION</u>
MOVING DEDMIT #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	IIT INFORMATION
<u> </u>	
BUILDING PERMIT #	OTHER PERMIT INFORMATION
_	_
DATE	COA INFO
	_
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
BOLDING PERMIT DESCRIPTION	INSTORIC INFO
COST	- OTHER COURCES
COST	OTHER SOURCES
-	Sanborn Fire Insurance Company Maps, 1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
00-66 (2/21/2000)rebuilt front porch, leaving roof in place; 2573 (2/2/1960)interior work, 2nd floor; 2 rooms and kitchen, 2 dormers, exterior stairway	-

Domestic - single dwelling

BEGINNING STREET NUMBER	162	
END STREET NUMBER	-	
STREET # SUFFIX	-	BROAD
STREET NAME	Broadway Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: BroadwayAve162
CRITERIA	NO	
CRITERIA	-	
	BUILDIN	IG DETAILS
BUILDING NAME		ZONING
-		R-8
GROUND FLOOR USE		NUMBER OF STORIES
Residence		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116415022
CURRENT OCCUPANT		
-		
	NATIONA	AL REGISTER
		
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL T	NFORMATION
	<u>OLIVEITAL I</u>	HI OKPIATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Excellent		[attached garage]
INTEGRITY		NR SECOND
Not altered		-
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	



Photo Id: broadway162

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/</u>	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	2009
DEDMIT	MOVING INFORMATION
PERMII	MOVING INI ORMATION
MOVING DERMIT #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	AL PERMIT INFORMATION
	
BUILDING PERMIT #	OTHER PERMIT INFORMATION
JRB-09-0008	-
DATE	COA INFO
7/28/2009	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
_	_
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
_	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
LAILRION ALIERATION PERMITS	VOLONTILER
I =	

Domestic - single dwelling

BEGINNING STREET NUMBER	204	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	The same of the sa
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: BroadwayAve204(1)
CRITERIA	-	
	BUILDIN	NG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residence		1.5
UPPER FLOOR USE		PROPERTY INDEX NUMBER
N/A		1116419012
CURRENT OCCUPANT		
NR DISTRICT CONTRIB/NON-CONTRIB	NATIONA	AL REGISTER NR ELIGIBLE?
NC		No No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	NFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Not altered		NC
CUDDENT LICE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Owner	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	



Photo Id: BroadwayAve204(2)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	Lazzaretto
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTOI	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOVIA	IC THEODMATION
PERMII MOVIN	IG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	<u> IIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
323 (5/7/1952)Alumawall shake siding; 6897 (August 1972) frame addition	-

Domestic - single dwelling

BEGINNING STREET NUMBER	208	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	attended to the second
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	_	
	N-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: Broadway208
CRITERIA	-	560 141 51044114/200
	BUILDIN	IG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residence		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116419013
CURRENT OCCUPANT		
-		
	NATIONA	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
NC		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	<u>GENERAL I</u>	NFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Major alterations and additions		NC
CURRENT USE		

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Queen Anne	Parged
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
1990	Wood
DATE SOURCE	WINDOW MATERIAL 2
Surveyor/Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood - shingles	1/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2	-
ROOF TYPE	ALTERATIONS
Front Gable	Original house obscured by extensive alterations and additions turret addition; front porch addition; 1-story rear addition; Queen Anne trim throughout
ROOF MATERIAL	
Acphalt - chingle	



Photo Id: BroadwayAve208(1)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
MOVING PERMIT # - ORIGINAL PER	- MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
COST	According to owner's House History form, the house was originally a one-room, 1.5-story structure that dated from the 19th century.
-	OTHER SOURCES
ORIGINAL OWNER OCCUPIED?	Sanborn maps:
-	HISTORIC INFO COMPILER
EXTERIOR ALTERATION PERMITS	LR
90-297 (5/22/1990)turret addition; 88-536 (8/27/1988)	VOLUNTEER
alterations (\$5,000); No permit # (4/15/1978)sun porch	TOLONTELN
addition; 82.151 (7/10/1982)deck addition	-

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER	214	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: BroadwayAve214(1)
CRITERIA	-	
	BUILDIN	NG DETAILS
BUILDING NAME		ZONING
-		R-7
GROUND FLOOR USE		NUMBER OF STORIES
Residence		1.5
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116419014
CURRENT OCCUPANT		
-		
	NATIONA	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		
-		
	GENERAL I	NFORMATION
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor alterations		NC

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Bungalow	Not visible
DETAILS	PORCH
Craftsman	Front entry
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	3/1; 4/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Broad side gable roof with long, shed-roof front dormer; inset
ROOF TYPE	corner entry porch; 4/1 wood windows on first floor; three-sided window bay on east facade
-	ALTERATIONS
ROOF MATERIAL	Replacement siding; replacement windows in dormer; entry
Asphalt - shingle	porch enclosed



Photo Id: BroadwayAve214(2)



Photo Id: broadway214

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	-
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT /LICE	
PERMII/HIS	TORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOV	VING INFORMATION
	
MOVING PERMIT #	DATE MOVED
-	-
<u>ORIGINAL PE</u>	ERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	88-477 (7/27/1988)garage
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
1576 (8/27/1956)replace two rear kitchen windows	-