BEGINNING STREET NUMBER	130
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Stewart Avenue
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: StewartAveN130(1)

## **BUILDING DETAILS**

BUILDING NAME	ZONING
-	R-7
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2.5
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1121104001
CURRENT OCCUPANT	·
-	

## **NATIONAL REGISTER**

NR DISTRICT CONTRIB/NON-CONTRIB		
С		
WITHIN DIST	IRICT?	
No		
NR LANDMAR	ι <b>Κ</b> ?	
No		
YEAR		
-		

#### NR ELIGIBLE?

No CRITERIA

-

ALTERNATE ADDRESS?

# **GENERAL INFORMATION**

D
SE
D
NR
С

#### HISTORIC USE

Domestic - single dwelling
ECONDARY STRUCTURE

Detached garage

NR SECOND

| C

#### ARCHITECTURAL CLASSIFICATION

Dutch Colonial Revival

DETAILS

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

**NO OF STORIES** 

2.5

ROOF TYPE

Front Gambrel

ROOF MATERIAL

Asphalt - shingle

#### FOUNDATION

Brick

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

Wood

WINDOW TYPE

Double hung, fixed & casement

WINDOW CONFIGURATION

9/1; 1/1; 6/1; multi-light

SIGNIFICANCE

#### HISTORIC FEATURES

Steep front gambrel roof with cornice returns; north and south dormers with triangular pediments

#### ALTERATIONS

Replacement siding; original full-width front porch replaced with gambrel-roof entry porch (post-1948); replacement windows in original openings (1999)



Photo Id: StewartAveN130(2)



Photo Id: Stewart130

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	

## **PERMIT/HISTORIC INFORMATION**

OLD ADDRESS

DATE OF CONSTRUCTION

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #** 

Γ.

DATE MOVED

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

92-474 (6/12/1992)--By front door remove marginal headers and replace with new ones. . .remove brick wall of house and expand into porch; 98-387 (5/20/1999)--windows and patio door

#### **OTHER PERMIT INFORMATION**

-

\_

COA INFO

HISTORIC INFO

Sanborn Maps--1924 (Sheet 5 and 9), 1933 (Sheet 5), 1948 (Sheet 5)

OTHER SOURCES

HISTORIC INFO COMPILER

LR

\_

VOLUNTEER

-

BEGINNING STREET NUMBER	201		
END STREET NUMBER	-		
STREET # SUFFIX	-		
STREET NAME	Stewart Avenue		
PIN			
LOCAL			
WITHIN LOCAL DISTRICT?	No		
LOCAL DIST CONTRIB/NON-CONTRIB?	С		
LOCAL LANDMARK?	No		
YEAR	-		
LOCAL LANDMARK ELIGIBLE?	Yes		
CRITERIA	A		



Photo Id: StewartAveN201(2)

## **BUILDING DETAILS**

#### **BUILDING NAME**

GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

	R-7
NUMBER OF STORIES	
	2.5

PROPERTY INDEX NUMBER

1116315006

ZONING

## **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

/EAR	
No	
NR LANDMARK?	
No	
WITHIN DISTRICT?	
С	

#### NR ELIGIBLE?

No

CRITERIA

#### ALTERNATE ADDRESS?

\_

## **GENERAL INFORMATION**

CATEGORY
Building
CONDITION
Good
INTEGRITY
Minor alterations
CURRENT USE
Domestic - single dwelling

HISTORIC USE					
Domestic - single dwelling					
SECONDARY STRUCTURE					
-					
NR SECOND					
-					

#### ARCHITECTURAL CLASSIFICATION

Gabled Ell

DETAILS

Queen Anne

OTHER YEAR

\_\_\_\_\_

DATE SOURCE

Surveyor

#### WALL MATERIAL (CURRENT)

Aluminum/vinyl

#### WALL MATERIAL 2 (CURRENT)

PLAN

#### Rectangular/L

**NO OF STORIES** 

#### 2.5

**ROOF TYPE** 

#### Clipped Gable

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Brick

#### PORCH

Wrap around

#### WINDOW MATERIAL

Wood

#### WINDOW MATERIAL 2

-

## WINDOW TYPE

Double hung, fixed & casement

## WINDOW CONFIGURATION

## 1/1; 1-light

## SIGNIFICANCE

Even with replacement siding, this Gabled-Ell residence with Queen Anne detailing may be eligible for local landmark designation.

#### HISTORIC FEATURES

Clipped front gable with south side gable-roof ell; wraparound porch with Ionic columns and historic wood railing; historic wood fixed and double hung windows; historic front door

#### ALTERATIONS

Replacement siding; concrete front porch steps with wrought iron railing; rear porch addition (1999)



Photo Id: StewartAveN201(3)



Photo Id: stewart201

OLD ADDRESS (CITY DIR.YEAR	BUILDER	
-	-	
BUILDING MOVED?	SURVEYOR	_
-	LR	
MOVED FROM	SURVEYOR ORGANIZATION	
-	Ramsey Historic Consultants	
ORIGINAL OWNER	SURVEY DATE	
-	May-June 2016	
ORIGINAL ARCHITECT	SURVEY AREA	
-	Downtown Libertyville	
ARCHITECT SOURCE		
-		
1		

## **PERMIT/HISTORIC INFORMATION**

OLD ADDRESS

DATE OF CONSTRUCTION

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #** 

DATE MOVED

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

#### EXTERIOR ALTERATION PERMITS

99-1213 (11/24/1999)--rear porch addition

#### **OTHER PERMIT INFORMATION**

-

\_

COA INFO

#### HISTORIC INFO

Sanborn maps--1924 (Sheet 5 & 9), 1933 (Sheet 5), 1948 (Sheet 5) According to owner's House History form, Ed Sullivan, representative for the 51st district in the IL State Legislature, grew up in the house, and lived in it with his wife and children until the 1980s.

#### OTHER SOURCES

|\_\_

#### HISTORIC INFO COMPILER

LR

VOLUNTEER

-

BEGINNING STREET NUMBER	202	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Stewart Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: StewartAveN202(1)

## **BUILDING DETAILS**

#### **BUILDING NAME**

GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
N/A	
CURRENT OCCUPANT	

# R-8 NUMBER OF STORIES

PROPERTY INDEX NUMBER

1116316006

ZONING

1

## **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

С	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

#### NR ELIGIBLE?

No

CRITERIA

#### ALTERNATE ADDRESS?

\_

## **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Minor alterations	
CURRENT USE	
Domestic - single dwelling	

HISTORIC USE	
Domestic - single dwelling	
SECONDARY STRUCTURE	
Garage	
NR SECOND	
С	

#### ARCHITECTURAL CLASSIFICATION

Pyramidal Cottage

DETAILS

OTHER YEAR

\_

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

1

**ROOF TYPE** 

Hipped

**ROOF MATERIAL** 

Asphalt - shingle

#### FOUNDATION

Brick

PORCH

Full Front

#### WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

#### 3/1; 1/1

SIGNIFICANCE

#### -

#### **HISTORIC FEATURES**

Hipped roof with center chimney; full front porch; wood siding; simple classical window lintels

#### ALTERATIONS

Front porch rebuilt or enclosed (c. 1930); rear shed addition (may have originally been rear porch that was enclosed); 1/1 replacement windows on side elevations



Photo Id: StewartAveN202(4)



Photo Id: StewartAveN202(3)



Photo Id: Stewart202

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT	/HISTORIC INFORMATION

#### OLD ADDRESS

DATE OF CONSTRUCTION

## **PERMIT MOVING INFORMATION**

-

-

**MOVING PERMIT #** 

DATE MOVED

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

-DATE

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

-

## EXTERIOR ALTERATION PERMITS

637 (6/20/1953)--re-shingle front porch roof

#### **OTHER PERMIT INFORMATION**

-

-

COA INFO

HISTORIC INFO

Sanborn Maps--1924 (Sheets 5 and 9), 1933 (Sheet 5), 1948 (Sheet 5)

#### **OTHER SOURCES**

HISTORIC INFO COMPILER

LR

-

#### VOLUNTEER

-

BEGINNING STREET NUMBER	207	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Stewart Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: StewartAveN207(1)

## **BUILDING DETAILS**

#### **BUILDING NAME**

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

İ	
NUMBER OF STORIES	

2.5

ZONING

PROPERTY INDEX NUMBER

1116315005

## **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

#### **NR ELIGIBLE?**

No

CRITERIA

#### ALTERNATE ADDRESS?

-

# **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Moderate alterations and additions	
CURRENT USE	
Domestic - single dwelling	

## HISTORIC USE

Domestic - single dwelling
SECONDARY STRUCTURE

NR SECOND

#### ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

OTHER YEAR

\_

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

## PLAN

Irregular

NO OF STORIES

#### -----

2.5

## ROOF TYPE

Front Gable

#### ROOF MATERIAL

Asphalt - shingle

#### FOUNDATION

Concrete-block

PORCH

Wrap around

#### WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

#### WINDOW TYPE

Double hung & fixed

WINDOW CONFIGURATION

#### 1/1; 1-light

SIGNIFICANCE

#### -

#### **HISTORIC FEATURES**

Steep front gable roof; two-story south bay with cutaway corners; wraparound porch with turned supports; historic wood windows

#### ALTERATIONS

Aluminum siding; one-story south side addition (1977); front porch rebuilt (1992)



Photo Id: StewartAveN207(2)





Photo Id: stewart207(2)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTO	DRIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-

## PERMIT MOVING INFORMATION

**MOVING PERMIT #** 

DATE MOVED

-

\_

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

-DATE

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

## EXTERIOR ALTERATION PERMITS

77-322 (6/8/1977)--rec room addition; 92-197 (4/24/1992)-rebuild front porch **OTHER PERMIT INFORMATION** 

#### COA INFO

\_

HISTORIC INFO

-

#### OTHER SOURCES

Sanborn Maps--1924 (Sheets 5 & 9), 1933 (Sheet 5), 1948 (Sheet 5)

#### HISTORIC INFO COMPILER

LR

#### VOLUNTEER

-

BEGINNING STREET NUMBER	314
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Wright Court
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: WrightCt314(4)

## **BUILDING DETAILS**

#### **BUILDING NAME**

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

#### ZONING

| R-7

NUMBER OF STORIES

2

PROPERTY INDEX NUMBER

1116415011

## **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

С	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

#### NR ELIGIBLE?

No

CRITERIA

\_\_\_\_\_

#### ALTERNATE ADDRESS?

-

# **GENERAL INFORMATION**

ŀ

ATEGORY	
Building	
CONDITION	
Good	
NTEGRITY	
Moderate alterations	
URRENT USE	
Domestic - single dwelling	

IISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
IR SECOND
NC

#### ARCHITECTURAL CLASSIFICATION

Bungalow

DETAILS

OTHER YEAR

-DATE SOURCE

Assessor/Sanborn

WALL MATERIAL (CURRENT)

Wood - shingles

WALL MATERIAL 2 (CURRENT)

## PLAN

Rectangular

NO OF STORIES

#### 1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

#### FOUNDATION

Concrete

PORCH

Front entry canopy

WINDOW MATERIAL

#### Aluminum/vinyl

WINDOW MATERIAL 2

Wood

WINDOW TYPE

Double hung & casement

WINDOW CONFIGURATION

#### 1/1; 1-light

SIGNIFICANCE

-

#### **HISTORIC FEATURES**

Front gable roof with overhanging eaves and cornice returns; gable entry canopy; some wood 1/1 windows on south elevation

#### ALTERATIONS

Replacement windows in original openings; rear porch enclosed; one-story rear addition (2007)



Photo Id: WrightCt314(3)



Photo Id: wright314

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
OLD ADDRESS - DEDMIT	DATE OF CONSTRUCTION  - MOVING INFORMATION
	HOVING IN OKHATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
	6483 (9/7/1971)garage
DATE	COA INFO
-	
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

JRA-06-0036 (2007)--addition and basement remodel

OTHER SOURCES

Sanborn Maps--1912, 1924, 1933, 1948

HISTORIC INFO COMPILER

LR VOLUNTEER

\_

BEGINNING STREET NUMBER	320	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Wright Court	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: WrightCt320(1)

## **BUILDING DETAILS**

#### **BUILDING NAME**

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

## ZONING R-7 NUMBER OF STORIES

2

PROPERTY INDEX NUMBER

1116415010

## **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

WITHIN DISTRICT?	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

#### NR ELIGIBLE?

No

CRITERIA

\_\_\_\_\_

#### ALTERNATE ADDRESS?

-

# **GENERAL INFORMATION**

F

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Moderate alterations	
CURRENT USE	
Domestic - single dwelling	

ISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
IR SECOND
NC

#### ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

OTHER YEAR

-

## DATE SOURCE

Surveyor/Sanborn maps

#### WALL MATERIAL (CURRENT)

Aluminum/vinyl

#### WALL MATERIAL 2 (CURRENT)

PLAN

Irregular

#### NO OF STORIES

2.5

## ROOF TYPE

Combination

## ROOF MATERIAL

Asphalt - shingle

#### FOUNDATION

Brick

PORCH

#### Front

\_

WINDOW MATERIAL

## Aluminum/vinyl

WINDOW MATERIAL 2

## WINDOW TYPE

## Double Hung

#### WINDOW CONFIGURATION

1/1

#### SIGNIFICANCE

#### HISTORIC FEATURES

Hipped main roof with front gable bay; 2-story south bay with cutaway corners; hipped-roof front porch structure; historic wood front door

#### ALTERATIONS

Replacement siding; replacement windows in original openings; replacement front porch; 2-story rear addition (2002)



Photo Id: WrightCt320(4)

OLD ADDRESS (CITY DIR.YEAR	BUILDER	
-	-	
BUILDING MOVED?	SURVEYOR	
-	LR	
MOVED FROM	SURVEYOR ORGANIZATION	
-	Ramsey Historic Consultants	
ORIGINAL OWNER	SURVEY DATE	
-	May-June 2016	
ORIGINAL ARCHITECT	SURVEY AREA	
-	Downtown Libertyville	
ARCHITECT SOURCE		
-		
PERMIT/HISTOR	IC INFORMATION	
OLD ADDRESS	DATE OF CONSTRUCTION	
-	-	
PERMIT MOVING INFORMATION		

**MOVING PERMIT #** 

DATE MOVED

## **ORIGINAL PERMIT INFORMATION**

-

\_

**BUILDING PERMIT #** 

-DATE

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

JRA-02-0078 (11/7/2002)--2 story rear kitchen addition

OTHER PERMIT INFORMATION

COA INFO

-

HISTORIC INFO

OTHER SOURCES

Sanborn Maps--1912, 1924, 1933, 1948 1970s photograph on IHSS

HISTORIC INFO COMPILER

LR

VOLUNTEER

-

BEGINNING STREET NUMBER	322
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Wright Court
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: WrightCt322

## **BUILDING DETAILS**

#### **BUILDING NAME**

-	
GROUND FLOOR USE	
Duplex	
UPPER FLOOR USE	
Duplex	
CURRENT OCCUPANT	

#### ZONING

R-7

NUMBER OF STORIES

2

PROPERTY INDEX NUMBER

1116415027

## **NATIONAL REGISTER**

NR	DISTRICT	CONTRIB	/NON-CONTRIB

NC	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
_	
1	

#### NR ELIGIBLE?

No

CRITERIA

-

#### ALTERNATE ADDRESS?

-

# **GENERAL INFORMATION**

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Not altered	
CURRENT USE	
Domestic - multiple dwelling	

HISTORIC USE
Domestic - multiple dwelling
SECONDARY STRUCTURE
-
NR SECOND
-

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Vernacular	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Permit	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATI
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	

ION

# OLD ADDRESS (CITY DIR.YEAR BUILDER BUILDING MOVED? SURVEYOR LR MOVED FROM SURVEYOR ORGANIZATION Ramsey Historic Consultants ORIGINAL OWNER SURVEY DATE May-June 2016 ORIGINAL ARCHITECT SURVEY AREA Downtown Libertyville

## **PERMIT/HISTORIC INFORMATION**

OLD ADDRESS

DATE OF CONSTRUCTION

\_

## PERMIT MOVING INFORMATION

**MOVING PERMIT #** 

DATE MOVED

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

86-288

**DATE** 5/7/1986

BUILDING PERMIT DESCRIPTION

Two family residential building

COST

\$137,500.00

**ORIGINAL OWNER OCCUPIED?** 

EXTERIOR ALTERATION PERMITS

#### OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

-

**OTHER SOURCES** 

HISTORIC INFO COMPILER

LR

VOLUNTEER

-

#### -

BEGINNING STREET NUMBER	328
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Wright Court
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Yes
CRITERIA	A



Photo Id: WrightCt328(1)

## **BUILDING DETAILS**

#### **BUILDING NAME**

Kern, Henry House	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	
-	

ZONING

R-7 NUMBER OF STORIES

2

PROPERTY INDEX NUMBER

1116415007

## **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

WITHIN DISTRICT?	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

#### **NR ELIGIBLE?**

No

CRITERIA

#### ALTERNATE ADDRESS?

-

# **GENERAL INFORMATION**

CATEGORY	н
Building	
CONDITION	s
Good	
INTEGRITY	N
Not altered	
CURRENT USE	
Domestic - single dwelling	

IISTORIC USE
Domestic - single dwelling
ECONDARY STRUCTURE
IR SECOND

#### ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

#### OTHER YEAR

••••••

-DATE SOURCE

House Plaque

#### WALL MATERIAL (CURRENT)

Stucco

#### WALL MATERIAL 2 (CURRENT)

PLAN

Irregular

#### NO OF STORIES

2.5

## ROOF TYPE

Combination

#### ROOF MATERIAL

Asphalt - shingle

#### FOUNDATION

Parged

PORCH

#### Front

#### WINDOW MATERIAL

Wood

#### WINDOW MATERIAL 2

Stained glass

#### WINDOW TYPE

Double hung & casement

#### WINDOW CONFIGURATION

1/1; 3/1; multi-light

## SIGNIFICANCE

Stately, nearly unaltered Queen Anne residence from the early 20th century, with stucco exterior, three-sided southwest corner tower, and hipped roof front porch with stucco square columns.

#### HISTORIC FEATURES

Hipped main roof with front gable bay; 2-story corner tower; north and south 2-story bays with cutaway corners; hipped-roof front porch; stained glass transom window under front porch; historic wood double hung windows

#### ALTERATIONS



Photo Id: WrightCt328(3)



Photo Id: wright328



328\_Wright\_Court

Photo Id:

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	Kern, T. H.
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Kern, Harry	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	

## **PERMIT/HISTORIC INFORMATION**

#### OLD ADDRESS

DATE OF CONSTRUCTION

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #** 

DATE MOVED

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #** 

DATE

**BUILDING PERMIT DESCRIPTION** 

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

#### **OTHER PERMIT INFORMATION**

|-

\_

COA INFO

#### HISTORIC INFO

Historic photograph of building on Illinois Digital Archive (in collection of the Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--

http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6521/rec/14 Henry Kern was the owner and operator of the Kern Hotel, originally located on the northwest corner of First Street and Orchard Avenue (now Church Street). The hotel was constructed in 1882, and is no longer extant.

#### OTHER SOURCES

Sanborn Maps--1912, 1924, 1933, 1948

HISTORIC INFO COMPILER

#### LR VOLUNTEER

BEGINNING STREET NUMBER	332	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Wright Court	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: WrightCt332(1)

## **BUILDING DETAILS**

#### **BUILDING NAME**

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

# R-7 NUMBER OF STORIES PROPERTY INDEX NUMBER

1116415006

ZONING

2

## **NATIONAL REGISTER**

#### NR DISTRICT CONTRIB/NON-CONTRIB

NC	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

#### NR ELIGIBLE?

No

CRITERIA

#### ALTERNATE ADDRESS?

\_

# **GENERAL INFORMATION**

ł

CATEGORY	
Building	
CONDITION	
Excellent	
INTEGRITY	
Minor alterations	
CURRENT USE	
Domestic - single dwelling	

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
NC

ARCHITECTURAL CLASSIFICATION	FOUNDATION
New Traditional	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Assessor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURA
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	
L	

ATION



Photo Id: WrightCt332(2)



Photo Id: wright332

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	-
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PER	MIT MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIG	INAL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-

**BUILDING PERMIT DESCRIPTION** 

-COST

\_

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

HISTORIC INFO

-

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

-

\_