BEGINNING STREET NUMBER	118	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	W. Cook Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: CookAveW118(2)

BUILDING DETAILS

BUILDING NAMEZONINGVillage Fire DepartmentC-1GROUND FLOOR USENUMBER OF STORIESMunicipal2MunicipalPROPERTY INDEX NUMBERMunicipal1116305012; 1116305013CURRENT OCCUPANTVillage Hall

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	
С	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	
L	

NR ELIGIBLE?

No CRITERIA

ALTERNATE ADDRESS?

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Government - city hall
CONDITION	SECONDARY STRUCTURE
Good	-
INTEGRITY	NR SECOND
Moderate alterations and additions	-
CURRENT USE	
Government - city hall	

ARCHITECTURAL CLASSIFICATION

	Colonial	Revival
--	----------	---------

DETAILS

OTHER YEAR

1970; 1994; 2001

DATE SOURCE

Illinois Digital Archives; permits

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

Aluminum/vinyl

PLAN

Irregular

NO OF STORIES

2

ROOF TYPE

Multi-gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete

PORCH

_

WINDOW MATERIAL

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

8/8; 12/12

SIGNIFICANCE

-

HISTORIC FEATURES

Front-gable, south-facing bay, and east square tower are part of original building

ALTERATIONS

Building expanded and remodeled when building became the Village Hall in 1993-4--front (south) garage bays filled in with windows; 1-story entry bay addition at southeast corner; clock face added to tower (2001); replacement windows on all facades, most in original openings, some in altered openings (see 1993 architectural drawings)



Photo Id: CookAveW118(3)



12

Photo Id: 118cook2

Photo Id: CookAveW118(5)



Photo Id: 118cook

OLD ADDRESS (CITY DIR.YEAR	BUILDER	
-	-	
BUILDING MOVED?	SURVEYOR	
-	LR	
MOVED FROM	SURVEYOR ORGANIZATION	
-	Ramsey Historic Consultants	
ORIGINAL OWNER	SURVEY DATE	
-	May-June 2016	
ORIGINAL ARCHITECT	SURVEY AREA	
-	Downtown Libertyville	
ARCHITECT SOURCE		

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

-

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

JCM-01-0032 (11/20/2001)--clock tower; architectural plans for changes to building as part of conversion to City Hall (3/1/1993)

OTHER PERMIT INFORMATION

| -

_

COA INFO

HISTORIC INFO

from Illinois Digital Archives (information provided by the Libertyville-Mundelein Historical Society and the Cook Memorial Public Library)--"Street view of West Cook Street looking east toward Milwaukee Ave with the village hall on the left. Built in 1913, Libertyville's original village hall was located on West Cook Street. According to local historian Dean Larson, the village hall housed the fire station, jail, meeting rooms and the Alpha Club Library (the forerunner of Cook Memorial Library) in addition to the village offices. When the village moved its offices to the new Schertz Municipal Building on East Cook Street in 1970, the old village hall was almost completely demolished and a new fire station was constructed at the site. In 1994 the village returned to its roots and moved back to its original site after remodeling the fire station into a new village hall."

OTHER SOURCES

Sanborn Maps (1948); Historic photos of building on Illinois Digital Archives

HISTORIC INFO COMPILER

LR

VOLUNTEER

BEGINNING STREET NUMBER	140
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Cook Avenue
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: WCook140

BUILDING DETAILS

BUILDING NAME	ZONING
First Lake County National Bank Building	C-1
GROUND FLOOR USE	NUMBER OF STORIES
Commercial	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Commercial	1116305012-1116305013
CURRENT OCCUPANT	
Chase Bank	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

NC	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	
-	

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

-

GENERAL INFORMATION

CATEGORY	
Building	
CONDITION	
Good	
INTEGRITY	
Minor alterations	
CURRENT USE	
Commerce/Trade - financial institution	

HISTORIC USE	
Commerce/Trade - financial institution	
SECONDARY STRUCTURE	
-	
NR SECOND	
-	

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Contemporary	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
-	-
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	-
PLAN	SIGNIFICANCE
-	-
NO OF STORIES	HISTORIC FEATURES
-	-
ROOF TYPE	ALTERATIONS
-	-
ROOF MATERIAL	
-	



Photo Id: WCook140(1)



Photo Id: WCook140(2)



Photo Id: WCook140(3)

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
Loeble, Schlossman, Bennett & Dart	Downtown Libertyville
ARCHITECT SOURCE	

CDT 4.9.1967 p. d1

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

ORIGINAL PERMIT INFORMATION

-

BUILDING PERMIT #

4142

DATE

No date (1967)

BUILDING PERMIT DESCRIPTION

2 story concrete and brick building

COST

\$756,000.00

ORIGINAL OWNER OCCUPIED?

Yes

EXTERIOR ALTERATION PERMITS

79-2 (1/16/1979)--alter north stairway

OTHER PERMIT INFORMATION

COA INFO

_

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR VOLUNTEER

_

BEGINNING STREET NUMBER	112
DEGIMING STREET NONDER	112
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Douglas Avenue
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: DouglasAve112(1)

BUILDING DETAILS

BUILDING NAME

-	
GROUND FLOOR USE	
Residence	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

ZONING	
R-8	
NUMBER OF STORIES	
2	
PROPERTY INDEX NUMBER	
1121105002	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

_	
YEAR	
No	
NR LANDMARK?	
No	
WITHIN DISTRICT?	
С	

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

-

GENERAL INFORMATION

ATEGORY	
Building	
ONDITION	
Good	
NTEGRITY	
Ioderate alterations	
URRENT USE	
Domestic - single dwelling	

ISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
NC

ARCHITECTURAL CLASSIFICATION

Side Gable

DETAILS

OTHER YEAR

••••••

-DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

Wood - shingles

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick

PORCH

Full Front

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

SIGNIFICANCE

HISTORIC FEATURES

Front gable roof; shed roof north and south dormers with gable ends; 4/1 historic wood windows on first story; west side sun porch with gable roof

ALTERATIONS

South side porch addition (1954); alterations to entry, replacement windows in original openings on 2nd story



Photo Id: DouglasAve112(2)



Photo Id: douglas112(2)



Photo Id: douglas112

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

-

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

JRR-15-0151 (12/14/2015)--remodel kitchen, 1/2 bath, basement; 976 (10/9/1954)--moving garage on lot; 884 (6/23/1954)--add screened porch on south side facing Park Avenue ; 700 (8/28/1953)--repair and remodel entryway; repair and replace sidewalk and concrete slab

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

_

OTHER SOURCES

Sanborn Maps--1933, 1948

HISTORIC INFO COMPILER

LR VOLUNTEER

_

BEGINNING STREET NUMBER	120
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Douglas Avenue
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: DouglasAve120(1)

BUILDING DETAILS

BUILDING NAME

-	
GROUND FLOOR USE	
Residence	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

R-8	
NUMBER OF STORIES	
2	
PROPERTY INDEX NUMBER	

1121105001

ZONING

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

YEAR		
No		
NR LANDMARK?		
No		
WITHIN DISTRI	CT?	
L		
C		

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

_

GENERAL INFORMATION

CATEGORY
Building
CONDITION
Good
INTEGRITY
Minor alterations and additions
CURRENT USE
Domestic - single dwelling

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
C

ARCHITECTURAL CLASSIFICATION

Tudor Revival

DETAILS

OTHER YEAR

_

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

Wood

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

6/1; 4/1

SIGNIFICANCE

-

HISTORIC FEATURES

Broad, asymmetrical front gable roof that extends south to include a south side sun porch; prominent brick end chimney centered; nested 1-story front gable entry bay; round-arch front entry; historic wood windows

ALTERATIONS

South side shed-roof dormer addition; replacement front door; rear deck addition; glass block window on front facade at 2nd story





Photo Id: douglas120

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u> </u>	
<u>PERMIT/HIS</u>	STORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT NO	
PERMIT MO	VING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
	ERMIT INFORMATION
URIGINAL P	

BUILDING PERMIT #

-DATE -

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

JD-01-0008 (7/25/2001)--deck

OTHER PERMIT INFORMATION

COA INFO

_

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1933, 1948

HISTORIC INFO COMPILER

LR VOLUNTEER

.

BEGINNING STREET NUMBER	126
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Douglas Avenue
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Potentially Eligible
CRITERIA	-



Photo Id: DouglasAve126(1)

BUILDING DETAILS

BUILDING NAME

-	
GROUND FLOOR USE	
Residence	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

R-7 NUMBER OF STORIES PROPERTY INDEX NUMBER

1121100005

ZONING

2

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

_

GENERAL INFORMATION

CATEGORY	
Building	
CONDITION	
Good	
NTEGRITY	
Minor alterations	
CURRENT USE	
Domestic - single dwelling	

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
C

ARCHITECTURAL CLASSIFICATION

Craftsman Bungalow

DETAILS

OTHER YEAR

_

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

Wood - shingles

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Full Front

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

WINDOW TYPE

Double hung & casement

WINDOW CONFIGURATION

SIGNIFICANCE

HISTORIC FEATURES

Broad side gable roof with overhanging eaves and wood brackets; shingle siding under gables, wood siding on 1st story; inset full-front porch structure (enclosed); historic wood windows; shallow shed-roof front dormer; south side square window bay

ALTERATIONS

Porch enclosed (not historic)



Photo Id: DouglasAve126(3)



Photo Id: douglas126(2)



Photo Id: douglas126

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
OLD ADDRESS	DATE OF CONSTRUCTION -
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINA	L PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-

DATE -

BUILDING PERMIT DESCRIPTION

COST -

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

COA INFO

-

HISTORIC INFO

_

OTHER SOURCES

Sanborn Maps--1933, 1948

HISTORIC INFO COMPILER

LR VOLUNTEER

_

BEGINNING STREET NUMBER	103
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt103(1)

BUILDING DETAILS

BUILDING NAME

-	
GROUND FLOOR USE	
Residential Apartments	
UPPER FLOOR USE	
Residential Apartments	
CURRENT OCCUPANT	

R-8 NUMBER OF STORIES PROPERTY INDEX NUMBER

1121203014

ZONING

2

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

С	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	,
-	

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

_

GENERAL INFORMATION

ł

ATEGORY
Building
ONDITION
Good
NTEGRITY
Minor alterations
URRENT USE
Domestic - multiple dwelling

HISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
NC

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

OTHER YEAR

_

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

2.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick

_

PORCH

WINDOW MATERIAL

-WINDOW MATERIAL 2

_

WINDOW TYPE

-

WINDOW CONFIGURATION

SIGNIFICANCE

HISTORIC FEATURES

_

_

ALTERATIONS



Photo Id: FirstSt103(2)



Photo Id: First103

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	-
MOVED FROM	SURVEYOR ORGANIZATION
-	-
ORIGINAL OWNER	SURVEY DATE
-	-
ORIGINAL ARCHITECT	SURVEY AREA
-	-
ARCHITECT SOURCE	·,
-	
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

-

BUILDING PERMIT #

_ DATE _

BUILDING PERMIT DESCRIPTION

COST -

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

-COA INFO

-HISTORIC INFO

OTHER SOURCES

-

HISTORIC INFO COMPILER

VOLUNTEER

_

BEGINNING STREET NUMBER	104
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	с
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt104(1)

BUILDING DETAILS

BUILDING NAME

-	
GROUND FLOOR USE	
Residence	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

ZONING
R-8
NUMBER OF STORIES
1.5
PROPERTY INDEX NUMBER

1121204007

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

С
WITHIN DISTRICT?
No
NR LANDMARK?
No
YEAR
YEAR

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

-

GENERAL INFORMATION

CATEGORY	
Building	
CONDITION	
Good	
NTEGRITY	
Historic alterations	
CURRENT USE	
Domestic - single dwelling	

HISTORIC USE	
Domestic - single dwelling	
SECONDARY STRUCTURE	
Detached garage	
NR SECOND	
С	
L	

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

Craftsman

OTHER YEAR

1950 (c)

DATE SOURCE

Assessor, Sanborn Map (1948)

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Historic photograph of building shortly after it was constructed and Sanborn maps indicate that the house was extensively altered some time after 1948. Front gable roof and rectangular massing are intact.

ALTERATIONS

Historic alterations (c. 1950) include: removal of full front porch; 1-story entry bay, pent roof at 1st story facade; three-sided window bay on 1st story of south facade. Other alterations include one-story rear addition; replacement siding; fixed shutters



Photo Id: FirstSt104(4)



Photo Id: FirstStreet104

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
McDonald, Edw.	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT	

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

JRF-11-0041 (5/4/11)--replace roof

OTHER PERMIT INFORMATION

|-

_

COA INFO

HISTORIC INFO

Historic photo of house at Illinois Digital Archives: http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6524/rec/3

OTHER SOURCES

Sanborn Maps (1933, 1948)

HISTORIC INFO COMPILER

LR

VOLUNTEER

BEGINNING STREET NUMBER	107	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	First Street	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	NC	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	
CRITERIA	-	



Photo Id: FirstSt107(1)

BUILDING DETAILS

BUILDING NAME

-	
GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

ZONING R-8

NUMBER OF STORIES

2.5

PROPERTY INDEX NUMBER

1121203013

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

NC	
WITHIN DISTRICT	
No	
NR LANDMARK?	
No	
YEAR	
-	

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

-

GENERAL INFORMATION

CATEGORY	
Building	
CONDITION	
Excellent	
INTEGRITY	
Not altered	
CURRENT USE	
Domestic - single dwelling	

IISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
NC

ARCHITECTURAL CLASSIFICATION

New Traditional - Queen Anne

DETAILS

OTHER YEAR

-

DATE SOURCE

Permit

WALL MATERIAL (CURRENT)

WALL MATERIAL 2 (CURRENT)

PLAN

-

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

Concrete

PORCH

_

WINDOW MATERIAL

-WINDOW MATERIAL 2

_

WINDOW TYPE

-

WINDOW CONFIGURATION

SIGNIFICANCE

HISTORIC FEATURES

_

_

ALTERATIONS





Photo Id: First107

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
Leider, Gregory	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
Line Works	Downtown Libertyville
ARCHITECT SOURCE	
Permit	

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

ORIGINAL PERMIT INFORMATION

-

BUILDING PERMIT #

JRB-04-0006

DATE

5/25/2004

BUILDING PERMIT DESCRIPTION

Single Family Residence

COST

\$350,000.00

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR VOLUNTEER

.

BEGINNING STREET NUMBER	108
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	С
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt108(3)

BUILDING DETAILS

BUILDING NAME

-	
GROUND FLOOR USE	
Residence	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

ZONING R-8 NUMBER OF STORIES 2 PROPERTY INDEX NUMBER 1121204006

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

-

GENERAL INFORMATION

ŀ

ATEGORY
Building
ONDITION
Good
ITEGRITY
Ioderate Alterations
URRENT USE
Domestic - single dwelling

ISTORIC USE
Domestic - single dwelling
ECONDARY STRUCTURE
Detached garage
IR SECOND
NC

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

OTHER YEAR

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Hardie board

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

WINDOW TYPE

Double hung & other

WINDOW CONFIGURATION

1/1; multi-light

SIGNIFICANCE

HISTORIC FEATURES

Front gable roof; three-sided, full-height gable bay on south facade; rectangular massing; hipped-roof front porch structure

ALTERATIONS

Replacement windows in original openings; replacement siding; replacement columns, railing, and base on front porch (2001); rear porch addition (2003)



Photo Id: FirstSt108(4)



Photo Id: FIrst108

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

3133 (7/26/1962)--rebuilt front porch, build new side porch; 2 new windows in attic; JRR_01-0008 (2/7/2001)--renovate front porch; No permit # or date--replace cedar siding with fiber cement siding; JRM-01-0040 (11/11/2003)--back porch and hot tub

OTHER PERMIT INFORMATION

JDB-11-0005 (6/7/2011)--demolish garage

COA INFO

_

HISTORIC INFO

OTHER SOURCES

Sanborn Maps (1933, 1948)

HISTORIC INFO COMPILER

LR VOLUNTEER

_

BEGINNING STREET NUMBER	112
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt112(1)

BUILDING DETAILS

BUILDING NAME

GROUND FLOOR USE	
Residential	
UPPER FLOOR USE	
Residential	
CURRENT OCCUPANT	

R-7	
NUMBER OF STORIES 2	
PROPERTY INDEX NUMBER	

1121204005

ZONING

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB

NC	
WITHIN DISTRICT?	
No	
NR LANDMARK?	
No	
YEAR	

NR ELIGIBLE?

No

CRITERIA

ALTERNATE ADDRESS?

_

GENERAL INFORMATION

ł

CATEGORY	
Building	
CONDITION	
Excellent	
INTEGRITY	
Not altered	
CURRENT USE	
Domestic - single dwelling	

IISTORIC USE
Domestic - single dwelling
SECONDARY STRUCTURE
Detached garage
NR SECOND
NC

ARCHITECTURAL CLASSIFICATION	FOUND
New Traditional - Craftsman	-
DETAILS	PORCH
-	-
OTHER YEAR	WINDO
-	-
DATE SOURCE	WINDO
Permit	-
WALL MATERIAL (CURRENT)	WINDO
-	-
WALL MATERIAL 2 (CURRENT)	WINDO
-	-
PLAN	SIGNIF
-	-
NO OF STORIES	HISTOR
-	-
ROOF TYPE	ALTERA
-	-
ROOF MATERIAL	
-	

ATION

OW MATERIAL

OW MATERIAL 2

OW TYPE

OW CONFIGURATION

ICANCE

RIC FEATURES

ATIONS



Photo Id: FirstSt112(2)



Photo Id: First112

OLD ADDRESS (CITY DIR.YEAR BUILDER ADR Custom Builders **BUILDING MOVED?** SURVEYOR LR **MOVED FROM** SURVEYOR ORGANIZATION Ramsey Historic Consultants ORIGINAL OWNER SURVEY DATE Greenhill, Tammy May-June 2016 **ORIGINAL ARCHITECT** SURVEY AREA Stojknovic, Danny Downtown Libertyville ARCHITECT SOURCE Permit

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

JENG-12-0164

DATE

1/18/2013

BUILDING PERMIT DESCRIPTION

New Single family residence

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR VOLUNTEER
